

Moran Environmental Recovery LLC Inspection Sheet

DATE: 9/4/22

LOCATION: Elba Island

INSIDE CONTAINER

		Circle one		Comments
6- 26lb Anchors with chain	Verified:	<u>YES</u>	NO	_____
4- Buoys with 2 shackles each	Verified:	<u>YES</u>	NO	_____
2 spools of line	Verified:	<u>YES</u>	NO	_____
2000' 18" containment boom (verification of)	Verified:	<u>YES</u>	NO	_____
4 Bundles absorbent pads	Verified:	<u>YES</u>	NO	_____
4- Bundles absorbent boom	Verified:	<u>YES</u>	NO	_____
1- Roll trash bags	Verified:	<u>YES</u>	NO	_____
1- Pair pliers	Verified:	<u>YES</u>	NO	_____
1- First Aid Kit	Verified:	<u>YES</u>	NO	_____
1-Eye Wash	Verified:	<u>YES</u>	NO	_____

OUTSIDE CONTAINER

Box number 1
 Container accessible Verified: YES NO _____
 Seal in place Verified: YES NO 1633030 / 1633025
 Seal number _____
 Container Temp Hi _____ Lo ✓ Date: 8-4-22

Inspector:
 Print: Isaac Cunningham

Signature: [Signature]

Facility Rep:
 Print: ARETHA Williams

Signature: [Signature]

Notify Facility 24 hrs prior to inspection

Person Notified: _____

Check if Verification only

Moran Environmental Recovery LLC Inspection Sheet

DATE: 8-4-22

LOCATION: Elba Island

INSIDE CONTAINER

		Circle one	
6- 26lb Anchors with chain	Verified:	<u>YES</u> NO	_____
4- Buoys with 2 shackles each	Verified:	<u>YES</u> NO	_____
2 spools of line	Verified:	<u>YES</u> NO	_____
2000' 18" containment boom (verification of)	Verified:	<u>YES</u> NO	_____
4 Bundles absorbent pads	Verified:	<u>YES</u> NO	_____
4- Bundles absorbent boom	Verified:	<u>YES</u> NO	_____
1- Roll trash bags	Verified:	<u>YES</u> NO	_____
1- Pair pliers	Verified:	<u>YES</u> NO	_____
1- First Aid Kit	Verified:	<u>YES</u> NO	_____
1-Eye Wash	Verified:	<u>YES</u> NO	_____

OUTSIDE CONTAINER

Box number 2
 Container accessible Verified: YES NO
 Seal in place Verified: YES NO
 Seal number 0485843 / 1633074
 Container Temp Hi _____ Lo ✓ Date: 8-4-22

Inspector:
 Print: Troy Cunningham
 Facility Rep Ametia Williams
 Print: _____

Signature: [Signature]
 Signature: [Signature]

Notify Facility 24 hrs prior to inspection

Person Notified: _____

Check if Verification only

Moran Environmental Recovery LLC Inspection Sheet

DATE: Aug 5 2022

LOCATION: Colonial Terminal

INSIDE CONTAINER

		Circle one	
6- 26lb Anchors with chain	Verified:	<input checked="" type="radio"/> YES NO	_____
4- Buoys with 2 shackels each	Verified:	<input checked="" type="radio"/> YES NO	_____
2 spools of line	Verified:	<input checked="" type="radio"/> YES NO	_____
2000' 18" containment boom (verification of)	Verified:	<input checked="" type="radio"/> YES NO	_____
4 Bundles absorbent pads	Verified:	<input checked="" type="radio"/> YES NO	_____
4- Bundles absorbent boom	Verified:	<input checked="" type="radio"/> YES NO	_____
1- Roll trash bags	Verified:	<input checked="" type="radio"/> YES NO	_____
1- Pair pliers	Verified:	<input checked="" type="radio"/> YES NO	_____
1- First Aid Kit	Verified:	<input checked="" type="radio"/> YES NO	_____
1-Eye Wash	Verified:	<input checked="" type="radio"/> YES NO	_____

OUTSIDE CONTAINER

Box number 3


Container accessible Verified: YES NO _____

Seal in place Verified: YES NO _____


Seal number 0485645 / 0485987

Container Temp Hi _____ Lo _____ Date: _____

Inspector:
Print: Carl Youmans

Signature: 

Facility Rep
Print: Tom Dola

Signature: 

Notify Facility 24 hrs prior to inspection

Person Notified: _____

Check if Verification only

Moran Environmental Recovery LLC Inspection Sheet

DATE: Aug 5 2022

LOCATION: IMTT North

INSIDE CONTAINER

		Circle one	
6- 26lb Anchors with chain	Verified:	<u>YES</u> NO	_____
4- Buoys with 2 shackles each	Verified:	<u>YES</u> NO	_____
2 spools of line	Verified:	<u>YES</u> NO	_____
2000' 18" containment boom (verification of)	Verified:	<u>YES</u> NO	_____
4 Bundles absorbent pads	Verified:	<u>YES</u> NO	_____
4- Bundles absorbent boom	Verified:	<u>YES</u> NO	_____
1- Roll trash bags	Verified:	<u>YES</u> NO	_____
1- Pair pliers	Verified:	<u>YES</u> NO	_____
1- First Aid Kit	Verified:	<u>YES</u> NO	_____
1-Eye Wash	Verified:	<u>YES</u> NO	_____

OUTSIDE CONTAINER

Box number 4

Container accessible Verified: YES NO _____

Seal in place Verified: YES NO _____

Seal number 0485853

Container Temp Hi _____ Lo _____ Date: _____

Inspector:
Print: Lari Youmans

Signature: [Signature]

Facility Rep
Print: R. Lee Lutz

Signature: [Signature]

Notify Facility 24 hrs prior to inspection

Person Notified: _____

Check if Verification only

Moran Environmental Recovery LLC Inspection Sheet

DATE: Aug 5 2022

LOCATION: Metro Ports

INSIDE CONTAINER

		Circle one	
6- 26lb Anchors with chain	Verified:	<u>YES</u> NO	_____
4- Buoys with 2 shackles each	Verified:	<u>YES</u> NO	_____
2 spools of line	Verified:	<u>YES</u> NO	_____
2000' 18" containment boom (verification of)	Verified:	<u>YES</u> NO	_____
4 Bundles absorbent pads	Verified:	<u>YES</u> NO	_____
4- Bundles absorbent boom	Verified:	<u>YES</u> NO	_____
1- Roll trash bags	Verified:	<u>YES</u> NO	_____
1- Pair pliers	Verified:	<u>YES</u> NO	_____
1- First Aid Kit	Verified:	<u>YES</u> NO	_____
1-Eye Wash	Verified:	<u>YES</u> NO	_____

OUTSIDE CONTAINER

Box number 5

Container accessible Verified: YES NO _____

Seal in place Verified: YES NO _____

Seal number 1633129 / 1633128

Container Temp Hi _____ Lo ✓ Date: 8/5/21

Inspector:
Print: Top Cunningham

Facility Rep:
Print: Tom Dolan

Signature: [Signature]

Signature: [Signature]

Notify Facility 24 hrs prior to inspection

Person Notified: _____

Check if Verification only

Moran Environmental Recovery LLC Inspection Sheet

DATE: Aug 5 2022

LOCATION: Metro Ports

INSIDE CONTAINER

	Circle one		Comments
6- 26lb Anchors with chain	Verified: <u>YES</u>	NO	_____
4- Buoys with 2 shackles each	Verified: <u>YES</u>	NO	_____
2 spools of line	Verified: <u>YES</u>	NO	_____
2000' 18" containment boom (verification of)	Verified: <u>YES</u>	NO	_____
4 Bundles absorbent pads	Verified: <u>YES</u>	NO	_____
4- Bundles absorbent boom	Verified: <u>YES</u>	NO	_____
1- Roll trash bags	Verified: <u>YES</u>	NO	_____
1- Pair pliers	Verified: <u>YES</u>	NO	_____
1- First Aid Kit	Verified: <u>YES</u>	NO	_____
1-Eye Wash	Verified: <u>YES</u>	NO	_____

OUTSIDE CONTAINER

Box number 6

Container accessible Verified: YES NO _____

Seal in place Verified: YES NO _____

Seal number 1623061 / 1623061

Container Temp Hi _____ Lo _____ Date: 8/5/21

Inspector:
Print: Trouf Arriandher

Signature: [Handwritten Signature]

Facility Rep:
Print: Tom Dolan

Signature: [Handwritten Signature]

Notify Facility 24 hrs prior to inspection

Person Notified: _____

Check if Verification only

Moran Environmental Recovery LLC Inspection Sheet

DATE: 8/10/22

LOCATION: MER Yard

INSIDE CONTAINER

		Circle one	
6- 26lb Anchors with chain	Verified:	<u>YES</u> NO	_____
4- Buoys with 2 shackles each	Verified:	<u>YES</u> NO	_____
2 spools of line	Verified:	<u>YES</u> NO	_____
2000' 18" containment boom (verification of)	Verified:	<u>YES</u> NO	_____
4 Bundles absorbent pads	Verified:	<u>YES</u> NO	_____
4- Bundles absorbent boom	Verified:	<u>YES</u> NO	_____
1- Roll trash bags	Verified:	<u>YES</u> NO	_____
1- Pair pliers	Verified:	<u>YES</u> NO	_____
1- First Aid Kit	Verified:	<u>YES</u> NO	_____
1-Eye Wash	Verified:	<u>YES</u> NO	_____

OUTSIDE CONTAINER

Box number 7

Container accessible Verified: YES NO _____

Seal in place Verified: YES NO _____

Seal number _____

Container Temp Hi _____ Lo _____ Date: 8/10/22

Inspector:
Print: Paul Cunningham

Signature: [Signature]

Facility Rep
Print: _____

Signature: _____

Notify Facility 24 hrs prior to inspection

Person Notified: _____

Check if Verification only

Moran Environmental Recovery LLC Inspection Sheet

DATE: 5/10/22

LOCATION: Plant McIntosh

INSIDE CONTAINER

		Circle one	Comments
6- 26lb Anchors with chain	Verified: YES	<input checked="" type="radio"/> NO	_____
4- Buoys with 2 shackles each	Verified: YES	<input checked="" type="radio"/> NO	_____
2 spools of line	Verified: YES	<input checked="" type="radio"/> NO	_____
2000' 18" containment boom (verification of)	Verified: YES	<input checked="" type="radio"/> NO	_____
4 Bundles absorbent pads	Verified: YES	<input checked="" type="radio"/> NO	_____
4- Bundles absorbent boom	Verified: YES	<input checked="" type="radio"/> NO	_____
1- Roll trash bags	Verified: YES	<input checked="" type="radio"/> NO	_____
1- Pair pliers	Verified: YES	<input checked="" type="radio"/> NO	_____
1- First Aid Kit	Verified: YES	<input checked="" type="radio"/> NO	_____
1-Eye Wash	Verified: YES	<input checked="" type="radio"/> NO	_____

OUTSIDE CONTAINER

Box number 8

Container accessible Verified: YES NO

Seal in place Verified: YES NO 1633005 / 1633026

Seal number _____

Container Temp Hi _____ Lo _____ Date: _____

Inspector: Chase Huest
Print: _____

Signature: [Signature]

Facility Rep: Owen Bryant
Print: _____

Signature: [Signature]

Notify Facility 24 hrs prior to inspection

Person Notified: _____



Check if Verification only

Moran Environmental Recovery LLC Inspection Sheet

DATE: 8/10/22

LOCATION: MER Yard

INSIDE CONTAINER

		Circle one		Comments
6- 26lb Anchors with chain	Verified:	<u>YES</u>	NO	_____
4- Buoys with 2 shackles each	Verified:	<u>YES</u>	NO	_____
2 spools of line	Verified:	<u>YES</u>	NO	_____
2000' 18" containment boom (verification of)	Verified:	<u>YES</u>	NO	_____
4 Bundles absorbent pads	Verified:	<u>YES</u>	NO	_____
4- Bundles absorbent boom	Verified:	<u>YES</u>	NO	_____
1- Roll trash bags	Verified:	<u>YES</u>	NO	_____
1- Pair pliers	Verified:	<u>YES</u>	NO	_____
1- First Aid Kit	Verified:	<u>YES</u>	NO	_____
1-Eye Wash	Verified:	<u>YES</u>	NO	_____

OUTSIDE CONTAINER

Box number 9

Container accessible Verified: YES NO _____

Seal in place Verified: YES NO _____

Seal number _____

Container Temp Hi _____ Lo ✓ Date: 8/10/21

Inspector:
Print: Troy Cunningham

Facility Rep
Print: _____

Signature: [Signature]

Signature: _____

Notify Facility 24 hrs prior to inspection

Person Notified: _____

Check if Verification only

Moran Environmental Recovery LLC Inspection Sheet

DATE: 8/16/22

LOCATION: MER SAV

INSIDE CONTAINER

		Circle one	
6- 26lb Anchors with chain	Verified:	<input checked="" type="radio"/> YES NO	_____
4- Buoys with 2 shackles each	Verified:	<input checked="" type="radio"/> YES NO	_____
2 spools of line	Verified:	<input checked="" type="radio"/> YES NO	_____
2000' 18" containment boom (verification of)	Verified:	<input checked="" type="radio"/> YES NO	_____
4 Bundles absorbent pads	Verified:	<input checked="" type="radio"/> YES NO	_____
4- Bundles absorbent boom	Verified:	<input checked="" type="radio"/> YES NO	_____
1- Roll trash bags	Verified:	<input checked="" type="radio"/> YES NO	_____
1- Pair pliers	Verified:	<input checked="" type="radio"/> YES NO	_____
1- First Aid Kit	Verified:	<input checked="" type="radio"/> YES NO	_____
1-Eye Wash	Verified:	<input checked="" type="radio"/> YES NO	_____

OUTSIDE CONTAINER

Box number 10

Container accessible Verified: YES NO _____

Seal in place Verified: YES NO _____

Seal number _____

Container Temp Hi _____ Lo _____ Date: 8/16/22

Inspector:
Print: Troup Cunningham

Signature: Troup Cunningham

Facility Rep
Print: _____

Signature: _____

Notify Facility 24 hrs prior to inspection

Person Notified: _____

Check if Verification only

Moran Environmental Recovery LLC Inspection Sheet

DATE: 8/16/22

Location: Phillips 66

Unit #: BR 4

BOOM REELS

	Circle						
Grease Chain	<input checked="" type="radio"/>	NO					
Grease Fittings	<input checked="" type="radio"/>	NO					
Inspect sprocket	<input checked="" type="radio"/>	NO					
Check Oil level in motor	<input checked="" type="radio"/>	NO					
Reel clear of debris and grass	<input checked="" type="radio"/>	NO					
Run motor	<input checked="" type="radio"/>	NO					
Hand Brake operational	<input checked="" type="radio"/>	NO					
Boom Reel cover secure	<input checked="" type="radio"/>	NO					
*** 1000ft of 18" containment boom (Verify Quantit	<input checked="" type="radio"/>	<input checked="" type="radio"/>					
Condition of Boom Reel Cover			<table border="1" style="display: inline-table; border-collapse: collapse;"> <tr> <td style="padding: 2px;">Excellent</td> <td style="padding: 2px;"><input checked="" type="radio"/> Good</td> <td style="padding: 2px;">Fair</td> <td style="padding: 2px;">Poor</td> </tr> </table>	Excellent	<input checked="" type="radio"/> Good	Fair	Poor
Excellent	<input checked="" type="radio"/> Good	Fair	Poor				
Condition of Boom Reel			<table border="1" style="display: inline-table; border-collapse: collapse;"> <tr> <td style="padding: 2px;">Excellent</td> <td style="padding: 2px;"><input checked="" type="radio"/> Good</td> <td style="padding: 2px;">Fair</td> <td style="padding: 2px;">Poor</td> </tr> </table>	Excellent	<input checked="" type="radio"/> Good	Fair	Poor
Excellent	<input checked="" type="radio"/> Good	Fair	Poor				

*** See Boom condition Report for updated Boom Condition

Inspector: Chase Hurst Signature: [Signature]

Facility Rep: Sandra Gomez Signature: [Signature]

Notify Facility 24 hrs prior to inspection

Person Notified: _____

Check if Verification only

Moran Environmental Recovery LLC Inspection Sheet

DATE: 8/5/22

Location: Imperial Sugar

Unit #: BR 5

BOOM REELS

	Circle		Comments
Grease Chain	YES	NO	_____
Grease Fittings	YES	NO	_____
Inspect sprocket	YES	NO	_____
Check Oil level in motor	YES	NO	_____
Reel clear of debris and grass	YES	NO	_____
Run motor	YES	NO	_____
Hand Brake operational	YES	NO	_____
Boom Reel cover secure	YES	NO	_____
*** 1000ft of 18" containment boom (Verify Quantiti	YES	NO	_____
Condition of Boom Reel Cover			Excellent Good Fair Poor
Condition of Boom Reel			Excellent Good Fair Poor

*** See Boom condition Report for updated Boom Condition

Inspector: _____
 Print: Chase Hwst Signature: 

Facility Rep _____
 Print: _____ Signature: _____

Notify Facility 24 hrs prior to inspection

Person Notified: _____



Check if Verification only

Moran Environmental Recovery LLC Inspection Sheet

DATE: 6/10/22

Location: Ocean Terminal

Unit #: BR 1

BOOM REELS

	Circle		
Grease Chain	<input checked="" type="radio"/> YES	<input type="radio"/> NO	_____
Grease Fittings	<input checked="" type="radio"/> YES	<input type="radio"/> NO	_____
Inspect sprocket	<input checked="" type="radio"/> YES	<input type="radio"/> NO	_____
Check Oil level in motor	<input checked="" type="radio"/> YES	<input type="radio"/> NO	_____
Reel clear of debris and grass	<input type="radio"/> YES	<input checked="" type="radio"/> NO	<u>Good to have reel moved @ dock</u>
Run motor	<input checked="" type="radio"/> YES	<input type="radio"/> NO	<u>low tide sets right over mud +</u>
Hand Brake operational	<input checked="" type="radio"/> YES	<input type="radio"/> NO	<u>cannot get to by best</u>
Boom Reel cover secure	<input checked="" type="radio"/> YES	<input type="radio"/> NO	_____
*** 1000ft of 18" containment boom (Verify Quantit	<input type="radio"/> YES	<input checked="" type="radio"/> NO	_____
Condition of Boom Reel Cover	<input type="radio"/> Excellent	<input checked="" type="radio"/> Good	<input type="radio"/> Fair <input type="radio"/> Poor
Condition of Boom Reel	<input type="radio"/> Excellent	<input checked="" type="radio"/> Good	<input type="radio"/> Fair <input type="radio"/> Poor

*** See Boom condition Report for updated Boom Condition

Inspector: [Signature]
 Print: _____ Signature: [Signature]

Facility Rep
 Print: _____ Signature: _____

Notify Facility 24 hrs prior to inspection Check if Verification only

Person Notified: _____

Moran Environmental Recovery LLC

Inspection Sheet

DATE: 2/10/22 LOCATION: MER YARD
 SKIMMER TRAILER
 Trailer #: 6020 Tag#: 29691 AC
 Removed: YES NO

SK-1 SKIMMERS

Elastic Drum Skimmer Hydraulic TDSH13699178
 - Condition Circle: Excellent Good Poor Fair
 - Last Run Test Date: 6/10/22
 Comment: _____

SK-2 Action Petroleum Drum Skimmer Air driven Mod 18A Serial # 314
 - Condition Circle: Excellent Good Poor Fair
 - Last Run Test Date: 6/10/22
 Comment: _____

SK-3 Crucial Coated Drum Skimmer Mod#1CD18H36 Ser#214468
 -Condition Circle: Excellent Good Poor Fair
 -Last Run Test Date: 6/10/22
 Comment: _____

PM-1 PUMPS

PM-1 3in Hydraulic Submersible Pump Serial # 11197
 - Condition Circle: Excellent Good Poor Fair
 - Last Run Test Date: 6/10/22
 Comment: _____

PM-2 4in Vickers Hydraulic Submersible Pump Serial # 25M65A1C20
 - Condition Circle: Excellent Good Poor Fair
 - Last Run Test Date: 6/10/22
 Comment: _____

PM-3 6in Hydrotech Hydraulic Submersible Pump Serial # 6F878
 - Condition Circle: Excellent Good Poor Fair
 - Last Run Test Date: 6/10/22
 Comment: _____

PM-4 3" Crucial Diesel SD Pump Mod#DDP-3 Ser#214468
 -Condition Circle: Excellent Good Poor Fair
 -Last Run Test Date: 6/10/22
 Comment: _____

PP-1 POWER PACKS

PP-1 Elastic Power Pack Serial # H1198258
 - Condition Circle: Excellent Good Poor Fair
 - Last Run Test Date: 6/10/22
 Comment: _____

PP-2 739 Hydrotech Power Pack Mod # HT60DCV Serial # F
 - Condition Circle: Excellent Good Poor Fair
 - Last Run Test Date: 6/10/22
 Comment: _____

PP-3 Crucial Diesel Compres Mod#L70190126P17E Ser#214468
 -Condition Circle: Excellent Good Poor Fair
 -Last Run Test Date: 6/10/22
 Comment: _____

Inspector: Troy Cunningham
 Print: _____

Signature: [Signature]

Inspector: _____
 Print: _____

Signature: _____

Moran Environmental Recovery LLC Inspection Sheet

DATE: 8/16/22

LOCATION: MER YARD

JON BOATS AND MOTORS

BOATS

Unit	Boat	G3	GEN	Circle: Excelent	Good	Fair	Poor
Unit 853	14' Boat	G3 1436	GEN6849JG900		Good		
G3 1438		GEN61758G708			Good		
Express		JBC21426B595			Good		
G3 1444		GEN 36264H506			Good		
Lowe L1436L		LWCJ2227F506			Good		

MOTORS

Motor	Mod#	SN#	Circle: Excelent	Good	Fair	Poor
Yamaha 9.9	559	Mod#F9.95MHA SN# GAUKS1024920		Good		
			Last Run Date: <u>8/10/22</u>			
			Comments: _____			
Yamaha 9.9	558	Mod # F9.95MHA SN# GAUKS1028386		Good		
			Last Run Date: <u>8/10/22</u>			
			Comments: _____			
Yamaha 9.9	560	Mod# F9.9MHB SN# GAUKS1030921		Good		
			Last Run Date: <u>8/10/22</u>			
			Comments: _____			
Yamaha 15		Mod# F15SMHA SN# 6AGKS1063676		Good		
			Last Run Date: <u>8/10/22</u>			
			Comments: _____			
Yamaha 15		Mod# F15SEHA SN# 6AGKS1062763		Good		
			Last Run Date: <u>8/10/22</u>			
			Comments: _____			

Inspector: Troy Cunningham
Print: _____

Signature: [Handwritten Signature]

Check if Verification only

Moran Environmental Recovery LLC Inspection Sheet

DATE: 6/5/22

LOCATION: VOPAK

Trailer # 6017 Trailer Serial # 4X4TSEZ253U202767 Date Placed in Service: 2003

Circle one

Comments

4- 26lb Anchors with chain	Verified:	<input checked="" type="radio"/> YES	<input type="radio"/> NO	<hr/>
4- Buoys with 2 shackles each	Verified:	<input checked="" type="radio"/> YES	<input type="radio"/> NO	<hr/>
4- Long lines	Verified:	<input checked="" type="radio"/> YES	<input type="radio"/> NO	<hr/>
4- Short lines	Verified:	<input checked="" type="radio"/> YES	<input type="radio"/> NO	<hr/>
*** 1000' 18" containment boom (Verify Qua	Verified:	<input checked="" type="radio"/> YES	<input type="radio"/> NO	<hr/>
4 Bundles absorbent pads	Verified:	<input checked="" type="radio"/> YES	<input type="radio"/> NO	<hr/>
4- Bundles absorbent boom	Verified:	<input checked="" type="radio"/> YES	<input type="radio"/> NO	<hr/>
1- Roll trash bags	Verified:	<input checked="" type="radio"/> YES	<input type="radio"/> NO	<hr/>
2- Life jackets	Verified:	<input checked="" type="radio"/> YES	<input type="radio"/> NO	<hr/>
1- Pair pliers	Verified:	<input checked="" type="radio"/> YES	<input type="radio"/> NO	<hr/>
1- Skimmer 1800 SH	Verified:	<input checked="" type="radio"/> YES	<input type="radio"/> NO	<hr/>
1- First Aid Kit	Verified:	<input checked="" type="radio"/> YES	<input type="radio"/> NO	<hr/>
1-EyeWash	Verified:	<input checked="" type="radio"/> YES	<input type="radio"/> NO	<hr/>

*** See Boom Condition Report for updated Boom Condition

Comments on above Inventory: Seal # 0485820
Seal # 0485587

OUTSIDE OF TRAILER

Circle

Comments

Tag in place and current	Tag#	<u>65263A1B</u>		<hr/>
Washed/Clean		<input checked="" type="radio"/> YES	<input type="radio"/> NO	<hr/>
Lights operational		<input checked="" type="radio"/> YES	<input type="radio"/> NO	<hr/>
Trailer tounge greased		<input checked="" type="radio"/> YES	<input type="radio"/> NO	<hr/>
Trailer number visible		<input checked="" type="radio"/> YES	<input type="radio"/> NO	<hr/>
Trailer moved and brakes working		<input checked="" type="radio"/> YES	<input type="radio"/> NO	<hr/>
Tire pressure ok		<input checked="" type="radio"/> YES	<input type="radio"/> NO	<hr/>
Tire tread ok		<input checked="" type="radio"/> YES	<input type="radio"/> NO	<hr/>
Hubs, lugs, and rims ok (need to be grea		<input checked="" type="radio"/> YES	<input type="radio"/> NO	<hr/>
Doors and hinges operating properly		<input checked="" type="radio"/> YES	<input type="radio"/> NO	<hr/>
Locks on doors (trailer secured)		<input checked="" type="radio"/> YES	<input type="radio"/> NO	<hr/>

Condition of Trailer Excellent Good Fair Poor

Comments on above items

Inspector:
Print: Isaac Cunningham
Facility Rep
Print: Morgan Francisco

Signature: [Signature]
Signature: [Signature]

Notify Facility 24 hrs prior to inspection

Person Notified:

Check if Verification only

Moran Environmental Recovery LLC Inspection Sheet

DATE: 6/8/22

LOCATION: MER

Trailer # 6187

Trailer Serial #

Date Placed in Service:

		Circle one		Comments
4- 26lb Anchors with chain	Verified:	YES	NO	_____
4- Buoys with 2 shackels each	Verified:	YES	NO	_____
4- Long lines	Verified:	YES	NO	_____
4- Short lines	Verified:	YES	NO	_____
*** 1000' 18" containment boom (Verify Qua	Verified:	YES	NO	_____
4 Bundles absorbent pads	Verified:	YES	NO	_____
4- Bundles absorbent boom	Verified:	YES	NO	_____
1- Roll trash bags	Verified:	YES	NO	_____
2- Life jackets	Verified:	YES	NO	_____
1- Pair pliers	Verified:	YES	NO	_____
1- Skimmer 1800 SH	Verified:	YES	NO	_____
1- First Aid Kit	Verified:	YES	NO	_____
1-EyeWash	Verified:	YES	NO	_____

*** See Boom Condition Report for updated Boom Conditiior

Comments on above Inventory: _____

OUTSIDE OF TRAILER

	Tag#	Circle		Comments
Tag in place and current				_____
Washed/Clean		YES	NO	_____
Lights operational		YES	NO	_____
Trailer tounge greased		YES	NO	_____
Trailer number visible		YES	NO	_____
Trailer moved and brakes working		YES	NO	_____
Tire pressure ok		YES	NO	_____
Tire tread ok		YES	NO	_____
Hubs, lugs, and rims ok (need to be grea		YES	NO	_____
Doors and hinges operating properly		YES	NO	_____
Locks on doors (trailer secured)		YES	NO	_____

Condition of Trailer

Excellent Good Fair Poor

Comments on above items Brunswick for Golden Bay

Inspector: Chase Hurst

Signature: [Signature]

Facility Rep
Print: _____

Signature: _____

Notify Facility 24 hrs prior to inspection

Person Notified: _____

Check if Verification only

Moran Environmental Recovery LLC Inspection Sheet

DATE: 10/18/22

LOCATION: MER

Trailer # 6188

Trailer Serial #

Date Placed in Service:

		Circle one		Comments
4- 26lb Anchors with chain	Verified:	<input checked="" type="radio"/> YES	NO	_____
4- Buoys with 2 shackles each	Verified:	<input checked="" type="radio"/> YES	NO	_____
4- Long lines	Verified:	<input checked="" type="radio"/> YES	NO	_____
4- Short lines	Verified:	<input checked="" type="radio"/> YES	NO	_____
*** 1000' 18" containment boom (Verify Qua	Verified:	<input checked="" type="radio"/> YES	NO	_____
4 Bundles absorbent pads	Verified:	<input checked="" type="radio"/> YES	NO	_____
4- Bundles absorbent boom	Verified:	<input checked="" type="radio"/> YES	NO	_____
1- Roll trash bags	Verified:	<input checked="" type="radio"/> YES	NO	_____
2- Life jackets	Verified:	<input checked="" type="radio"/> YES	NO	_____
1- Pair pliers	Verified:	<input checked="" type="radio"/> YES	NO	_____
1- Skimmer 1800 SH	Verified:	<input checked="" type="radio"/> YES	NO	_____
1- First Aid Kit	Verified:	<input checked="" type="radio"/> YES	NO	_____
1-EyeWash	Verified:	<input checked="" type="radio"/> YES	NO	_____

*** See Boom Condition Report for updated Boom Conditiior

Comments on above Inventory: _____

OUTSIDE OF TRAILER

	Tag#	Circle		Comments
Tag in place and current		<input checked="" type="radio"/> YES	NO	_____
Washed/Clean		<input checked="" type="radio"/> YES	NO	_____
Lights operational		<input checked="" type="radio"/> YES	NO	_____
Trailer tounge greased		<input checked="" type="radio"/> YES	NO	_____
Trailer number visible		<input checked="" type="radio"/> YES	NO	_____
Trailer moved and brakes working		<input checked="" type="radio"/> YES	NO	_____
Tire pressure ok		<input checked="" type="radio"/> YES	NO	_____
Tire tread ok		<input checked="" type="radio"/> YES	NO	_____
Hubs, lugs, and rims ok (need to be grea		<input checked="" type="radio"/> YES	NO	_____
Doors and hinges operating properly		<input checked="" type="radio"/> YES	NO	_____
Locks on doors (trailer secured)		<input checked="" type="radio"/> YES	NO	_____
Condition of Trailer			<input type="radio"/> Excellent <input checked="" type="radio"/> Good <input type="radio"/> Fair <input type="radio"/> Poor	_____

Comments on above items _____

Inspector:
Print: Chae Hurst

Signature: [Signature]

Facility Rep
Print: _____

Signature: _____

Notify Facility 24 hrs prior to inspection

Person Notified: _____

Check if Verification only

Moran Environmental Recovery LLC Inspection Sheet

DATE: 8/6/22

LOCATION: MER

Trailer # 6189 Trailer Serial #53FBE2426KF050872 Date Placed in Service:

		Circle one		Comments
4- 26lb Anchors with chain	Verified:	YES	NO	_____
4- Buoys with 2 shackles each	Verified:	YES	NO	_____
4- Long lines	Verified:	YES	NO	_____
4- Short lines	Verified:	YES	NO	_____
*** 1000' 18" containment boom (Verify Qua	Verified:	YES	NO	_____
4 Bundles absorbent pads	Verified:	YES	NO	_____
4- Bundles absorbent boom	Verified:	YES	NO	_____
1- Roll trash bags	Verified:	YES	NO	_____
2- Life jackets	Verified:	YES	NO	_____
1- Pair pliers	Verified:	YES	NO	_____
1- Skimmer 1800 SH	Verified:	YES	NO	_____
1- First Aid Kit	Verified:	YES	NO	_____
1-EyeWash	Verified:	YES	NO	_____

*** See Boom Condition Report for updated Boom Condition

Comments on above Inventory: _____

OUTSIDE OF TRAILER

	Circle			Comments
Tag in place and current				_____
Washed/Clean	YES	NO		_____
Lights operational	YES	NO		_____
Trailer tounge greased	YES	NO		_____
Trailer number visible	YES	NO		_____
Trailer moved and brakes working	YES	NO		_____
Tire pressure ok	YES	NO		_____
Tire tread ok	YES	NO		_____
Hubs, lugs, and rims ok (need to be grea	YES	NO		_____
Doors and hinges operating properly	YES	NO		_____
Locks on doors (trailer secured)	YES	NO		_____

Condition of Trailer Excellent Good Fair Poor

Comments on above items In shop for repairs

Inspector:
Print: Chase Hurst

Signature: [Signature]

Facility Rep
Print: _____

Signature: _____

Notify Facility 24 hrs prior to inspection

Person Notified: _____

Check if Verification only

Moran Environmental Recovery LLC Inspection Sheet

DATE: 8/10/22

LOCATION: MER

Trailer # 6190 Trailer Serial # 53FBE2427KF050878 Date Placed in Service:

		Circle one		Comments
4- 26lb Anchors with chain	Verified:	<input checked="" type="radio"/> YES	NO	_____
4- Buoys with 2 shackles each	Verified:	<input checked="" type="radio"/> YES	NO	_____
4- Long lines	Verified:	<input checked="" type="radio"/> YES	NO	_____
4- Short lines	Verified:	<input checked="" type="radio"/> YES	NO	_____
*** 1000' 18" containment boom (Verify Qua	Verified:	<input checked="" type="radio"/> YES	NO	_____
4 Bundles absorbent pads	Verified:	<input checked="" type="radio"/> YES	NO	_____
4- Bundles absorbent boom	Verified:	<input checked="" type="radio"/> YES	NO	_____
1- Roll trash bags	Verified:	<input checked="" type="radio"/> YES	NO	_____
2- Life jackets	Verified:	<input checked="" type="radio"/> YES	NO	_____
1- Pair pliers	Verified:	<input checked="" type="radio"/> YES	NO	_____
1- Skimmer 1800 SH	Verified:	<input checked="" type="radio"/> YES	NO	_____
1- First Aid Kit	Verified:	<input checked="" type="radio"/> YES	NO	_____
1-EyeWash	Verified:	<input checked="" type="radio"/> YES	NO	_____

*** See Boom Condition Report for updated Boom Condition

Comments on above Inventory: Good

OUTSIDE OF TRAILER

		Circle		Comments
Tag in place and current	Tag#	<u>1725M.56</u>		_____
Washed/Clean		<input checked="" type="radio"/> YES	NO	_____
Lights operational		<input checked="" type="radio"/> YES	NO	_____
Trailer tounge greased		<input checked="" type="radio"/> YES	NO	_____
Trailer number visible		<input checked="" type="radio"/> YES	NO	_____
Trailer moved and brakes working		<input checked="" type="radio"/> YES	NO	_____
Tire pressure ok		<input checked="" type="radio"/> YES	NO	_____
Tire tread ok		<input checked="" type="radio"/> YES	NO	_____
Hubs, lugs, and rims ok (need to be grea		<input checked="" type="radio"/> YES	NO	_____
Doors and hinges operating properly		<input checked="" type="radio"/> YES	NO	_____
Locks on doors (trailer secured)		<input checked="" type="radio"/> YES	NO	_____

Condition of Trailer Excellent Good Fair Poor

Comments on above items _____

Inspector: Paul Cunningham
 Print: _____
 Facility Rep
 Print: _____

Signature: Paul Cunningham
 Signature: _____

Notify Facility 24 hrs prior to inspection

Person Notified: _____

Check if Verification only

Moran Environmental Recovery LLC Inspection Sheet

DATE: 6/10/22

LOCATION: MER

Trailer # 6186 Trailer Serial #53FBE2421KF050875 Date Placed in Service:

	Circle one		Comments
4- 26lb Anchors with chain	Verified: <u>YES</u>	NO	_____
4- Buoys with 2 shackles each	Verified: <u>YES</u>	NO	_____
4- Long lines	Verified: <u>YES</u>	NO	_____
4- Short lines	Verified: <u>YES</u>	NO	_____
*** 1000' 18" containment boom (Verify Qua	Verified: <u>YES</u>	NO	_____
4 Bundles absorbent pads	Verified: <u>YES</u>	NO	_____
4- Bundles absorbent boom	Verified: <u>YES</u>	NO	_____
1- Roll trash bags	Verified: <u>YES</u>	NO	_____
2- Life jackets	Verified: <u>YES</u>	NO	_____
1- Pair pliers	Verified: <u>YES</u>	NO	_____
1- Skimmer 1800 SH	Verified: <u>YES</u>	NO	_____
1- First Aid Kit	Verified: <u>YES</u>	NO	_____
1-EyeWash	Verified: <u>YES</u>	NO	_____

*** See Boom Condition Report for updated Boom Condition

Comments on above Inventory: _____

OUTSIDE OF TRAILER

	Circle		Comments
Tag in place and current	Tag#	<u>T25M57</u>	_____
Washed/Clean	<u>YES</u>	NO	_____
Lights operational	<u>YES</u>	NO	_____
Trailer tounge greased	<u>YES</u>	NO	_____
Trailer number visible	<u>YES</u>	NO	_____
Trailer moved and brakes working	<u>YES</u>	NO	_____
Tire pressure ok	<u>YES</u>	NO	_____
Tire tread ok	<u>YES</u>	NO	_____
Hubs, lugs, and rims ok (need to be grea	<u>YES</u>	NO	_____
Doors and hinges operating properly	<u>YES</u>	NO	_____
Locks on doors (trailer secured)	<u>YES</u>	NO	_____

Condition of Trailer Excellent Good Fair Poor

Comments on above items _____

Inspector:
Print: Tracy Cunningham

Facility Rep
Print: _____

Signature: [Signature]

Signature: _____

Notify Facility 24 hrs prior to inspection

Person Notified: _____

Check if Verification only

Moran Environmental Recovery LLC Inspection Sheet

DATE: 8/8/22

LOCATION: MER YARD


TOWABLE BLADDER

		Circle one	Comments
BLADDER #1 Abasco Towable 1000gal	Verified:	<input checked="" type="radio"/> YES NO	_____
Stored in place at MER Yard	Verified:	YES <input checked="" type="radio"/> NO	_____
Deployed and tested			_____

BLADDER #2 Abaso Towable 1000gal	Verified:	<input checked="" type="radio"/> YES NO	_____
Stored in place at MER Yard	Verified:	YES <input checked="" type="radio"/> NO	_____
Deployed and tested			_____

BLADDER #3 Abaso Towable 1000gal			_____
Stored in place at MER Yard			_____
Deployed and tested			_____

Inspector:
Print: Chase Huert

Signature: 

Facility Rep
Print: _____

Signature: _____

Notify Facility 24 hrs prior to inspection

Person Notified: _____

Check if Verification only

Moran Environmental Recovery LLC Inspection Sheet

Vessel Name: Munson

Vessel Make: Custom

Inspection Date: 8-5-22

Unit #: 871

Location: MER Savannah

Last Months Recorded Hours
Current Months Recorded Hours

11.5
15.0

Check items (X)

Check items (X)

Visual Hull Inspection

Check fuel level (full)

Check Batteries

Check oil level

Inspect fuel lines

Spark Plug wires

Inspect Bilge

Boat Clean

Operate Bilge pump

Operate for 15 min

No Electronics

*** VESSEL SHOULD GO THROUGH A SEA TRIAL TO INSURE OPERATING AT PEAK PERFORMANCE A MIN OF ONCE PER QUARTER

Ran Good

Trailer #: _____

Inspector:
Print: Troy Cunningham

Signature: Troy Cunningham

Facility Rep
Print: R. Lee

Signature: R. Lee

Notify Facility 24 hrs prior to inspection

Person Notified: _____

Check if Verification only

Moran Environmental Recovery LLC Inspection Sheet

Vessel Name: Al Allen Vessel Make: Lobelle
Inspection Date: 8-4-22 Unit #: 862
Location: MER Yard

Last Months Recorded Hours _____
Current Months Recorded Hours 195

Check items (X)

Check items (X)

Visual Hull Inspection

Check fuel level (full)

Check Batteries

Check oil level

Inspect fuel lines

Spark Plug wires

Inspect Bilge

Boat Clean

Operate Bilge pump

Operate for 15 min

GPS /VHF Working

*** VESSEL SHOULD GO THROUGH A SEA TRIAL TO INSURE OPERATING AT PEAK PERFORMANCE A MIN OF ONCE PER QUARTER

Ran Good

Trailer #: 6094

Inspector:
Print: Paul Cunningham

Signature: [Signature]

Facility Rep
Print: Sandra Coome

Signature: [Signature]

Notify Facility 24 hrs prior to inspection

Person Notified: _____

Check if Verification only

Moran Environmental Recovery LLC Inspection Sheet

Vessel Name: 34' Barge Boat

Vessel Make: Custom

Inspection Date: 8/5/22

Unit #: 891

Location: MER Savannah

Last Months Recorded Hours
Current Months Recorded Hours

12.5
14.5

Check items (X)

Check items (X)

Visual Hull Inspection

Check fuel level (full)

Check Batteries

Check oil level

Inspect fuel lines

Spark Plug wires

Inspect Bilge

Boat Clean

Operate Bilge pump

Operate for 15 min

No Electronics

*** VESSEL SHOULD GO THROUGH A SEA TRIAL TO INSURE OPERATING AT PEAK PERFORMANCE A MIN OF ONCE PER QUARTER

Trailer #: _____

Inspector:
Print: Travis Cunningham

Signature: Travis Cunningham

Facility Rep
Print: _____

Signature: _____

Notify Facility 24 hrs prior to inspection

Person Notified: _____

Check if Verification only

Moran Environmental Recovery LLC Inspection Sheet

Vessel Name: Porpoise

Vessel Make: Custom

Inspection Date: 8/4/22

Unit #: 835

Location: ~~Phillips 66~~ MC-DI

Last Months Recorded Hours 275.2
Current Months Recorded Hours 275.2

Check items (X)

Check items (X)

Visual Hull Inspection

Check fuel level (full)

Check Batteries

Check oil level

Inspect fuel lines

Spark Plug wires

Inspect Bilge

Boat Clean

Operate Bilge pump

Operate for 15 min

No Electronics

*** VESSEL SHOULD GO THROUGH A SEA TRIAL TO INSURE OPERATING AT PEAK PERFORMANCE A MIN OF ONCE PER QUARTER

Trailer #: 6042

Inspector:
Print: Chase Hurst

Signature: [Signature]

Facility Rep
Print: _____

Signature: _____

Notify Facility 24 hrs prior to inspection

Person Notified: _____

Check if Verification only

Moran Environmental Recovery LLC Inspection Sheet

Vessel Name: 17' Work Boat

Vessel Make: Custom

Inspection Date: 4/8/22

Unit #: 866

Location: MER SAVANNAH

Last Months Recorded Hours
Current Months Recorded Hours

152

Check items (X)

Check items (X)

Visual Hull Inspection

Check fuel level (full)

Check Batteries

Check oil level

Inspect fuel lines

Spark Plug wires

Inspect Bilge

Boat Clean

Operate Bilge pump

Operate for 15 min

No Electronics

*** VESSEL SHOULD GO THROUGH A SEA TRIAL TO INSURE OPERATING AT PEAK PERFORMANCE A MIN OF ONCE PER QUARTER

Ran Great

Trailer #: 6/35

Inspector:

Print: Brad Cunningham

Signature: [Signature]

Facility Rep

Print: _____

Signature: _____

Notify Facility 24 hrs prior to inspection

Person Notified: _____

Check if Verification only

Moran Environmental Recovery LLC Inspection Sheet

Vessel Name: Savannah Patriot

Vessel Make: Custom

Inspection Date: 8/8/22

Unit #: ~~460~~ 465

Location: shop/repairs

Last Months Recorded Hours _____
Current Months Recorded Hours _____

Check items (X)

Check items (X)

Visual Hull Inspection

Check fuel level (full)

Check Batteries

Check oil level

Inspect fuel lines

Spark Plug wires

Inspect Bilge

Boat Clean

Operate Bilge pump

Operate for 15 min

No Electronics

*** VESSEL SHOULD GO THROUGH A SEA TRIAL TO INSURE OPERATING AT PEAK PERFORMANCE A MIN OF ONCE PER QUARTER

In shop for trailer
repairs

Trailer #: _____

Inspector:

Print: Chase Hurst

Signature: [Signature]

Facility Rep

Print: _____

Signature: _____

Notify Facility 24 hrs prior to inspection

Person Notified: _____

Check if Verification only