

Moran Environmental Recovery LLC Inspection Sheet

Vessel Name: Savannah Patriot

Vessel Make: Custom

Inspection Date: 10/28/22

Unit #: 865

Location: Savannah yard

Last Months Recorded Hours
Current Months Recorded Hours

976/996

Check items (X)

Check items (X)

Visual Hull Inspection

Check fuel level (full)

Check Batteries

Check oil level

Inspect fuel lines

Spark Plug wires

Inspect Bilge

Boat Clean

Operate Bilge pump

Operate for 15 min

No Electronics

*** VESSEL SHOULD GO THROUGH A SEA TRIAL TO INSURE OPERATING AT PEAK PERFORMANCE A MIN OF ONCE PER QUARTER

Anchors light out

Starboard motor wont start
port vhf not working

Trailer #: 6113

Inspector:
Print: Chase Hwert

Signature: [Signature]

Facility Rep
Print: _____

Signature: _____

Notify Facility 24 hrs prior to inspection

Person Notified: _____

Check if Verification only

Moran Environmental Recovery LLC Inspection Sheet

Vessel Name: Munson

Vessel Make: Custom

Inspection Date: 10/28/22

Unit #: 471

Location: SAV yard

Last Months Recorded Hours _____
Current Months Recorded Hours 33.4

Check items (X)

Check items (X)

Visual Hull Inspection

Check fuel level (full)

Check Batteries

Check oil level

Inspect fuel lines

Spark Plug wires

Inspect Bilge

Boat Clean

Operate Bilge pump

Operate for 15 min

No Electronics

*** VESSEL SHOULD GO THROUGH A SEA TRIAL TO INSURE OPERATING AT PEAK PERFORMANCE A MIN OF ONCE PER QUARTER

Port Nav light out

Trailer #: 6651

Inspector:

Print: Chase Huest

Signature: [Signature]

Facility Rep

Print: _____

Signature: _____

Notify Facility 24 hrs prior to inspection

Person Notified: _____

Check if Verification only

Moran Environmental Recovery LLC Inspection Sheet

Vessel Name: 17' Work Boat

Vessel Make: Custom

Inspection Date: 10/28/22

Unit #: 466

Location: SAV Yard

Last Months Recorded Hours _____
Current Months Recorded Hours 152

Check items (X)

Check items (X)

Visual Hull Inspection

Check fuel level (full)

Check Batteries

Check oil level

Inspect fuel lines

Spark Plug wires

Inspect Bilge

Boat Clean

Operate Bilge pump

Operate for 15 min

No Electronics

*** VESSEL SHOULD GO THROUGH A SEA TRIAL TO INSURE OPERATING AT PEAK PERFORMANCE A MIN OF ONCE PER QUARTER

Anchors light out

Trailer #: 6135

Inspector:
Print: Chase HUST

Signature: [Signature]

Facility Rep
Print: _____

Signature: _____

Notify Facility 24 hrs prior to inspection

Person Notified: _____

Check if Verification only

Moran Environmental Recovery LLC Inspection Sheet

Vessel Name: 34' Barge Boat

Vessel Make: Custom

Inspection Date: 10/28/22

Unit #: 591

Location: Savannah yard

Last Months Recorded Hours
Current Months Recorded Hours

14.7 / 14.5

Check items (X)

Check items (X)

Visual Hull Inspection

Check fuel level (full)

Check Batteries

Check oil level

Inspect fuel lines

Spark Plug wires

Inspect Bilge

Boat Clean

Operate Bilge pump

Operate for 15 min

No Electronics

*** VESSEL SHOULD GO THROUGH A SEA TRIAL TO INSURE OPERATING AT PEAK PERFORMANCE A MIN OF ONCE PER QUARTER

replace wiper blade
no power to electronics (radar + GPS) Needs unit # decal

Trailer #: L0004

Inspector:

Print: _____

Signature: _____

Facility Rep

Print: _____

Signature: _____

Notify Facility 24 hrs prior to inspection

Person Notified: _____

Check if Verification only

Moran Environmental Recovery LLC Inspection Sheet

DATE: 10/28/22

Location: Phillips 66

Unit #: BR 4

BOOM REELS

	Circle						
Grease Chain	<u>YES</u>	NO					
Grease Fittings	<u>YES</u>	NO					
Inspect sprocket	<u>YES</u>	NO					
Check Oil level in motor	<u>YES</u>	NO					
Reel clear of debris and grass	<u>YES</u>	NO					
Run motor	<u>YES</u>	NO					
Hand Brake operational	<u>YES</u>	NO					
Boom Reel cover secure	YES	<u>NO</u>	<u>Cover torn</u>				
*** 1000ft of 18" containment boom (Verify Quanti	YES	<u>NO</u>					
Condition of Boom Reel Cover			<table border="0" style="width: 100%; text-align: center;"> <tr> <td>Excellent</td> <td>Good</td> <td>Fair</td> <td><u>Poor</u></td> </tr> </table>	Excellent	Good	Fair	<u>Poor</u>
Excellent	Good	Fair	<u>Poor</u>				
Condition of Boom Reel			<table border="0" style="width: 100%; text-align: center;"> <tr> <td>Excellent</td> <td><u>Good</u></td> <td>Fair</td> <td>Poor</td> </tr> </table>	Excellent	<u>Good</u>	Fair	Poor
Excellent	<u>Good</u>	Fair	Poor				

*** See Boom condition Report for updated Boom Condition

Inspector: Chase Hurst Signature: [Signature]

Facility Rep: _____ Signature: _____

Notify Facility 24 hrs prior to inspection

Person Notified: _____



Check if Verification only

Moran Environmental Recovery LLC Inspection Sheet

DATE: 10/28/12

Location: Ocean Terminal

Unit #: BR 1

BOOM REELS

	Circle		Comments								
Grease Chain	<input checked="" type="radio"/> YES	NO	_____								
Grease Fittings	<input checked="" type="radio"/> YES	NO	_____								
Inspect sprocket	<input checked="" type="radio"/> YES	NO	_____								
Check Oil level in motor	<input checked="" type="radio"/> YES	NO	_____								
Reel clear of debris and grass	<input checked="" type="radio"/> YES	NO	_____								
Run motor	<input checked="" type="radio"/> YES	NO	_____								
Hand Brake operational	<input checked="" type="radio"/> YES	NO	_____								
Boom Reel cover secure	<input checked="" type="radio"/> YES	NO	_____								
*** 1000ft of 18" containment boom (Verify Quantiti	YES	<input checked="" type="radio"/> NO	_____								
Condition of Boom Reel Cover			<table border="0" style="width: 100%; font-size: small;"> <tr> <td style="width: 25%;">Excellent</td> <td style="width: 25%;">Good</td> <td style="width: 25%;">Fair</td> <td style="width: 25%; text-align: center;"><input checked="" type="radio"/> Poor</td> </tr> <tr> <td>Excellent</td> <td style="text-align: center;"><input checked="" type="radio"/> Good</td> <td>Fair</td> <td>Poor</td> </tr> </table>	Excellent	Good	Fair	<input checked="" type="radio"/> Poor	Excellent	<input checked="" type="radio"/> Good	Fair	Poor
Excellent	Good	Fair	<input checked="" type="radio"/> Poor								
Excellent	<input checked="" type="radio"/> Good	Fair	Poor								
Condition of Boom Reel			<table border="0" style="width: 100%; font-size: small;"> <tr> <td style="width: 25%;">Excellent</td> <td style="width: 25%; text-align: center;"><input checked="" type="radio"/> Good</td> <td style="width: 25%;">Fair</td> <td style="width: 25%;">Poor</td> </tr> </table>	Excellent	<input checked="" type="radio"/> Good	Fair	Poor				
Excellent	<input checked="" type="radio"/> Good	Fair	Poor								

*** See Boom condition Report for updated Boom Condition

Inspector: _____
 Print: Chase Hunt Signature: [Signature]

Facility Rep _____
 Print: _____ Signature: _____

Notify Facility 24 hrs prior to inspection

Check if Verification only

Person Notified: _____

Moran Environmental Recovery LLC Inspection Sheet

DATE: 10/28/22

LOCATION: Colonial Terminal

INSIDE CONTAINER

		Circle one	Comments
6- 26lb Anchors with chain	Verified: YES	<input checked="" type="radio"/> NO	_____
4- Buoys with 2 shackles each	Verified: YES	<input checked="" type="radio"/> NO	_____
2 spools of line	Verified: YES	<input checked="" type="radio"/> NO	_____
2000' 18" containment boom (verification of)	Verified: YES	<input checked="" type="radio"/> NO	_____
4 Bundles absorbent pads	Verified: YES	<input checked="" type="radio"/> NO	_____
4- Bundles absorbent boom	Verified: YES	<input checked="" type="radio"/> NO	_____
1- Roll trash bags	Verified: YES	<input checked="" type="radio"/> NO	_____
1- Pair pliers	Verified: YES	<input checked="" type="radio"/> NO	_____
1- First Aid Kit	Verified: YES	<input checked="" type="radio"/> NO	_____
1-Eye Wash	Verified: YES	<input checked="" type="radio"/> NO	_____

OUTSIDE CONTAINER

Box number 3

Container accessible Verified: YES NO _____

Seal in place Verified: YES NO 0485645/0485987

Seal number _____

Container Temp Hi _____ Lo _____ Date: _____

Inspector:
Print: Chase Hurd

Signature: [Signature]

Facility Rep
Print: Tom Dolan

Signature: [Signature]

Notify Facility 24 hrs prior to inspection

Person Notified: _____

Check if Verification only

Moran Environmental Recovery LLC Inspection Sheet

DATE: 10/28/22

LOCATION: Metro Ports

INSIDE CONTAINER

		Circle one	Comments
6- 26lb Anchors with chain	Verified: YES	<input checked="" type="radio"/> NO	_____
4- Buoys with 2 shackles each	Verified: YES	<input checked="" type="radio"/> NO	_____
2 spools of line	Verified: YES	<input checked="" type="radio"/> NO	_____
2000' 18" containment boom (verification of)	Verified: YES	<input checked="" type="radio"/> NO	_____
4 Bundles absorbent pads	Verified: YES	<input checked="" type="radio"/> NO	_____
4- Bundles absorbent boom	Verified: YES	<input checked="" type="radio"/> NO	_____
1- Roll trash bags	Verified: YES	<input checked="" type="radio"/> NO	_____
1- Pair pliers	Verified: YES	<input checked="" type="radio"/> NO	_____
1- First Aid Kit	Verified: YES	<input checked="" type="radio"/> NO	_____
1-Eye Wash	Verified: YES	<input checked="" type="radio"/> NO	_____

OUTSIDE CONTAINER

Box number 5

Container accessible Verified: YES NO _____

Seal in place Verified: YES NO 1633128/1633123

Seal number _____

Container Temp Hi _____ Lo _____ Date: _____

Inspector:
Print: Chase Huot

Signature: [Signature]

Facility Rep:
Print: Tom Dolan

Signature: [Signature]

Notify Facility 24 hrs prior to inspection

Person Notified: _____



Check if Verification only

Moran Environmental Recovery LLC Inspection Sheet

DATE: 10/28/22

LOCATION: Metro Ports

INSIDE CONTAINER

		Circle one	Comments
6- 26lb Anchors with chain	Verified: YES	<input checked="" type="radio"/> NO	_____
4- Buoys with 2 shackles each	Verified: YES	<input checked="" type="radio"/> NO	_____
2 spools of line	Verified: YES	<input checked="" type="radio"/> NO	_____
2000' 18" containment boom (verification of)	Verified: YES	<input checked="" type="radio"/> NO	_____
4 Bundles absorbent pads	Verified: YES	<input checked="" type="radio"/> NO	_____
4- Bundles absorbent boom	Verified: YES	<input checked="" type="radio"/> NO	_____
1- Roll trash bags	Verified: YES	<input checked="" type="radio"/> NO	_____
1- Pair pliers	Verified: YES	<input checked="" type="radio"/> NO	_____
1- First Aid Kit	Verified: YES	<input checked="" type="radio"/> NO	_____
1-Eye Wash	Verified: YES	<input checked="" type="radio"/> NO	_____

OUTSIDE CONTAINER

Box number 6

Container accessible Verified: YES NO _____

Seal in place Verified: YES NO 1633024 / 1633062

Seal number _____

Container Temp Hi _____ Lo _____ Date: _____

Inspector:
Print: Chase Hurst

Signature: [Signature]

Facility Rep
Print: [Signature]

Signature: [Signature]

Notify Facility 24 hrs prior to inspection

Person Notified: _____

Check if Verification only

Moran Environmental Recovery LLC Inspection Sheet

DATE: 10/20/22

LOCATION: VOPAK

Trailer # 6017 Trailer Serial # 4X4TSEZ253U202767 Date Placed in Service: 2003

	Circle one	Comments
4- 26lb Anchors with chain	Verified: <u>YES</u> NO	
4- Buoys with 2 shackles each	Verified: <u>YES</u> NO	
4- Long lines	Verified: <u>YES</u> NO	
4- Short lines	Verified: <u>YES</u> NO	
*** 1000' 18" containment boom (Verify Qua	Verified: <u>YES</u> NO	
4 Bundles absorbent pads	Verified: <u>YES</u> NO	
4- Bundles absorbent boom	Verified: <u>YES</u> NO	
1- Roll trash bags	Verified: <u>YES</u> NO	
2- Life jackets	Verified: <u>YES</u> NO	
1- Pair pliers	Verified: <u>YES</u> NO	
1- Skimmer 1800 SH	Verified: <u>YES</u> NO	
1- First Aid Kit	Verified: <u>YES</u> NO	
1-EyeWash	Verified: <u>YES</u> NO	

*** See Boom Condition Report for updated Boom Condition

Comments on above Inventory: _____

OUTSIDE OF TRAILER

	Circle	Comments
Tag in place and current	Tag# <u>65363 AB</u>	<u>July 23 DOT APR 22</u>
Washed/Clean	<u>YES</u> NO	
Lights operational	<u>YES</u> NO	
Trailer tounge greased	<u>YES</u> NO	
Trailer number visible	<u>YES</u> NO	
Trailer moved and brakes working	<u>YES</u> NO	
Tire pressure ok	<u>YES</u> NO	
Tire tread ok	<u>YES</u> NO	
Hubs, lugs, and rims ok (need to be grea	<u>YES</u> NO	
Doors and hinges operating properly	<u>YES</u> NO	
Locks on doors (trailer secured)	<u>YES</u> NO	<u>020606/1633061</u>
Condition of Trailer	Excellent <u>Good</u> Fair Poor	

Comments on above items _____

Inspector:
 Print: Chase Hurst

Signature: [Signature]

Facility Rep
 Print: Morgan Francisco

Signature: [Signature]

Notify Facility 24 hrs prior to inspection

Person Notified: _____

Check if Verification only

Moran Environmental Recovery LLC Inspection Sheet

DATE: 10/28/22

LOCATION: IMTT North

INSIDE CONTAINER

		Circle one	Comments
6- 26lb Anchors with chain	Verified: YES	<input checked="" type="radio"/> NO	_____
4- Buoys with 2 shackles each	Verified: YES	<input checked="" type="radio"/> NO	_____
2 spools of line	Verified: YES	<input checked="" type="radio"/> NO	_____
2000' 18" containment boom (verification of)	Verified: YES	<input checked="" type="radio"/> NO	_____
4 Bundles absorbent pads	Verified: YES	<input checked="" type="radio"/> NO	_____
4- Bundles absorbent boom	Verified: YES	<input checked="" type="radio"/> NO	_____
1- Roll trash bags	Verified: YES	<input checked="" type="radio"/> NO	_____
1- Pair pliers	Verified: YES	<input checked="" type="radio"/> NO	_____
1- First Aid Kit	Verified: YES	<input checked="" type="radio"/> NO	_____
1-Eye Wash	Verified: YES	<input checked="" type="radio"/> NO	_____

OUTSIDE CONTAINER

Box number 4

Container accessible Verified: YES NO _____

Seal in place Verified: YES NO 1633122/1633121

Seal number _____

Container Temp Hi _____ Lo _____ Date: _____

Inspector: Chris Hurst
Print: _____

Signature: [Signature]

Facility Rep: Kurt White
Print: _____

Signature: [Signature]

Notify Facility 24 hrs prior to inspection

Person Notified: _____

Check if Verification only

Moran Environmental Recovery LLC Inspection Sheet

DATE: 10/27/22

LOCATION: Plant McIntosh

INSIDE CONTAINER

		Circle one	Comments
6- 26lb Anchors with chain	Verified: YES	<input checked="" type="radio"/> NO	_____
4- Buoys with 2 shackles each	Verified: YES	<input checked="" type="radio"/> NO	_____
2 spools of line	Verified: YES	<input checked="" type="radio"/> NO	_____
2000' 18" containment boom (verification of	Verified: YES	<input checked="" type="radio"/> NO	_____
4 Bundles absorbent pads	Verified: YES	<input checked="" type="radio"/> NO	_____
4- Bundles absorbent boom	Verified: YES	<input checked="" type="radio"/> NO	_____
1- Roll trash bags	Verified: YES	<input checked="" type="radio"/> NO	_____
1- Pair pliers	Verified: YES	<input checked="" type="radio"/> NO	_____
1- First Aid Kit	Verified: YES	<input checked="" type="radio"/> NO	_____
1-Eye Wash	Verified: YES	<input checked="" type="radio"/> NO	_____

OUTSIDE CONTAINER

Box number 8

Container accessible Verified: YES NO

Seal in place Verified: YES NO 1633005 / 1633008

Seal number _____

Container Temp Hi _____ Lo _____ Date: _____

Inspector:
Print: Chase Hurst

Signature: [Signature]

Facility Rep
Print: Owen Bryant

Signature: [Signature]

Notify Facility 24 hrs prior to inspection

Person Notified: _____

Check if Verification only

Moran Environmental Recovery LLC Inspection Sheet

DATE: 10/28/22

LOCATION: MER Yard

INSIDE CONTAINER

		Circle one	
6- 26lb Anchors with chain	Verified:	<input checked="" type="radio"/> YES NO	_____
4- Buoys with 2 shackles each	Verified:	<input checked="" type="radio"/> YES NO	_____
2 spools of line	Verified:	<input checked="" type="radio"/> YES NO	_____
2000' 18" containment boom (verification of)	Verified:	<input checked="" type="radio"/> YES NO	_____
4 Bundles absorbent pads	Verified:	<input checked="" type="radio"/> YES NO	_____
4- Bundles absorbent boom	Verified:	<input checked="" type="radio"/> YES NO	_____
1- Roll trash bags	Verified:	<input checked="" type="radio"/> YES NO	_____
1- Pair pliers	Verified:	<input checked="" type="radio"/> YES NO	_____
1- First Aid Kit	Verified:	<input checked="" type="radio"/> YES NO	_____
1-Eye Wash	Verified:	<input checked="" type="radio"/> YES NO	_____

OUTSIDE CONTAINER

Box number 7

Container accessible Verified: YES NO

Seal in place Verified: YES NO

Seal number _____

Container Temp Hi _____ Lo _____ Date: _____

Inspector: Chase Hewet
Print: _____

Signature: [Signature]

Facility Rep
Print: _____

Signature: _____

Notify Facility 24 hrs prior to inspection

Person Notified: _____

Check if Verification only

Moran Environmental Recovery LLC Inspection Sheet

DATE: 10/18/22

LOCATION: MER Yard

INSIDE CONTAINER

		Circle one	Comments
6- 26lb Anchors with chain	Verified:	<input checked="" type="radio"/> YES NO	_____
4- Buoys with 2 shackles each	Verified:	<input checked="" type="radio"/> YES NO	_____
2 spools of line	Verified:	<input checked="" type="radio"/> YES NO	_____
2000' 18" containment boom (verification of)	Verified:	YES <input checked="" type="radio"/> NO	<u>only 1000 ft</u>
4 Bundles absorbent pads	Verified:	<input checked="" type="radio"/> YES NO	_____
4- Bundles absorbent boom	Verified:	<input checked="" type="radio"/> YES NO	_____
1- Roll trash bags	Verified:	<input checked="" type="radio"/> YES NO	_____
1- Pair pliers	Verified:	<input checked="" type="radio"/> YES NO	_____
1- First Aid Kit	Verified:	<input checked="" type="radio"/> YES NO	_____
1-Eye Wash	Verified:	<input checked="" type="radio"/> YES NO	_____

OUTSIDE CONTAINER

Box number 9

Container accessible Verified: YES NO _____

Seal in place Verified: YES NO _____

Seal number _____

Container Temp Hi _____ Lo _____ Date: _____

Inspector:
Print: Chase Hurst

Signature: [Handwritten Signature]

Facility Rep
Print: _____

Signature: _____

Notify Facility 24 hrs prior to inspection

Person Notified: _____

Check if Verification only

Moran Environmental Recovery LLC Inspection Sheet

DATE: 10/18/12

LOCATION: _____

INSIDE CONTAINER

		Circle one	Comments
6- 26lb Anchors with chain	Verified: YES	<input checked="" type="radio"/> NO	<u>Empty</u>
4- Buoys with 2 shackles each	Verified: YES	<input checked="" type="radio"/> NO	
2 spools of line	Verified: YES	<input checked="" type="radio"/> NO	
2000' 18" containment boom (verification of)	Verified: YES	<input checked="" type="radio"/> NO	
4 Bundles absorbent pads	Verified: YES	<input checked="" type="radio"/> NO	
4- Bundles absorbent boom	Verified: YES	<input checked="" type="radio"/> NO	
1- Roll trash bags	Verified: YES	<input checked="" type="radio"/> NO	
1- Pair pliers	Verified: YES	<input checked="" type="radio"/> NO	
1- First Aid Kit	Verified: YES	<input checked="" type="radio"/> NO	
1-Eye Wash	Verified: YES	<input checked="" type="radio"/> NO	

OUTSIDE CONTAINER

Box number 10

Container accessible Verified: YES NO

Seal in place Verified: YES NO

Seal number _____

Container Temp Hi _____ Lo _____ Date: _____

Inspector:
Print: Chase Huest

Signature: [Handwritten Signature]

Facility Rep
Print: _____

Signature: _____

Notify Facility 24 hrs prior to inspection

Person Notified: _____

Check if Verification only

Moran Environmental Recovery LLC Inspection Sheet

DATE: 10/28/12

LOCATION: MER YARD

TOWABLE BLADDER

	Circle one	
BLADDER #1 Abasco Towable 1000gal		
Stored in place at MER Yard	Verified: <u>YES</u> NO	_____
Deployed and tested	Verified: YES <u>NO</u>	_____

BLADDER #2 Abaso Towable 1000gal		
Stored in place at MER Yard	Verified: <u>YES</u> NO	_____
Deployed and tested	Verified: YES <u>NO</u>	_____

BLADDER #3 Abaso Towable 1000gal		
Stored in place at MER Yard	<u>yes</u> <u>no</u>	_____
Deployed and tested	<u>yes</u> <u>no</u>	_____

Inspector:
Print: Chase Hurst

Signature: [Handwritten Signature]

Facility Rep
Print: _____

Signature: _____

Notify Facility 24 hrs prior to inspection
Person Notified: _____

Check if Verification only

Moran Environmental Recovery LLC Inspection Sheet

Vessel Name: Porpoise

Vessel Make: Custom

Inspection Date: 10/19/12

Unit #: 835

Location: Phillips 66

Last Months Recorded Hours _____
Current Months Recorded Hours 852

Check items (X)

Check items (X)

Visual Hull Inspection

Check fuel level (full)

Check Batteries

Check oil level

Inspect fuel lines

Spark Plug wires

Inspect Bilge

Boat Clean

Operate Bilge pump

Operate for 15 min

No Electronics

*** VESSEL SHOULD GO THROUGH A SEA TRIAL TO INSURE OPERATING AT PEAK PERFORMANCE A MIN OF ONCE PER QUARTER

Not Start

Trailer #: 6042

Inspector:
Print: Chase Ilwst

Signature: [Signature]

Facility Rep
Print: _____

Signature: _____

Notify Facility 24 hrs prior to inspection

Person Notified: _____

Check if Verification only

Moran Environmental Recovery LLC Inspection Sheet

DATE: 10/28/22

LOCATION: Elba Island

INSIDE CONTAINER

		Circle one	Comments
6- 26lb Anchors with chain	Verified:	YES NO	_____
4- Buoys with 2 shackles each	Verified:	YES NO	_____
2 spools of line	Verified:	YES NO	_____
2000' 18" containment boom (verification of)	Verified:	YES NO	_____
4 Bundles absorbent pads	Verified:	YES NO	_____
4- Bundles absorbent boom	Verified:	YES NO	_____
1- Roll trash bags	Verified:	YES NO	_____
1- Pair pliers	Verified:	YES NO	_____
1- First Aid Kit	Verified:	YES NO	_____
1-Eye Wash	Verified:	YES NO	_____

OUTSIDE CONTAINER

Box number 2

Container accessible Verified: YES NO _____

Seal in place Verified: YES NO _____

Seal number _____

Container Temp Hi _____ Lo _____ Date: _____

Inspector:
Print: Chase Hurst

Signature: [Handwritten Signature]

Facility Rep
Print: _____

Signature: _____

Notify Facility 24 hrs prior to inspection

Person Notified: _____

Check if Verification only

in Florida for Hurricane clean up

Moran Environmental Recovery LLC Inspection Sheet

DATE: 10/28/22

LOCATION: Elba Island

INSIDE CONTAINER

		Circle one	
6- 26lb Anchors with chain	Verified:	YES NO	_____
4- Buoys with 2 shackles each	Verified:	YES NO	_____
2 spools of line	Verified:	YES NO	_____
2000' 18" containment boom (verification of)	Verified:	YES NO	_____
4 Bundles absorbent pads	Verified:	YES NO	_____
4- Bundles absorbent boom	Verified:	YES NO	_____
1- Roll trash bags	Verified:	YES NO	_____
1- Pair pliers	Verified:	YES NO	_____
1- First Aid Kit	Verified:	YES NO	_____
1-Eye Wash	Verified:	YES NO	_____

OUTSIDE CONTAINER

Box number 1
 Container accessible Verified: YES NO _____
 Seal in place Verified: YES NO _____
 Seal number _____
 Container Temp Hi _____ Lo _____ Date: _____

Inspector: Chase Hurst
 Print: _____

Signature: [Signature] _____

Facility Rep
 Print: _____

Signature: _____

Notify Facility 24 hrs prior to inspection

Person Notified: _____

Check if Verification only

in florida for hurricane clean up

Moran Environmental Recovery LLC Inspection Sheet

Vessel Name: Al Allen

Vessel Make: Lobelle

Inspection Date: 10/28/22

Unit #: 862

Location: MER Yard

Last Months Recorded Hours 197
Current Months Recorded Hours 197

Check items (X)

Check items (X)

Visual Hull Inspection

Check fuel level (full)

Check Batteries

Check oil level

Inspect fuel lines

Spark Plug wires

Inspect Bilge

Boat Clean

Operate Bilge pump

Operate for 15 min

GPS /VHF Working

*** VESSEL SHOULD GO THROUGH A SEA TRIAL TO INSURE OPERATING AT PEAK PERFORMANCE A MIN OF ONCE PER QUARTER

Wont start
Batteries left on when removed (fixed 11/1/22)

Trailer #: 6094

Inspector:

Print: Chris West

Signature: [Signature]

Facility Rep

Print: _____

Signature: _____

Notify Facility 24 hrs prior to inspection

Person Notified: _____

Check if Verification only

Moran Environmental Recovery LLC Inspection Sheet

DATE: 10/28/22

LOCATION: MER

Trailer # 6188

Trailer Serial #

Date Placed in Service:

Circle one

Comments

4- 26lb Anchors with chain	Verified:	YES	NO	_____
4- Buoys with 2 shackles each	Verified:	YES	NO	_____
4- Long lines	Verified:	YES	NO	_____
4- Short lines	Verified:	YES	NO	_____
*** 1000' 18" containment boom (Verify Qua	Verified:	YES	NO	_____
4 Bundles absorbent pads	Verified:	YES	NO	_____
4- Bundles absorbent boom	Verified:	YES	NO	_____
1- Roll trash bags	Verified:	YES	NO	_____
2- Life jackets	Verified:	YES	NO	_____
1- Pair pliers	Verified:	YES	NO	_____
1- Skimmer 1800 SH	Verified:	YES	NO	_____
1- First Aid Kit	Verified:	YES	NO	_____
1-EyeWash	Verified:	YES	NO	_____

*** See Boom Condition Report for updated Boom Condition

Comments on above inventory: _____

OUTSIDE OF TRAILER

Circle

Comments

Tag in place and current	Tag#			
Washed/Clean		YES	NO	_____
Lights operational		YES	NO	_____
Trailer tounge greased		YES	NO	_____
Trailer number visible		YES	NO	_____
Trailer moved and brakes working		YES	NO	_____
Tire pressure ok		YES	NO	_____
Tire tread ok		YES	NO	_____
Hubs, lugs, and rims ok (need to be grea		YES	NO	_____
Doors and hinges operating properly		YES	NO	_____
Locks on doors (trailer secured)		YES	NO	_____

Condition of Trailer

Excellent Good Fair Poor

Comments on above items Out for repairs

Inspector: R. Chase Hurst

Signature: [Signature]

Facility Rep
Print: _____

Signature: _____

Notify Facility 24 hrs prior to inspection

Person Notified: _____

Check if Verification only

Moran Environmental Recovery LLC Inspection Sheet

DATE: 10/28/22

Location: Imperial Sugar

Unit #: BR 5

BOOM REELS

	Circle	Comments
Grease Chain	YES <input type="radio"/> NO <input checked="" type="radio"/>	
Grease Fittings	YES <input type="radio"/> NO <input checked="" type="radio"/>	
Inspect sprocket	YES <input type="radio"/> NO <input checked="" type="radio"/>	
Check Oil level in motor	YES <input type="radio"/> NO <input checked="" type="radio"/>	
Reel clear of debris and grass	YES <input type="radio"/> NO <input checked="" type="radio"/>	
Run motor	YES <input type="radio"/> NO <input checked="" type="radio"/>	
Hand Brake operational	YES <input type="radio"/> NO <input checked="" type="radio"/>	
Boom Reel cover secure	YES <input type="radio"/> NO <input checked="" type="radio"/>	
*** 1000ft of 18" containment boom (Verify Quantiti	YES <input type="radio"/> NO <input checked="" type="radio"/>	
Condition of Boom Reel Cover		Excellent Good Fair <input checked="" type="radio"/> Poor
Condition of Boom Reel		Excellent Good Fair <input checked="" type="radio"/> Poor

*** See Boom condition Report for updated Boom Condition

Inspector: Chase Hurst Signature: [Signature]

Facility Rep Print: _____ Signature: _____

Notify Facility 24 hrs prior to inspection

Person Notified: _____

 Check if Verification only

Moran Environmental Recovery LLC Inspection Sheet

DATE: 10/28/22 LOCATION: MER YARD
SKIMMER TRAILER

Trailer #: 6020 Tag#: 29691 AC
 Removed: YES NO

SKIMMERS

- SK-1
 Elastic Drum Skimmer Hydrolic TDSH13699178
 - Condition Circle: Excellent Good Poor Fair
 - Last Run Test Date: 9/1/22
 Comment: _____
- SK-2
 Action Pertolium Drum Skimmer Air driven Mod 18A Serial # 314
 - Condition Circle: Excellent Good Poor Fair
 - Last Run Test Date: 9/1/22
 Comment: _____
- SK-3
 Crucial Coated Drum Skimmer Mod#1CD18H36 Ser#214468
 -Condition Circle: Excellent Good Poor Fair
 -Last RunTest Date: 9/1/22
 Comment: _____

PUMPS

- PM-1
 3in Hydrolic Submersible Pump Serial # 11197
 - Condition Circle: Excellent Good Poor Fair
 - Last Run Test Date: 9/1/22
 Comment: _____
- PM-2
 4in Vickers Hydrolic Submersible Pump Serial # 25M65A1C20
 - Condition Circle: Excellent Good Poor Fair
 - Last Run Test Date: 9/1/22
 Comment: _____
- PM-3
 6in Hydrotech Hydrolic Submersible Pump Serial # 6F878
 - Condition Circle: Excellent Good Poor Fair
 - Last Run Test Date: 9/1/22
 Comment: _____
- PM-4
 3" Crucial Diesel SD Pump Mod#DDP-3 Ser#214468
 -Condition Circle: Excellent Good Poor Fair
 -Last Run Test Date: 9/1/22
 Comment: _____

POWER PACKS

- PP-1
 Elastic Power Pack Serial # H1198258
 - Condition Circle: Excellent Good Poor Fair
 - Last Run Test Date: 9/1/22
 Comment: _____
- PP-2
 739 Hydrotech Power Pack Mod # HT60DCV Serial # F
 - Condition Circle: Excellent Good Poor Fair
 - Last Run Test Date: 9/1/22
 Comment: _____
- PP-3
 Crucial Diesel Compre: **Mod#L70190126P17E Ser#214468**
 -Condition Circle: Excellent Good Poor Fair
 -Last Run Test Date: 9/1/22
 Comment: _____

Inspector: Chase Hurst
 Print: _____

Signature: [Signature]

Inspector: _____
 Print: _____

Signature: _____

Moran Environmental Recovery LLC Inspection Sheet

DATE: 10/28/22

LOCATION: MER

Trailer # 6187

Trailer Serial # _____

Date Placed in Service: _____

			Circle one	Comments
4- 26lb Anchors with chain	Verified:	YES	<input checked="" type="radio"/> NO	_____
4- Buoys with 2 shackles each	Verified:	YES	<input checked="" type="radio"/> NO	_____
4- Long lines	Verified:	YES	<input checked="" type="radio"/> NO	_____
4- Short lines	Verified:	YES	<input checked="" type="radio"/> NO	_____
*** 1000' 18" containment boom (Verify Qua	Verified:	YES	<input checked="" type="radio"/> NO	_____
4 Bundles absorbent pads	Verified:	YES	<input checked="" type="radio"/> NO	_____
4- Bundles absorbent boom	Verified:	YES	<input checked="" type="radio"/> NO	_____
1- Roll trash bags	Verified:	YES	<input checked="" type="radio"/> NO	_____
2- Life jackets	Verified:	YES	<input checked="" type="radio"/> NO	_____
1- Pair pliers	Verified:	YES	<input checked="" type="radio"/> NO	_____
1- Skimmer 1800 SH	Verified:	YES	<input checked="" type="radio"/> NO	_____
1- First Aid Kit	Verified:	YES	<input checked="" type="radio"/> NO	_____
1-EyeWash	Verified:	YES	<input checked="" type="radio"/> NO	_____

*** See Boom Condition Report for updated Boom Condition

Comments on above Inventory: _____

OUTSIDE OF TRAILER

		Circle		Comments
Tag in place and current	Tag#		<u>TTAS M65</u>	_____
Washed/Clean		<input checked="" type="radio"/> YES	NO	_____
Lights operational		<input checked="" type="radio"/> YES	NO	_____
Trailer tounge greased		<input checked="" type="radio"/> YES	NO	_____
Trailer number visible		<input checked="" type="radio"/> YES	NO	_____
Trailer moved and brakes working		<input checked="" type="radio"/> YES	NO	_____
Tire pressure ok		<input checked="" type="radio"/> YES	NO	_____
Tire tread ok		<input checked="" type="radio"/> YES	NO	_____
Hubs, lugs, and rims ok (need to be grea		<input checked="" type="radio"/> YES	NO	_____
Doors and hinges operating properly		<input checked="" type="radio"/> YES	NO	_____
Locks on doors (trailer secured)		<input checked="" type="radio"/> YES	NO	_____
Condition of Trailer			Excellent <input checked="" type="radio"/> Good Fair Poor	_____

Comments on above items _____

Inspector:
 Print: Chase Hwot

Signature: [Signature]

Facility Rep
 Print: _____

Signature: _____

Notify Facility 24 hrs prior to inspection

Person Notified: _____



Check if Verification only

Moran Environmental Recovery LLC Inspection Sheet

DATE: 10/28/22

LOCATION: MER

Trailer # 6186 Trailer Serial #53FBE2421KF050875 Date Placed in Service: _____

		Circle one		Comments
4- 26lb Anchors with chain	Verified:	<input checked="" type="radio"/> YES	NO	_____
4- Buoys with 2 shackles each	Verified:	<input checked="" type="radio"/> YES	NO	_____
4- Long lines	Verified:	<input checked="" type="radio"/> YES	NO	_____
4- Short lines	Verified:	<input checked="" type="radio"/> YES	NO	_____
*** 1000' 18" containment boom (Verify Qua	Verified:	<input checked="" type="radio"/> YES	NO	_____
4 Bundles absorbent pads	Verified:	<input checked="" type="radio"/> YES	NO	_____
4- Bundles absorbent boom	Verified:	<input checked="" type="radio"/> YES	NO	_____
1- Roll trash bags	Verified:	<input checked="" type="radio"/> YES	NO	_____
2- Life jackets	Verified:	<input checked="" type="radio"/> YES	NO	_____
1- Pair pliers	Verified:	<input checked="" type="radio"/> YES	NO	_____
1- Skimmer 1800 SH	Verified:	<input checked="" type="radio"/> YES	NO	_____
1- First Aid Kit	Verified:	<input checked="" type="radio"/> YES	NO	_____
1-EyeWash	Verified:	<input checked="" type="radio"/> YES	NO	_____

*** See Boom Condition Report for updated Boom Condition

Comments on above Inventory: _____

OUTSIDE OF TRAILER

		Circle		Comments
Tag in place and current	Tag#	<u>TI 25M57</u>		_____
Washed/Clean		<input checked="" type="radio"/> YES	NO	_____
Lights operational		<input checked="" type="radio"/> YES	NO	_____
Trailer tounge greased		<input checked="" type="radio"/> YES	NO	_____
Trailer number visible		<input checked="" type="radio"/> YES	NO	_____
Trailer moved and brakes working		<input checked="" type="radio"/> YES	NO	_____
Tire pressure ok		<input checked="" type="radio"/> YES	NO	_____
Tire tread ok		<input checked="" type="radio"/> YES	NO	_____
Hubs, lugs, and rims ok (need to be grea		<input checked="" type="radio"/> YES	NO	_____
Doors and hinges operating properly		<input checked="" type="radio"/> YES	NO	_____
Locks on doors (trailer secured)		<input checked="" type="radio"/> YES	NO	_____
Condition of Trailer		Excellent	<input checked="" type="radio"/> Good	Fair Poor

Comments on above items _____

Inspector
 Print: Chase Huest

Signature: [Signature]

Facility Rep
 Print: _____

Signature: _____

Notify Facility 24 hrs prior to inspection

Person Notified: _____

Check if Verification only

Moran Environmental Recovery LLC Inspection Sheet

DATE: 10/28/22

LOCATION: MER

Trailer # 6189 Trailer Serial # 53FBE2426KF050872 Date Placed in Service: _____

		Circle one	Comments
4- 26lb Anchors with chain	Verified: YES	<input checked="" type="radio"/> NO	_____
4- Buoys with 2 shackles each	Verified: YES	<input checked="" type="radio"/> NO	_____
4- Long lines	Verified: YES	<input checked="" type="radio"/> NO	_____
4- Short lines	Verified: YES	<input checked="" type="radio"/> NO	_____
*** 1000' 18" containment boom (Verify Qua	Verified: YES	<input checked="" type="radio"/> NO	_____
4 Bundles absorbent pads	Verified: YES	<input checked="" type="radio"/> NO	_____
4- Bundles absorbent boom	Verified: YES	<input checked="" type="radio"/> NO	_____
1- Roll trash bags	Verified: YES	<input checked="" type="radio"/> NO	_____
2- Life jackets	Verified: YES	<input checked="" type="radio"/> NO	_____
1- Pair pliers	Verified: YES	<input checked="" type="radio"/> NO	_____
1- Skimmer 1800 SH	Verified: YES	<input checked="" type="radio"/> NO	_____
1- First Aid Kit	Verified: YES	<input checked="" type="radio"/> NO	_____
1-EyeWash	Verified: YES	<input checked="" type="radio"/> NO	_____

*** See Boom Condition Report for updated Boom Condition

Comments on above Inventory: _____

OUTSIDE OF TRAILER

		Circle	Comments
Tag in place and current	Tag#	<u>T135W73</u>	_____
Washed/Clean		<input checked="" type="radio"/> YES <input type="radio"/> NO	_____
Lights operational		<input checked="" type="radio"/> YES <input type="radio"/> NO	_____
Trailer tounge greased		<input checked="" type="radio"/> YES <input type="radio"/> NO	_____
Trailer number visible		<input checked="" type="radio"/> YES <input type="radio"/> NO	_____
Trailer moved and brakes working		<input checked="" type="radio"/> YES <input type="radio"/> NO	_____
Tire pressure ok		<input checked="" type="radio"/> YES <input type="radio"/> NO	_____
Tire tread ok		<input checked="" type="radio"/> YES <input type="radio"/> NO	_____
Hubs, lugs, and rims ok (need to be grea		<input checked="" type="radio"/> YES <input type="radio"/> NO	_____
Doors and hinges operating properly		<input checked="" type="radio"/> YES <input type="radio"/> NO	_____
Locks on doors (trailer secured)		<input checked="" type="radio"/> YES <input type="radio"/> NO	_____

Condition of Trailer Excellent Good Fair Poor

Comments on above items _____

Inspector: _____
 Print: Chase Huest Signature: [Signature]

Facility Rep _____
 Print: _____ Signature: _____

Notify Facility 24 hrs prior to inspection

Person Notified: _____

c

 Check if Verification only

Moran Environmental Recovery LLC Inspection Sheet

DATE: 10/28/22

LOCATION: MER

Trailer # 6190 Trailer Serial # 53FBE2427KF050878 Date Placed in Service: _____

		Circle one		Comments
4- 26lb Anchors with chain	Verified:	<input checked="" type="radio"/> YES	<input type="radio"/> NO	_____
4- Buoys with 2 shackles each	Verified:	<input checked="" type="radio"/> YES	<input type="radio"/> NO	_____
4- Long lines	Verified:	<input checked="" type="radio"/> YES	<input type="radio"/> NO	_____
4- Short lines	Verified:	<input checked="" type="radio"/> YES	<input type="radio"/> NO	_____
*** 1000' 18" containment boom (Verify Qua	Verified:	<input checked="" type="radio"/> YES	<input type="radio"/> NO	_____
4 Bundles absorbent pads	Verified:	<input checked="" type="radio"/> YES	<input type="radio"/> NO	_____
4- Bundles absorbent boom	Verified:	<input checked="" type="radio"/> YES	<input type="radio"/> NO	_____
1- Roll trash bags	Verified:	<input checked="" type="radio"/> YES	<input type="radio"/> NO	_____
2- Life jackets	Verified:	<input checked="" type="radio"/> YES	<input type="radio"/> NO	_____
1- Pair pliers	Verified:	<input checked="" type="radio"/> YES	<input type="radio"/> NO	_____
1- Skimmer 1800 SH	Verified:	<input checked="" type="radio"/> YES	<input type="radio"/> NO	_____
1- First Aid Kit	Verified:	<input checked="" type="radio"/> YES	<input type="radio"/> NO	_____
1-EyeWash	Verified:	<input checked="" type="radio"/> YES	<input type="radio"/> NO	_____

*** See Boom Condition Report for updated Boom Condition

Comments on above Inventory: _____

OUTSIDE OF TRAILER

		Circle		Comments
Tag in place and current	Tag#	<u>TT25m56</u>		_____
Washed/Clean		<input checked="" type="radio"/> YES	<input type="radio"/> NO	_____
Lights operational		<input checked="" type="radio"/> YES	<input type="radio"/> NO	_____
Trailer tongue greased		<input checked="" type="radio"/> YES	<input type="radio"/> NO	_____
Trailer number visible		<input checked="" type="radio"/> YES	<input type="radio"/> NO	_____
Trailer moved and brakes working		<input checked="" type="radio"/> YES	<input type="radio"/> NO	_____
Tire pressure ok		<input checked="" type="radio"/> YES	<input type="radio"/> NO	_____
Tire tread ok		<input checked="" type="radio"/> YES	<input type="radio"/> NO	_____
Hubs, lugs, and rims ok (need to be grea		<input checked="" type="radio"/> YES	<input type="radio"/> NO	_____
Doors and hinges operating properly		<input checked="" type="radio"/> YES	<input type="radio"/> NO	_____
Locks on doors (trailer secured)		<input checked="" type="radio"/> YES	<input type="radio"/> NO	_____
Condition of Trailer		Excellent	<input checked="" type="radio"/> Good	Fair Poor

Comments on above items _____

Inspector:
Print: Chase Hunt

Signature: [Signature]

Facility Rep
Print: _____

Signature: _____

Notify Facility 24 hrs prior to inspection

Person Notified: _____

Check if Verification only

Moran Environmental Recovery LLC Inspection Sheet

DATE: 10/28/22

LOCATION: MER YARD

JON BOATS AND MOTORS

BOATS

Unit 853	14' Boat	G3 1436	GEN6849JG900 ?	Circle:	Excelent	Good	Fair	Poor
G3 1438		GEN61758G708		Circle:	Excelent	Good	Fair	Poor
Express		JBC21426B595		Circle:	Excelent	Good	Fair	Poor
G3 1444		GEN 36264H506 ?		Circle:	Excelent	Good	Fair	Poor
Lowe L1436L		LWCJ2227F506		Circle:	Excelent	Good	Fair	Poor

MOTORS

Yamaha 9.9	559	Mod#F9.95MHA SN# GAUKS1024920	Circle:	Excelent	Good	Fair	Poor
			Last Run Date:	<u>10/28/22</u>			
			Comments:	_____			
Yamaha 9.9	558	Mod # F9.95MHA SN# GAUKS1028386	Circle:	Excelent	Good	Fair	Poor
			Last Run Date:	<u>10/28/22</u>			
			Comments:	_____			
Yamaha 9.9	560	Mod# F9.9MHB SN# GAUKS1030921	Circle:	Excelent	Good	Fair	Poor
			Last Run Date:	<u>10/28/22</u>			
			Comments:	_____			
Yamaha 15		Mod# F15SMHA SN# 6AGKS1063676	Circle:	Excelent	Good	Fair	Poor
			Last Run Date:	<u>10/28/22</u>			
			Comments:	_____			
Yamaha 15		Mod# F15SEHA SN# 6AGKS1062763	Circle:	Excelent	Good	Fair	Poor
			Last Run Date:	<u>10/28/22</u>			
			Comments:	_____			

Inspector: Chase Hurst
Print: _____

Signature: [Signature]

Check if Verification only