

Moran Environmental Recovery LLC Inspection Sheet

DATE: 11/17/22

LOCATION: MER

Trailer # 6186 Trailer Serial # 53FBE2421KF050875 Date Placed in Service: _____

		Circle one		Comments
4- 26lb Anchors with chain	Verified:	<input checked="" type="radio"/> YES	NO	_____
4- Buoys with 2 shackles each	Verified:	<input checked="" type="radio"/> YES	NO	_____
4- Long lines	Verified:	<input checked="" type="radio"/> YES	NO	_____
4- Short lines	Verified:	<input checked="" type="radio"/> YES	NO	_____
*** 1000' 18" containment boom (Verify Qua	Verified:	<input checked="" type="radio"/> YES	NO	_____
4 Bundles absorbent pads	Verified:	<input checked="" type="radio"/> YES	NO	_____
4- Bundles absorbent boom	Verified:	<input checked="" type="radio"/> YES	NO	_____
1- Roll trash bags	Verified:	<input checked="" type="radio"/> YES	NO	_____
2- Life jackets	Verified:	<input checked="" type="radio"/> YES	NO	_____
1- Pair pliers	Verified:	<input checked="" type="radio"/> YES	NO	_____
1- Skimmer 1800 SH	Verified:	<input checked="" type="radio"/> YES	NO	_____
1- First Aid Kit	Verified:	<input checked="" type="radio"/> YES	NO	_____
1-EyeWash	Verified:	<input checked="" type="radio"/> YES	NO	_____

*** See Boom Condition Report for updated Boom Condition

Comments on above inventory: _____

OUTSIDE OF TRAILER

		Circle		Comments
Tag in place and current	Tag#			_____
Washed/Clean		<input checked="" type="radio"/> YES	NO	_____
Lights operational		<input checked="" type="radio"/> YES	NO	_____
Trailer tongue greased		<input checked="" type="radio"/> YES	NO	_____
Trailer number visible		<input checked="" type="radio"/> YES	NO	_____
Trailer moved and brakes working		<input checked="" type="radio"/> YES	NO	_____
Tire pressure ok		<input checked="" type="radio"/> YES	NO	_____
Tire tread ok		<input checked="" type="radio"/> YES	NO	_____
Hubs, lugs, and rims ok (need to be grea		<input checked="" type="radio"/> YES	NO	_____
Doors and hinges operating properly		<input checked="" type="radio"/> YES	NO	_____
Locks on doors (trailer secured)		<input checked="" type="radio"/> YES	NO	_____

Condition of Trailer Excellent Good Fair Poor

Comments on above items _____

Inspector: W. Schmitt Signature: [Signature]

Facility Rep: _____ Signature: _____

Notify Facility 24 hrs prior to inspection

Person Notified: _____

Check if Verification only

Moran Environmental Recovery LLC Inspection Sheet

DATE: 11/17/22

LOCATION: MER

Trailer # 6190 Trailer Serial # 53FBE2427KF050878 Date Placed in Service:

		Circle one		Comments
4- 26lb Anchors with chain	Verified: <u>YES</u>	NO		_____
4- Buoys with 2 shackels each	Verified: <u>YES</u>	NO		_____
4- Long lines	Verified: <u>YES</u>	NO		_____
4- Short lines	Verified: <u>YES</u>	NO		_____
*** 1000' 18" containment boom (Verify Qua	Verified: <u>YES</u>	NO		_____
4 Bundles absorbent pads	Verified: <u>YES</u>	NO		_____
4- Bundles absorbent boom	Verified: <u>YES</u>	NO		_____
1- Roll trash bags	Verified: <u>YES</u>	NO		_____
2- Life jackets	Verified: <u>YES</u>	NO		_____
1- Pair pliers	Verified: <u>YES</u>	NO		_____
1- Skimmer 1800 SH	Verified: <u>YES</u>	NO		_____
1- First Aid Kit	Verified: <u>YES</u>	NO		_____
1-EyeWash	Verified: <u>YES</u>	NO		_____

*** See Boom Condition Report for updated Boom Conditiior

Comments on above Inventory: _____

OUTSIDE OF TRAILER

	Circle		Comments
Tag in place and current Tag#			_____
Washed/Clean	<u>YES</u>	NO	_____
Lights operational	<u>YES</u>	NO	_____
Trailer tounge greased	<u>YES</u>	NO	_____
Trailer number visible	<u>YES</u>	NO	_____
Trailer moved and brakes working	<u>YES</u>	NO	_____
Tire pressure ok	<u>YES</u>	NO	_____
Tire tread ok	<u>YES</u>	NO	_____
Hubs, lugs, and rims ok (need to be grea	<u>YES</u>	NO	_____
Doors and hinges operating properly	<u>YES</u>	NO	_____
Locks on doors (trailer secured)	<u>YES</u>	NO	_____

Condition of Trailer Excellent Good Fair Poor

Comments on above items _____

Inspector: RCV Signature: Chase Hurs
 Print: _____
 Facility Rep Signature: _____
 Print: _____

Notify Facility 24 hrs prior to inspection

Person Notified: _____

Check if Verification only

Moran Environmental Recovery LLC Inspection Sheet

Vessel Name: Al Allen

Vessel Make: Lobelle

Inspection Date: 11/28/22

Unit #: 862

Location: MER Yard

Last Months Recorded Hours _____
Current Months Recorded Hours _____

Check items (X)

Check items (X)

Visual Hull Inspection

Check fuel level (full)

Check Batteries

Check oil level

Inspect fuel lines

Spark Plug wires

Inspect Bilge

Boat Clean

Operate Bilge pump

Operate for 15 min

GPS /VHF Working

*** VESSEL SHOULD GO THROUGH A SEA TRIAL TO INSURE OPERATING AT PEAK PERFORMANCE A MIN OF ONCE PER QUARTER

LP: TL7PX02

Trailer #: 6094

Inspector:
Print: Troy Cunningham

Signature: [Signature]

Facility Rep
Print: _____

Signature: _____

Notify Facility 24 hrs prior to inspection

Person Notified: _____

Check if Verification only

Moran Environmental Recovery LLC Inspection Sheet

DATE: 11/28/22

LOCATION: MER

Trailer # 6189

Trailer Serial #53FBE2426KF050872 Date Placed in Service:

		Circle one		Comments
4- 26lb Anchors with chain	Verified:	<input checked="" type="radio"/> YES	NO	_____
4- Buoys with 2 shackles each	Verified:	<input checked="" type="radio"/> YES	NO	_____
4- Long lines	Verified:	<input checked="" type="radio"/> YES	NO	_____
4- Short lines	Verified:	<input checked="" type="radio"/> YES	NO	_____
*** 1000' 18" containment boom (Verify Qua	Verified:	<input checked="" type="radio"/> YES	NO	_____
4 Bundles absorbent pads	Verified:	<input checked="" type="radio"/> YES	NO	_____
4- Bundles absorbent boom	Verified:	<input checked="" type="radio"/> YES	NO	_____
1- Roll trash bags	Verified:	<input checked="" type="radio"/> YES	NO	_____
2- Life jackets	Verified:	<input checked="" type="radio"/> YES	NO	_____
1- Pair pliers	Verified:	<input checked="" type="radio"/> YES	NO	_____
1- Skimmer 1800 SH	Verified:	<input checked="" type="radio"/> YES	NO	_____
1- First Aid Kit	Verified:	<input checked="" type="radio"/> YES	NO	_____
1-EyeWash	Verified:	<input checked="" type="radio"/> YES	NO	_____

*** See Boom Condition Report for updated Boom Condition

Comments on above Inventory: _____

OUTSIDE OF TRAILER

	Tag#	Circle		Comments
Tag in place and current			<u>TT35473</u>	_____
Washed/Clean		<input checked="" type="radio"/> YES	NO	_____
Lights operational		YES	<input checked="" type="radio"/> NO	_____
Trailer tounge greased		<input checked="" type="radio"/> YES	NO	_____
Trailer number visible		<input checked="" type="radio"/> YES	NO	_____
Trailer moved and brakes working		<input checked="" type="radio"/> YES	NO	_____
Tire pressure ok		<input checked="" type="radio"/> YES	NO	_____
Tire tread ok		<input checked="" type="radio"/> YES	NO	_____
Hubs, lugs, and rims ok (need to be grea		<input checked="" type="radio"/> YES	NO	_____
Doors and hinges operating properly		<input checked="" type="radio"/> YES	NO	_____
Locks on doors (trailer secured)		<input checked="" type="radio"/> YES	NO	_____
Condition of Trailer			Excellent <u>Good</u> Fair Poor	_____

Comments on above items _____

Inspector: Chaschurst
 Print: _____

Signature: [Signature]

Facility Rep
 Print: _____

Signature: _____

Notify Facility 24 hrs prior to inspection

Person Notified: _____

Check if Verification only

Moran Environmental Recovery LLC Inspection Sheet

Vessel Name: Savannah Patriot

Vessel Make: Custom

Inspection Date: 11/14/22

Unit #: 365

Location: Savannah, GA

Last Months Recorded Hours
Current Months Recorded Hours

976

Check items (X)

Check items (X)

Visual Hull Inspection

Check fuel level (full)

Check Batteries

Check oil level

Inspect fuel lines

Spark Plug wires

Inspect Bilge

Boat Clean

Operate Bilge pump

Operate for 15 min

No Electronics

*** VESSEL SHOULD GO THROUGH A SEA TRIAL TO INSURE OPERATING AT PEAK PERFORMANCE A MIN OF ONCE PER QUARTER

Trailer #: 6113

Inspector:
Print: Chase Hurst

Signature: [Signature]

Facility Rep
Print: _____

Signature: _____

Notify Facility 24 hrs prior to inspection

Person Notified: _____

Check if Verification only

Moran Environmental Recovery LLC Inspection Sheet

DATE: 11/28/22

LOCATION: MER

Trailer # 6187

Trailer Serial #

Date Placed in Service:

Circle one

Comments

4- 26lb Anchors with chain	Verified:	YES	NO	_____
4- Buoys with 2 shackels each	Verified:	YES	NO	_____
4- Long lines	Verified:	YES	NO	_____
4- Short lines	Verified:	YES	NO	_____
*** 1000' 18" containment boom (Verify Qua	Verified:	YES	NO	_____
4 Bundles absorbent pads	Verified:	YES	NO	_____
4- Bundles absorbent boom	Verified:	YES	NO	_____
1- Roll trash bags	Verified:	YES	NO	_____
2- Life jackets	Verified:	YES	NO	_____
1- Pair pliers	Verified:	YES	NO	_____
1- Skimmer 1800 SH	Verified:	YES	NO	_____
1- First Aid Kit	Verified:	YES	NO	_____
1-EyeWash	Verified:	YES	NO	_____

*** See Boom Condition Report for updated Boom Condition

Comments on above Inventory: Empty

OUTSIDE OF TRAILER

Circle

Comments

Tag in place and current	Tag#	<u>TTASm6s</u>	_____
Washed/Clean		<u>YES</u> NO	_____
Lights operational		<u>YES</u> NO	_____
Trailer tounge greased		<u>YES</u> NO	_____
Trailer number visible		<u>YES</u> NO	_____
Trailer moved and brakes working		<u>YES</u> NO	_____
Tire pressure ok		<u>YES</u> NO	_____
Tire tread ok		<u>YES</u> NO	_____
Hubs, lugs, and rims ok (need to be grea		<u>YES</u> NO	_____
Doors and hinges operating properly		<u>YES</u> NO	_____
Locks on doors (trailer secured)		YES <u>NO</u>	_____

Condition of Trailer

Excellent Good Fair Poor

Comments on above items _____

Inspector: Chase Huest
Print: _____

Signature: [Signature]

Facility Rep
Print: _____

Signature: _____

Notify Facility 24 hrs prior to inspection

Person Notified: _____

Check if Verification only

Moran Environmental Recovery LLC Inspection Sheet

DATE: 11/28/22

LOCATION: MER

Trailer # 6188

Trailer Serial #

Date Placed in Service:

Circle one

Comments

4- 26lb Anchors with chain	Verified:	YES	NO	_____
4- Buoys with 2 shackles each	Verified:	YES	NO	_____
4- Long lines	Verified:	YES	NO	_____
4- Short lines	Verified:	YES	NO	_____
*** 1000' 18" containment boom (Verify Qua	Verified:	YES	NO	_____
4 Bundles absorbent pads	Verified:	YES	NO	_____
4- Bundles absorbent boom	Verified:	YES	NO	_____
1- Roll trash bags	Verified:	YES	NO	_____
2- Life jackets	Verified:	YES	NO	_____
1- Pair pliers	Verified:	YES	NO	_____
1- Skimmer 1800 SH	Verified:	YES	NO	_____
1- First Aid Kit	Verified:	YES	NO	_____
1-EyeWash	Verified:	YES	NO	_____

*** See Boom Condition Report for updated Boom Conditiior

Comments on above Inventory: _____

OUTSIDE OF TRAILER

Circle

Comments

Tag in place and current	Tag#	<u>TT35W24</u>		<u>July 23</u>
Washed/Clean		<u>YES</u>	NO	_____
Lights operational		<u>YES</u>	NO	_____
Trailer tounge greased		<u>YES</u>	NO	_____
Trailer number visible		<u>YES</u>	NO	_____
Trailer moved and brakes working		<u>YES</u>	NO	_____
Tire pressure ok		<u>YES</u>	NO	_____
Tire tread ok		<u>YES</u>	NO	_____
Hubs, lugs, and rims ok (need to be grea		<u>YES</u>	NO	_____
Doors and hinges operating properly		<u>YES</u>	NO	_____
Locks on doors (trailer secured)		YES	<u>NO</u>	_____
Condition of Trailer		Excellent	<u>Good</u>	Fair Poor

Comments on above items _____

Inspector: Chase Huest
 Print: _____

Signature: [Signature]

Facility Rep
 Print: _____

Signature: _____

Notify Facility 24 hrs prior to inspection

Person Notified: _____



Check if Verification only

Moran Environmental Recovery LLC Inspection Sheet

Vessel Name: 34' Barge Boat

Vessel Make: Custom

Inspection Date: 11/14/22

Unit #: _____

Location: MER Savannah

Last Months Recorded Hours
Current Months Recorded Hours

14.7

Check items (X)

Check items (X)

Visual Hull Inspection

Check fuel level (full)

Check Batteries

Check oil level

Inspect fuel lines

Spark Plug wires

Inspect Bilge

Boat Clean

Operate Bilge pump

Operate for 15 min

No Electronics


*** VESSEL SHOULD GO THROUGH A SEA TRIAL TO INSURE OPERATING AT PEAK PERFORMANCE A MIN OF ONCE PER QUARTER

Trailer #: 6009 / XKG964

Inspector:

Print: Troy Cunningham

Signature: _____



Facility Rep:

Print: _____

Signature: _____

Notify Facility 24 hrs prior to inspection

Person Notified: _____

Check if Verification only

Moran Environmental Recovery LLC Inspection Sheet

Vessel Name: SCOUT
17' Work Boat

Vessel Make: Custom

Inspection Date: 11/14/22

Unit #: 266

Location: MER Savannah

Last Months Recorded Hours
Current Months Recorded Hours

152

Check items (X)

Check items (X)

Visual Hull Inspection

Check fuel level (full)

Check Batteries

Check oil level

Inspect fuel lines

Spark Plug wires

Inspect Bilge

Boat Clean

Operate Bilge pump

Operate for 15 min

No Electronics

*** VESSEL SHOULD GO THROUGH A SEA TRIAL TO INSURE OPERATING AT PEAK PERFORMANCE A MIN OF ONCE PER QUARTER

Trailer #: 6135 // T5916Q

Inspector:
Print: Tracy Cunningham

Signature: [Signature]

Facility Rep
Print: _____

Signature: _____

Notify Facility 24 hrs prior to inspection

Person Notified: _____

Check if Verification only

Moran Environmental Recovery LLC Inspection Sheet

Vessel Name: Porpoise

Vessel Make: Custom

Inspection Date: 11/14/22

Unit #: 835

Location: Phillips 66

Last Months Recorded Hours _____
Current Months Recorded Hours _____

Check items (X)

Check items (X)

<input type="checkbox"/>	Visual Hull Inspection	<input type="checkbox"/>	Check fuel level (full)
<input type="checkbox"/>	Check Batteries	<input type="checkbox"/>	Check oil level
<input type="checkbox"/>	Inspect fuel lines	<input type="checkbox"/>	Spark Plug wires
<input type="checkbox"/>	Inspect Bilge	<input type="checkbox"/>	Boat Clean
<input type="checkbox"/>	Operate Bilge pump	<input type="checkbox"/>	Operate for 15 min
<input type="checkbox"/>	No Electronics		

*** VESSEL SHOULD GO THROUGH A SEA TRIAL TO INSURE OPERATING AT PEAK PERFORMANCE A MIN OF ONCE PER QUARTER

Trailer #: 6042

Inspector:
Print: _____

Signature: _____

Facility Rep
Print: _____

Signature: _____

Notify Facility 24 hrs prior to inspection

Person Notified: _____

Check if Verification only

Moran Environmental Recovery LLC Inspection Sheet

DATE: 11/11/22

LOCATION: MER Yard

INSIDE CONTAINER

		Circle one	Comments
6- 26lb Anchors with chain	Verified: YES	<input checked="" type="radio"/> NO	_____
4- Buoys with 2 shackels each	Verified: YES	<input checked="" type="radio"/> NO	_____
2 spools of line	Verified: YES	<input checked="" type="radio"/> NO	_____
2000' 18" containment boom (verification of)	Verified: YES	<input checked="" type="radio"/> NO	_____
4 Bundles absorbent pads	Verified: YES	<input checked="" type="radio"/> NO	_____
4- Bundles absorbent boom	Verified: YES	<input checked="" type="radio"/> NO	_____
1- Roll trash bags	Verified: YES	<input checked="" type="radio"/> NO	_____
1- Pair pliers	Verified: YES	<input checked="" type="radio"/> NO	_____
1- First Aid Kit	Verified: YES	<input checked="" type="radio"/> NO	_____
1-Eye Wash	Verified: YES	<input checked="" type="radio"/> NO	_____

OUTSIDE CONTAINER

Box number 10

Container accessible Verified: YES NO _____

Seal in place Verified: YES NO _____

Seal number _____

Container Temp Hi _____ Lo _____ Date: _____

Inspector:
Print: Chase Huet

Signature: [Handwritten Signature]

Facility Rep
Print: _____

Signature: _____

Notify Facility 24 hrs prior to inspection

Person Notified: _____



Check if Verification only

Moran Environmental Recovery LLC Inspection Sheet

DATE: 11/11/22

LOCATION MER Yard

INSIDE CONTAINER

		Circle one	Comments
6- 26lb Anchors with chain	Verified: YES	<input checked="" type="radio"/> NO	_____
4- Buoys with 2 shackles each	Verified: YES	<input checked="" type="radio"/> NO	_____
2 spools of line	Verified: YES	<input checked="" type="radio"/> NO	_____
2000' 18" containment boom (verification of)	Verified: YES	<input checked="" type="radio"/> NO	_____
4 Bundles absorbent pads	Verified: YES	<input checked="" type="radio"/> NO	_____
4- Bundles absorbent boom	Verified: YES	<input checked="" type="radio"/> NO	_____
1- Roll trash bags	Verified: YES	<input checked="" type="radio"/> NO	_____
1- Pair pliers	Verified: YES	<input checked="" type="radio"/> NO	_____
1- First Aid Kit	Verified: YES	<input checked="" type="radio"/> NO	_____
1-Eye Wash	Verified: YES	<input checked="" type="radio"/> NO	_____

OUTSIDE CONTAINER

Box number 9

Container accessable Verified: YES NO _____

Seal in place Verified: YES NO _____

Seal number _____

Container Temp Hi _____ Lo _____ Date: _____

Inspector: Chase Hurst
Print: _____

Signature: [Signature]

Facility Rep
Print: _____

Signature: _____

Notify Facility 24 hrs prior to inspection

Person Notified: _____

Check if Verification only

Moran Environmental Recovery LLC Inspection Sheet

DATE: 11/11/22

LOCATION: MER Yard

INSIDE CONTAINER

		Circle one	Comments
6- 26lb Anchors with chain	Verified: YES	<input checked="" type="radio"/> NO	_____
4- Buoys with 2 shackles each	Verified: YES	<input checked="" type="radio"/> NO	_____
2 spools of line	Verified: YES	<input checked="" type="radio"/> NO	_____
2000' 18" containment boom (verification of)	Verified: YES	<input checked="" type="radio"/> NO	_____
4 Bundles absorbent pads	Verified: YES	<input checked="" type="radio"/> NO	_____
4- Bundles absorbent boom	Verified: YES	<input checked="" type="radio"/> NO	_____
1- Roll trash bags	Verified: YES	<input checked="" type="radio"/> NO	_____
1- Pair pliers	Verified: YES	<input checked="" type="radio"/> NO	_____
1- First Aid Kit	Verified: YES	<input checked="" type="radio"/> NO	_____
1-Eye Wash	Verified: YES	<input checked="" type="radio"/> NO	_____

OUTSIDE CONTAINER

Box number 7

Container accessible Verified: YES NO _____

Seal in place Verified: YES NO _____

Seal number _____

Container Temp Hi _____ Lo _____ Date: _____

Inspector:
Print: Chase Hurst

Signature: [Handwritten Signature]

Facility Rep
Print: _____

Signature: _____

Notify Facility 24 hrs prior to inspection

Person Notified: _____

Check if Verification only

Moran Environmental Recovery LLC Inspection Sheet

DATE: 11/11/22

LOCATION: MER YARD

TOWABLE BLADDER

		Circle one	Comments
BLADDER #1 Abasco Towable 1000gal	Verified:	<input checked="" type="radio"/> YES NO	_____
Stored in place at MER Yard	Verified:	YES <input checked="" type="radio"/> NO	_____
Deployed and tested			_____
 BLADDER #2 Abaso Towable 1000gal	Verified:	<input checked="" type="radio"/> YES NO	_____
Stored in place at MER Yard	Verified:	YES <input checked="" type="radio"/> NO	_____
Deployed and tested			_____
 BLADDER #3 Abaso Towable 1000gal		<input checked="" type="radio"/> YES NO	_____
Stored in place at MER Yard		YES <input checked="" type="radio"/> NO	_____
Deployed and tested			_____
_____			_____
_____			_____

Inspector:
Print: Chase Hurst

Signature: [Handwritten Signature]

Facility Rep
Print: _____

Signature: _____

Notify Facility 24 hrs prior to inspection

Person Notified: _____



Check if Verification only

Moran Environmental Recovery LLC Inspection Sheet

DATE: 11/11/22

LOCATION: MER YARD
SKIMMER TRAILER

Trailer #: 6080

Tag#: _____
Removed: **YES NO**

SK-1 SKIMMERS

Elastic Drum Skimmer Hydraulic TDSH13699178
 - Condition Circle: Excellent Good Poor Fair
 - Last Run Test Date: 11/11/22
 Comment: _____

SK-2

Action Petroleum Drum Skimmer Air driven Mod 18A Serial # 314
 - Condition Circle: Excellent Good Poor Fair
 - Last Run Test Date: 11/11/22
 Comment: _____

SK-3

Crucial Coated Drum Skimmer Mod#1CD18H36 Ser#214468
 -Condition Circle: Excellent Good Poor Fair
 -Last Run Test Date: 11/11/22
 Comment: _____

PM-1 PUMPS

3in Hydraulic Submersible Pump Serial # 11197
 - Condition Circle: Excellent Good Poor Fair
 - Last Run Test Date: 11/11/22
 Comment: _____

PM-2

4in Vickers Hydraulic Submersible Pump Serial # 25M65A1C20
 - Condition Circle: Excellent Good Poor Fair
 - Last Run Test Date: 11/11/22
 Comment: _____

PM-3

6in Hydrotech Hydraulic Submersible Pump Serial # 6F878
 - Condition Circle: Excellent Good Poor Fair
 - Last Run Test Date: 11/11/22
 Comment: _____

PM-4

3" Crucial Diesel SD Pump Mod#DDP-3 Ser#214468
 -Condition Circle: Excellent Good Poor Fair
 -Last Run Test Date: 11/11/22
 Comment: _____

PP-1 POWER PACKS

Elastic Power Pack Serial # H1198258
 - Condition Circle: Excellent Good Poor Fair
 - Last Run Test Date: 11/11/22
 Comment: _____

PP-2

739 Hydrotech Power Pack Mod # HT60DCV Serial # F
 - Condition Circle: Excellent Good Poor Fair
 - Last Run Test Date: 11/11/22
 Comment: _____

PP-3

Crucial Diesel Compressor **Mod#L70190126P17E Ser#214468**
 -Condition Circle: Excellent Good Poor Fair
 -Last Run Test Date: 11/11/22
 Comment: _____

Inspector: Chase Hurst
 Print: _____

Signature: [Signature]

Inspector: _____
 Print: _____

Signature: _____

Moran Environmental Recovery LLC Inspection Sheet

DATE: 11/7/21

Location: Ocean Terminal

Unit #: BR 1

BOOM REELS

	Circle		Comments
Grease Chain	<input checked="" type="radio"/> YES	NO	_____
Grease Fittings	<input checked="" type="radio"/> YES	NO	_____
Inspect sprocket	<input checked="" type="radio"/> YES	NO	_____
Check Oil level in motor	<input checked="" type="radio"/> YES	NO	_____
Reel clear of debris and grass	<input checked="" type="radio"/> YES	NO	_____
Run motor	<input checked="" type="radio"/> YES	NO	_____
Hand Brake operational	<input checked="" type="radio"/> YES	NO	_____
Boom Reel cover secure	YES	<input checked="" type="radio"/> NO	_____
*** 1000ft of 18" containment boom (Verify Quantit	YES	<input checked="" type="radio"/> NO	_____
Condition of Boom Reel Cover			Excellent Good Fair <input checked="" type="radio"/> Poor
Condition of Boom Reel			Excellent <input checked="" type="radio"/> Good Fair Poor

*** See Boom condition Report for updated Boom Condition

Inspector: _____
 Print: Chloe Hunt Signature: [Signature]

Facility Rep _____
 Print: _____ Signature: _____

Notify Facility 24 hrs prior to inspection



Check if Verification only

Person Notified: _____

Moran Environmental Recovery LLC Inspection Sheet

DATE: 11/28/22

LOCATION: MER YARD

JON BOATS AND MOTORS

BOATS

Unit 853	14' Boat	G3 1436	GEN6849JG900	Circle: Excelent	<u>Good</u>	Fair	Poor
G3 1438		GEN61758G708		Circle: Excelent	<u>Good</u>	Fair	Poor
Express		JBC21426B595		Circle: Excelent	<u>Good</u>	Fair	Poor
G3 1444		GEN 36264H506		Circle: Excelent	<u>Good</u>	Fair	Poor
Lowe L1436L		LWCJ2227F506		Circle: Excelent	<u>Good</u>	Fair	Poor

MOTORS

Yamaha 9.9	559	Mod#F9.95MHA SN# GAUKS1024920	Circle: Excelent	<u>Good</u>	Fair	Poor
			Last Run Date: <u>11/28/22</u>	Comments: _____		
Yamaha 9.9	558	Mod # F9.95MHA SN# GAUKS1028386	Circle: Excelent	<u>Good</u>	Fair	Poor
			Last Run Date: <u>11/28/22</u>	Comments: _____		
Yamaha 9.9	560	Mod# F9.9MHB SN# GAUKS1030921	Circle: Excelent	<u>Good</u>	Fair	Poor
			Last Run Date: <u>11/28/22</u>	Comments: _____		
Yamaha 15		Mod# F15SMHA SN# 6AGKS1063676	Circle: Excelent	<u>Good</u>	Fair	Poor
			Last Run Date: <u>11/28/22</u>	Comments: _____		
Yamaha 15		Mod# F15SEHA SN# 6AGKS1062763	Circle: Excelent	<u>Good</u>	Fair	Poor
			Last Run Date: <u>11/28/22</u>	Comments: _____		

Inspector: Chase Hwst
Print: _____

Signature: REU FTU

Check if Verification only

Moran Environmental Recovery LLC Inspection Sheet

DATE: 11/16/22

LOCATION Elba Island

INSIDE CONTAINER

		Circle one	Comments
6- 26lb Anchors with chain	Verified: YES	<input checked="" type="radio"/> NO	<u>only 3</u>
4- Buoys with 2 shackles each	Verified: YES	<input checked="" type="radio"/> NO	
2 spools of line	Verified: <input checked="" type="radio"/> YES	NO	
2000' 18" containment boom (verification of)	Verified: <input checked="" type="radio"/> YES	NO	
4 Bundles absorbent pads	Verified: YES	<input checked="" type="radio"/> NO	<u>need 4</u>
4- Bundles absorbent boom	Verified: YES	<input checked="" type="radio"/> NO	<u>need 4</u>
1- Roll trash bags	Verified: <input checked="" type="radio"/> YES	NO	
1- Pair pliers	Verified: <input checked="" type="radio"/> YES	NO	
1- First Aid Kit	Verified: <input checked="" type="radio"/> YES	NO	
1-Eye Wash	Verified: <input checked="" type="radio"/> YES	NO	

OUTSIDE CONTAINER

Box number 2

Container accessible Verified: YES NO

Seal in place Verified: YES NO

Seal number _____

Container Temp Hi _____ Lo _____ Date: _____

Inspector:
Print: Chase Hunt

Signature: [Handwritten Signature]

Facility Rep
Print: _____

Signature: _____

Notify Facility 24 hrs prior to inspection

Person Notified: _____

Check if Verification only

Moran Environmental Recovery LLC Inspection Sheet

DATE: 11/16/22

LOCATION: Elba Island

INSIDE CONTAINER

		Circle one	
6- 26lb Anchors with chain	Verified:	<input checked="" type="radio"/> YES NO	_____
4- Buoys with 2 shackles each	Verified:	<input checked="" type="radio"/> YES NO	_____
2 spools of line	Verified:	<input checked="" type="radio"/> YES NO	_____
2000' 18" containment boom (verification of)	Verified:	<input checked="" type="radio"/> YES NO	_____
4 Bundles absorbent pads	Verified:	YES <input checked="" type="radio"/> NO	_____
4- Bundles absorbent boom	Verified:	<input checked="" type="radio"/> YES NO	_____
1- Roll trash bags	Verified:	<input checked="" type="radio"/> YES NO	_____
1- Pair pliers	Verified:	<input checked="" type="radio"/> YES NO	_____
1- First Aid Kit	Verified:	<input checked="" type="radio"/> YES NO	_____
1-Eye Wash	Verified:	<input checked="" type="radio"/> YES NO	_____

OUTSIDE CONTAINER

Box number 1

Container accessible Verified: YES NO _____

Seal in place Verified: YES NO _____

Seal number _____

Container Temp Hi _____ Lo _____ Date: _____

Inspector: Chase Hines

Signature: [Signature]

Facility Rep
Print: _____

Signature: _____

Notify Facility 24 hrs prior to inspection

Person Notified: _____

Check if Verification only

Moran Environmental Recovery LLC Inspection Sheet

DATE: 11/7/22

LOCATION: Plant McIntosh

INSIDE CONTAINER

		Circle one	Comments
6- 26lb Anchors with chain	Verified: YES	<input checked="" type="radio"/> NO	_____
4- Buoys with 2 shackles each	Verified: YES	<input checked="" type="radio"/> NO	_____
2 spools of line	Verified: YES	<input checked="" type="radio"/> NO	_____
2000' 18" containment boom (verification of)	Verified: YES	<input checked="" type="radio"/> NO	_____
4 Bundles absorbent pads	Verified: YES	<input checked="" type="radio"/> NO	_____
4- Bundles absorbent boom	Verified: YES	<input checked="" type="radio"/> NO	_____
1- Roll trash bags	Verified: YES	<input checked="" type="radio"/> NO	_____
1- Pair pliers	Verified: YES	<input checked="" type="radio"/> NO	_____
1- First Aid Kit	Verified: YES	<input checked="" type="radio"/> NO	_____
1-Eye Wash	Verified: YES	<input checked="" type="radio"/> NO	_____

OUTSIDE CONTAINER

Box number 8

Container accessible Verified: YES NO _____

Seal in place Verified: YES NO 1688005 / 1631028

Seal number _____

Container Temp Hi _____ Lo _____ Date: _____

Inspector: Chris Hunt
Print: _____

Signature: [Signature]

Facility Rep: Owen Bryant
Print: _____

Signature: [Signature]

Notify Facility 24 hrs prior to inspection

Person Notified: _____

Check if Verification only

Moran Environmental Recovery LLC Inspection Sheet

DATE: 11/7/22

Location: Phillips 66

Unit #: BR 4

BOOM REELS

	Circle		Comments
Grease Chain	<u>YES</u>	NO	_____
Grease Fittings	<u>YES</u>	NO	_____
Inspect sprocket	<u>YES</u>	NO	_____
Check Oil level in motor	<u>YES</u>	NO	_____
Reel clear of debris and grass	<u>YES</u>	NO	_____
Run motor	<u>YES</u>	NO	_____
Hand Brake operational	<u>YES</u>	NO	_____
Boom Reel cover secure	YES	<u>NO</u>	_____
*** 1000ft of 18" containment boom (Verify Quantii	YES	<u>NO</u>	_____
Condition of Boom Reel Cover			Excellent Good Fair <u>Poor</u>
Condition of Boom Reel			Excellent <u>Good</u> Fair Poor

*** See Boom condition Report for updated Boom Condition

Inspector: Chase Huest Signature: [Signature]

Facility Rep: Sandra Gomez Signature: [Signature]

Notify Facility 24 hrs prior to inspection

Person Notified: _____



Check if Verification only

Moran Environmental Recovery LLC Inspection Sheet

Vessel Name: Al Allen

Vessel Make: Lobelle

Inspection Date: 11/7/22

Unit #: 862

Location: MER Yard

Last Months Recorded Hours _____
Current Months Recorded Hours 197.6

Check items (X)

Check items (X)

Visual Hull Inspection

Check fuel level (full)

Check Batteries

Check oil level

Inspect fuel lines

Spark Plug wires

Inspect Bilge

Boat Clean

Operate Bilge pump

Operate for 15 min

GPS /VHF Working

*** VESSEL SHOULD GO THROUGH A SEA TRIAL TO INSURE OPERATING AT PEAK PERFORMANCE A MIN OF ONCE PER QUARTER

Trailer #: 6094

Inspector: [Signature]
Print: _____

Signature: [Signature]

Facility Rep: Sandra Gomez
Print: _____

Signature: [Signature]

Notify Facility 24 hrs prior to inspection

Person Notified: _____

Check if Verification only

Moran Environmental Recovery LLC Inspection Sheet

Vessel Name: Munson

Vessel Make: Custom

Inspection Date: 11/7/22

Unit #: 471

Location: JMPTT North

Last Months Recorded Hours
Current Months Recorded Hours

31.9

Check items (X)

Check items (X)

Visual Hull Inspection

Check fuel level (full)

Check Batteries

Check oil level

Inspect fuel lines

Spark Plug wires

Inspect Bilge

Boat Clean

Operate Bilge pump

Operate for 15 min

No Electronics

*** VESSEL SHOULD GO THROUGH A SEA TRIAL TO INSURE OPERATING AT PEAK PERFORMANCE A MIN OF ONCE PER QUARTER

Trailer #: 6651

Inspector:
Print: Chase Hurst

Signature: [Signature]

Facility Rep
Print: Ray BABOT

Signature: [Signature]

Notify Facility 24 hrs prior to inspection

Person Notified: _____

Check if Verification only

Moran Environmental Recovery LLC Inspection Sheet

DATE: 11/7/22

LOCATION: IMTT North

INSIDE CONTAINER

		Circle one	Comments
6- 26lb Anchors with chain	Verified: YES	<input checked="" type="radio"/> NO	_____
4- Buoys with 2 shackels each	Verified: YES	<input checked="" type="radio"/> NO	_____
2 spools of line	Verified: YES	<input checked="" type="radio"/> NO	_____
2000' 18" containment boom (verification of)	Verified: YES	<input checked="" type="radio"/> NO	_____
4 Bundles absorbent pads	Verified: YES	<input checked="" type="radio"/> NO	_____
4- Bundles absorbent boom	Verified: YES	<input checked="" type="radio"/> NO	_____
1- Roll trash bags	Verified: YES	<input checked="" type="radio"/> NO	_____
1- Pair pliers	Verified: YES	<input checked="" type="radio"/> NO	_____
1- First Aid Kit	Verified: YES	<input checked="" type="radio"/> NO	_____
1-Eye Wash	Verified: YES	<input checked="" type="radio"/> NO	_____

OUTSIDE CONTAINER

Box number 4

Container accessible Verified: YES NO _____

Seal in place Verified: YES NO 1633121 / 1633122

Seal number _____

Container Temp Hi _____ Lo _____ Date: _____

Inspector:
Print: Chase Hest

Signature: [Signature]

Facility Rep
Print: Roy BABOT

Signature: [Signature]

Notify Facility 24 hrs prior to inspection

Person Notified: _____



Check if Verification only

Moran Environmental Recovery LLC Inspection Sheet

DATE: 11/7/22

LOCATION: Metro Ports

INSIDE CONTAINER

		Circle one	Comments
6- 26lb Anchors with chain	Verified: YES	<input checked="" type="radio"/> NO	_____
4- Buoys with 2 shackles each	Verified: YES	<input checked="" type="radio"/> NO	_____
2 spools of line	Verified: YES	<input checked="" type="radio"/> NO	_____
2000' 18" containment boom (verification of)	Verified: YES	<input checked="" type="radio"/> NO	_____
4 Bundles absorbent pads	Verified: YES	<input checked="" type="radio"/> NO	_____
4- Bundles absorbent boom	Verified: YES	<input checked="" type="radio"/> NO	_____
1- Roll trash bags	Verified: YES	<input checked="" type="radio"/> NO	_____
1- Pair pliers	Verified: YES	<input checked="" type="radio"/> NO	_____
1- First Aid Kit	Verified: YES	<input checked="" type="radio"/> NO	_____
1-Eye Wash	Verified: YES	<input checked="" type="radio"/> NO	_____

OUTSIDE CONTAINER

Box number 5

Container accessable Verified: YES NO _____

Seal in place Verified: YES NO 1633128/1633123

Seal number _____

Container Temp Hi _____ Lo _____ Date: _____

Inspector:
Print: Chase Hunt

Signature: [Signature]

Facility Rep:
Print: Tom John

Signature: [Signature]

Notify Facility 24 hrs prior to inspection

Person Notified: _____

Check if Verification only

Moran Environmental Recovery LLC Inspection Sheet

DATE: 11/7/22

LOCATION: Metro Ports

INSIDE CONTAINER

		Circle one	Comments
6- 26lb Anchors with chain	Verified: YES	<input checked="" type="radio"/> NO	_____
4- Buoys with 2 shackles each	Verified: YES	<input checked="" type="radio"/> NO	_____
2 spools of line	Verified: YES	<input checked="" type="radio"/> NO	_____
2000' 18" containment boom (verification of)	Verified: YES	<input checked="" type="radio"/> NO	_____
4 Bundles absorbent pads	Verified: YES	<input checked="" type="radio"/> NO	_____
4- Bundles absorbent boom	Verified: YES	<input checked="" type="radio"/> NO	_____
1- Roll trash bags	Verified: YES	<input checked="" type="radio"/> NO	_____
1- Pair pliers	Verified: YES	<input checked="" type="radio"/> NO	_____
1- First Aid Kit	Verified: YES	<input checked="" type="radio"/> NO	_____
1-Eye Wash	Verified: YES	<input checked="" type="radio"/> NO	_____

OUTSIDE CONTAINER

Box number 6

Container accessible Verified: YES NO _____

Seal in place Verified: YES NO 1683094/1633062

Seal number _____

Container Temp Hi _____ Lo _____ Date: _____

Inspector: Chase Hurst
Print: _____

Signature: [Signature]

Facility Rep: Tom Adair
Print: _____

Signature: [Signature]

Notify Facility 24 hrs prior to inspection

Person Notified: _____



Check if Verification only

Moran Environmental Recovery LLC Inspection Sheet

DATE: 11/7/22

LOCATION: Colonial Terminal

INSIDE CONTAINER

		Circle one	Comments
6- 26lb Anchors with chain	Verified: YES	<input checked="" type="radio"/> NO	_____
4- Buoys with 2 shackles each	Verified: YES	<input checked="" type="radio"/> NO	_____
2 spools of line	Verified: YES	<input checked="" type="radio"/> NO	_____
2000' 18" containment boom (verification of)	Verified: YES	<input checked="" type="radio"/> NO	_____
4 Bundles absorbent pads	Verified: YES	<input checked="" type="radio"/> NO	_____
4- Bundles absorbent boom	Verified: YES	<input checked="" type="radio"/> NO	_____
1- Roll trash bags	Verified: YES	<input checked="" type="radio"/> NO	_____
1- Pair pliers	Verified: YES	<input checked="" type="radio"/> NO	_____
1- First Aid Kit	Verified: YES	<input checked="" type="radio"/> NO	_____
1-Eye Wash	Verified: YES	<input checked="" type="radio"/> NO	_____

OUTSIDE CONTAINER

Box number 3

Container accessible Verified: YES NO _____

Seal in place Verified: YES NO 0485693/0485987

Seal number _____

Container Temp Hi _____ Lo _____ Date: _____

Inspector: Chris Huest
Print: _____

Signature: [Signature]

Facility Rep: Tom Dida
Print: _____

Signature: [Signature]

Notify Facility 24 hrs prior to inspection

Person Notified: _____

Check if Verification only

Moran Environmental Recovery LLC Inspection Sheet

DATE: 11/7/22

LOCATION: VOPAK

Trailer # 6017 Trailer Serial # 4X4TSEZ253U202767 Date Placed in Service: 2003

		Circle one	Comments
4- 26lb Anchors with chain	Verified: YES	<input checked="" type="radio"/> NO	_____
4- Buoys with 2 shackles each	Verified: YES	<input checked="" type="radio"/> NO	_____
4- Long lines	Verified: YES	<input checked="" type="radio"/> NO	_____
4- Short lines	Verified: YES	<input checked="" type="radio"/> NO	_____
*** 1000' 18" containment boom (Verify Qua	Verified: YES	<input checked="" type="radio"/> NO	_____
4 Bundles absorbent pads	Verified: YES	<input checked="" type="radio"/> NO	_____
4- Bundles absorbent boom	Verified: YES	<input checked="" type="radio"/> NO	_____
1- Roll trash bags	Verified: YES	<input checked="" type="radio"/> NO	_____
2- Life jackets	Verified: YES	<input checked="" type="radio"/> NO	_____
1- Pair pliers	Verified: YES	<input checked="" type="radio"/> NO	_____
1- Skimmer 1800 SH	Verified: YES	<input checked="" type="radio"/> NO	_____
1- First Aid Kit	Verified: YES	<input checked="" type="radio"/> NO	_____
1-EyeWash	Verified: YES	<input checked="" type="radio"/> NO	_____

*** See Boom Condition Report for updated Boom Condition

Comments on above Inventory: _____

OUTSIDE OF TRAILER

	Tag#	Circle		Comments
Tag in place and current				_____
Washed/Clean		<input checked="" type="radio"/> YES	NO	_____
Lights operational		<input checked="" type="radio"/> YES	NO	_____
Trailer tounge greased		<input checked="" type="radio"/> YES	NO	_____
Trailer number visible		<input checked="" type="radio"/> YES	NO	_____
Trailer moved and brakes working		<input checked="" type="radio"/> YES	NO	_____
Tire pressure ok		<input checked="" type="radio"/> YES	NO	_____
Tire tread ok		<input checked="" type="radio"/> YES	NO	_____
Hubs, lugs, and rims ok (need to be grea		<input checked="" type="radio"/> YES	NO	_____
Doors and hinges operating properly		YES	<input checked="" type="radio"/> NO	_____ <i>did not open</i>
Locks on doors (trailer secured)		<input checked="" type="radio"/> YES	NO	_____ <i>020206/1633061</i>
Condition of Trailer			Excellent <input checked="" type="radio"/> Good Fair Poor	_____

Comments on above items Seals _____

Inspector: _____
 Print: Chase Hyslop

Signature: _____

Facility Rep _____
 Print: Mike Jackson

Signature: _____

Notify Facility 24 hrs prior to inspection

Person Notified: _____

Check if Verification only

Moran Environmental Recovery LLC Inspection Sheet

DATE: 11/7/22

LOCATION: Plant McIntosh

INSIDE CONTAINER

		Circle one	Comments
6- 26lb Anchors with chain	Verified: YES	<input checked="" type="radio"/> NO	_____
4- Buoys with 2 shackles each	Verified: YES	<input checked="" type="radio"/> NO	_____
2 spools of line	Verified: YES	<input checked="" type="radio"/> NO	_____
2000' 18" containment boom (verification of)	Verified: YES	<input checked="" type="radio"/> NO	_____
4 Bundles absorbent pads	Verified: YES	<input checked="" type="radio"/> NO	_____
4- Bundles absorbent boom	Verified: YES	<input checked="" type="radio"/> NO	_____
1- Roll trash bags	Verified: YES	<input checked="" type="radio"/> NO	_____
1- Pair pliers	Verified: YES	<input checked="" type="radio"/> NO	_____
1- First Aid Kit	Verified: YES	<input checked="" type="radio"/> NO	_____
1-Eye Wash	Verified: YES	<input checked="" type="radio"/> NO	_____

OUTSIDE CONTAINER

Box number 8

Container accessible Verified: YES NO _____

Seal in place Verified: YES NO 1633 005 / 1631 023

Seal number _____

Container Temp Hi _____ Lo _____ Date: _____

Inspector: Chris Hunter
Print: _____

Signature: [Signature]

Facility Rep: Owen Bryant
Print: _____

Signature: [Signature]

Notify Facility 24 hrs prior to inspection

Person Notified: _____

Check if Verification only

Moran Environmental Recovery LLC Inspection Sheet

DATE: 11/7/22

Location: Phillips 66

Unit #: BR 4

BOOM REELS

	Circle										
Grease Chain	<input checked="" type="radio"/> YES	NO									
Grease Fittings	<input checked="" type="radio"/> YES	NO									
Inspect sprocket	<input checked="" type="radio"/> YES	NO									
Check Oil level in motor	<input checked="" type="radio"/> YES	NO									
Reel clear of debris and grass	<input checked="" type="radio"/> YES	NO									
Run motor	<input checked="" type="radio"/> YES	NO									
Hand Brake operational	<input checked="" type="radio"/> YES	NO									
Boom Reel cover secure	YES	<input checked="" type="radio"/> NO									
*** 1000ft of 18" containment boom (Verify Quantiti	YES	<input checked="" type="radio"/> NO									
Condition of Boom Reel Cover	<table border="0" style="margin: auto;"> <tr> <td style="padding: 0 10px;">Excellent</td> <td style="padding: 0 10px;">Good</td> <td style="padding: 0 10px;">Fair</td> <td style="padding: 0 10px;"><input checked="" type="radio"/> Poor</td> </tr> <tr> <td style="padding: 0 10px;">Excellent</td> <td style="padding: 0 10px;"><input checked="" type="radio"/> Good</td> <td style="padding: 0 10px;">Fair</td> <td style="padding: 0 10px;">Poor</td> </tr> </table>			Excellent	Good	Fair	<input checked="" type="radio"/> Poor	Excellent	<input checked="" type="radio"/> Good	Fair	Poor
Excellent	Good	Fair	<input checked="" type="radio"/> Poor								
Excellent	<input checked="" type="radio"/> Good	Fair	Poor								
Condition of Boom Reel	<table border="0" style="margin: auto;"> <tr> <td style="padding: 0 10px;">Excellent</td> <td style="padding: 0 10px;"><input checked="" type="radio"/> Good</td> <td style="padding: 0 10px;">Fair</td> <td style="padding: 0 10px;">Poor</td> </tr> </table>			Excellent	<input checked="" type="radio"/> Good	Fair	Poor				
Excellent	<input checked="" type="radio"/> Good	Fair	Poor								

*** See Boom condition Report for updated Boom Condition

Inspector: Chaseth Signature: [Signature]

Facility Rep: Sandra Gomez Signature: [Signature]

Notify Facility 24 hrs prior to inspection

Person Notified: _____

Check if Verification only

Moran Environmental Recovery LLC Inspection Sheet

Vessel Name: Al Allen

Vessel Make: Lobelle

Inspection Date: 11/7/22

Unit #: 862

Location: MER Yard Phillips 66

Last Months Recorded Hours _____
Current Months Recorded Hours 197.6

Check items (X)

Check items (X)

Visual Hull Inspection

Check fuel level (full)

Check Batteries

Check oil level

Inspect fuel lines

Spark Plug wires

Inspect Bilge

Boat Clean

Operate Bilge pump

Operate for 15 min

GPS /VHF Working

*** VESSEL SHOULD GO THROUGH A SEA TRIAL TO INSURE OPERATING AT PEAK PERFORMANCE A MIN OF ONCE PER QUARTER

Trailer #: 6094

Inspector:
Print: [Signature]

Signature: [Signature]

Facility Rep
Print: Sandra Gomez

Signature: [Signature]

Notify Facility 24 hrs prior to inspection

Person Notified: _____

Check if Verification only

Moran Environmental Recovery LLC Inspection Sheet

Vessel Name: Munson

Vessel Make: Custom

Inspection Date: 11/7/22

Unit #: 471

Location: JMitt North

Last Months Recorded Hours _____
Current Months Recorded Hours 31.9

Check items (X)

Check items (X)

Visual Hull Inspection

Check fuel level (full)

Check Batteries

Check oil level

Inspect fuel lines

Spark Plug wires

Inspect Bilge

Boat Clean

Operate Bilge pump

Operate for 15 min

No Electronics

*** VESSEL SHOULD GO THROUGH A SEA TRIAL TO INSURE OPERATING AT PEAK PERFORMANCE A MIN OF ONCE PER QUARTER

Trailer #: 6651

Inspector:
Print: Chase Hurst

Signature: [Signature]

Facility Rep
Print: Roy BABOT

Signature: [Signature]

Notify Facility 24 hrs prior to inspection

Person Notified: _____

Check if Verification only

Moran Environmental Recovery LLC Inspection Sheet

DATE: 11/7/22

LOCATION: IMTT North

INSIDE CONTAINER

		Circle one	Comments
6- 26lb Anchors with chain	Verified: YES	<input checked="" type="radio"/> NO	_____
4- Buoys with 2 shackels each	Verified: YES	<input checked="" type="radio"/> NO	_____
2 spools of line	Verified: YES	<input checked="" type="radio"/> NO	_____
2000' 18" containment boom (verification of)	Verified: YES	<input checked="" type="radio"/> NO	_____
4 Bundles absorbent pads	Verified: YES	<input checked="" type="radio"/> NO	_____
4- Bundles absorbent boom	Verified: YES	<input checked="" type="radio"/> NO	_____
1- Roll trash bags	Verified: YES	<input checked="" type="radio"/> NO	_____
1- Pair pliers	Verified: YES	<input checked="" type="radio"/> NO	_____
1- First Aid Kit	Verified: YES	<input checked="" type="radio"/> NO	_____
1-Eye Wash	Verified: YES	<input checked="" type="radio"/> NO	_____

OUTSIDE CONTAINER

Box number 4
 Container accessible Verified: YES NO
 Seal in place Verified: YES NO 1633121 / 1633122
 Seal number _____
 Container Temp Hi _____ Lo _____ Date: _____

Inspector:
 Print: A. Raschewski

Signature: [Signature]

Facility Rep
 Print: Roy BABOT

Signature: [Signature]

Notify Facility 24 hrs prior to inspection

Person Notified: _____



Check if Verification only

Moran Environmental Recovery LLC Inspection Sheet

DATE: 11/7/22

LOCATION: Metro Ports

INSIDE CONTAINER

		Circle one	Comments
6- 26lb Anchors with chain	Verified: YES	<input checked="" type="radio"/> NO	_____
4- Buoys with 2 shackles each	Verified: YES	<input checked="" type="radio"/> NO	_____
2 spools of line	Verified: YES	<input checked="" type="radio"/> NO	_____
2000' 18" containment boom (verification of)	Verified: YES	<input checked="" type="radio"/> NO	_____
4 Bundles absorbent pads	Verified: YES	<input checked="" type="radio"/> NO	_____
4- Bundles absorbent boom	Verified: YES	<input checked="" type="radio"/> NO	_____
1- Roll trash bags	Verified: YES	<input checked="" type="radio"/> NO	_____
1- Pair pliers	Verified: YES	<input checked="" type="radio"/> NO	_____
1- First Aid Kit	Verified: YES	<input checked="" type="radio"/> NO	_____
1-Eye Wash	Verified: YES	<input checked="" type="radio"/> NO	_____

OUTSIDE CONTAINER

Box number 5

Container accessible Verified: YES NO

Seal in place Verified: YES NO 1633123 / 1633123

Seal number _____

Container Temp Hi _____ Lo _____ Date: _____

Inspector: Chase Huest
Print: _____

Signature: [Signature]

Facility Rep: Tom Dolan
Print: _____

Signature: [Signature]

Notify Facility 24 hrs prior to inspection

Person Notified: _____



Check if Verification only

Moran Environmental Recovery LLC Inspection Sheet

DATE: 11/7/22

LOCATION: Metro Ports

INSIDE CONTAINER

		Circle one	Comments
6- 26lb Anchors with chain	Verified: YES	<input checked="" type="radio"/> NO	_____
4- Buoys with 2 shackles each	Verified: YES	<input checked="" type="radio"/> NO	_____
2 spools of line	Verified: YES	<input checked="" type="radio"/> NO	_____
2000' 18" containment boom (verification of)	Verified: YES	<input checked="" type="radio"/> NO	_____
4 Bundles absorbent pads	Verified: YES	<input checked="" type="radio"/> NO	_____
4- Bundles absorbent boom	Verified: YES	<input checked="" type="radio"/> NO	_____
1- Roll trash bags	Verified: YES	<input checked="" type="radio"/> NO	_____
1- Pair pliers	Verified: YES	<input checked="" type="radio"/> NO	_____
1- First Aid Kit	Verified: YES	<input checked="" type="radio"/> NO	_____
1-Eye Wash	Verified: YES	<input checked="" type="radio"/> NO	_____

OUTSIDE CONTAINER

Box number 6
 Container accessible Verified: YES NO _____
 Seal in place Verified: YES NO 1633004/1633062
 Seal number _____
 Container Temp Hi _____ Lo _____ Date: _____

Inspector: Chase Hurst
 Print: _____

Signature: [Signature]

Facility Rep: Tom Dulan
 Print: _____

Signature: [Signature]

Notify Facility 24 hrs prior to inspection

Person Notified: _____

Check if Verification only

Moran Environmental Recovery LLC Inspection Sheet

DATE: 11/7/22

LOCATION Colonial Terminal

INSIDE CONTAINER

		Circle one	Comments
6- 26lb Anchors with chain	Verified: YES	<input checked="" type="radio"/> NO	_____
4- Buoys with 2 shackles each	Verified: YES	<input checked="" type="radio"/> NO	_____
2 spools of line	Verified: YES	<input checked="" type="radio"/> NO	_____
2000' 18" containment boom (verification of)	Verified: YES	<input checked="" type="radio"/> NO	_____
4 Bundles absorbent pads	Verified: YES	<input checked="" type="radio"/> NO	_____
4- Bundles absorbent boom	Verified: YES	<input checked="" type="radio"/> NO	_____
1- Roll trash bags	Verified: YES	<input checked="" type="radio"/> NO	_____
1- Pair pliers	Verified: YES	<input checked="" type="radio"/> NO	_____
1- First Aid Kit	Verified: YES	<input checked="" type="radio"/> NO	_____
1-Eye Wash	Verified: YES	<input checked="" type="radio"/> NO	_____

OUTSIDE CONTAINER

Box number 3

Container accessible Verified: YES NO

Seal in place Verified: YES NO 0485693/0485987

Seal number _____

Container Temp Hi _____ Lo _____ Date: _____

Inspector Chase Hurd
Print: _____

Signature: [Signature]

Facility Rep Tom Dida
Print: _____

Signature: [Signature]

Notify Facility 24 hrs prior to inspection

Person Notified: _____

Check if Verification only

Moran Environmental Recovery LLC Inspection Sheet

DATE: 11/7/22

LOCATION: VOPAK

Trailer # 6017 Trailer Serial # 4X4TSEZ253U202767 Date Placed in Service: 2003

		Circle one	Comments
4- 26lb Anchors with chain	Verified: YES	<input checked="" type="radio"/> NO	_____
4- Buoys with 2 shackles each	Verified: YES	<input checked="" type="radio"/> NO	_____
4- Long lines	Verified: YES	<input checked="" type="radio"/> NO	_____
4- Short lines	Verified: YES	<input checked="" type="radio"/> NO	_____
*** 1000' 18" containment boom (Verify Qua	Verified: YES	<input checked="" type="radio"/> NO	_____
4 Bundles absorbent pads	Verified: YES	<input checked="" type="radio"/> NO	_____
4- Bundles absorbent boom	Verified: YES	<input checked="" type="radio"/> NO	_____
1- Roll trash bags	Verified: YES	<input checked="" type="radio"/> NO	_____
2- Life jackets	Verified: YES	<input checked="" type="radio"/> NO	_____
1- Pair pliers	Verified: YES	<input checked="" type="radio"/> NO	_____
1- Skimmer 1800 SH	Verified: YES	<input checked="" type="radio"/> NO	_____
1- First Aid Kit	Verified: YES	<input checked="" type="radio"/> NO	_____
1-EyeWash	Verified: YES	<input checked="" type="radio"/> NO	_____

*** See Boom Condition Report for updated Boom Condition

Comments on above Inventory: _____

OUTSIDE OF TRAILER

		Circle	Comments
Tag in place and current	Tag#		_____
Washed/Clean		<input checked="" type="radio"/> YES NO	_____
Lights operational		<input checked="" type="radio"/> YES NO	_____
Trailer tounge greased		<input checked="" type="radio"/> YES NO	_____
Trailer number visible		<input checked="" type="radio"/> YES NO	_____
Trailer moved and brakes working		<input checked="" type="radio"/> YES NO	_____
Tire pressure ok		<input checked="" type="radio"/> YES NO	_____
Tire tread ok		<input checked="" type="radio"/> YES NO	_____
Hubs, lugs, and rims ok (need to be grea		<input checked="" type="radio"/> YES NO	_____
Doors and hinges operating properly		YES <input checked="" type="radio"/> NO	Did not open
Locks on doors (trailer secured)		<input checked="" type="radio"/> YES NO	020806/1633061
Condition of Trailer		Excellent <input checked="" type="radio"/> Good Fair Poor	_____

Comments on above items Seals _____

Inspector: _____
 Print: Crashley

Signature: [Signature]

Facility Rep: _____
 Print: Mike Jackson

Signature: _____

Notify Facility 24 hrs prior to inspection

Person Notified: _____

Check if Verification only