

Moran Environmental Recovery LLC Inspection Sheet

Vessel Name: 17' Work Boat Vessel Make: Custom

Inspection Date: _____ Unit #: 866

Location: Savannah, GA Registration #: GA 0302 UT

Last Months Recorded Hours _____
Current Months Recorded Hours AT the Shop

Check items (X)

Check items (X)

- | | |
|---|--|
| <input type="checkbox"/> Visual Hull Inspection | <input type="checkbox"/> Check fuel level (full) |
| <input type="checkbox"/> Check Batteries | <input type="checkbox"/> Check oil level |
| <input type="checkbox"/> Inspect fuel lines | <input type="checkbox"/> Spark Plug wires |
| <input type="checkbox"/> Inspect Bilge | <input type="checkbox"/> Boat Clean |
| <input type="checkbox"/> Operate Bilge pump | <input type="checkbox"/> Operate for 15 min |
| <input type="checkbox"/> No Electronics | |

*** VESSEL SHOULD GO THROUGH A SEA TRIAL TO INSURE OPERATING AT PEAK PERFORMANCE A MIN OF ONCE PER QUARTER

Trailer #: 6135 Tag & Exp: _____

DOT Inspection: _____ Insurance: _____

Tire Pressure: _____ Wheels/Lugs: _____

Brakes: _____ Axle Hubs: _____

Trailer Lights: _____ Trailer Jack: _____

Trailer Frame: _____ Bunks: _____

Inspector: _____
Print: _____ Signature: _____

Facility Rep _____
Print: _____ Signature: _____

Notify Facility 24 hrs prior to inspection

Person Notified: _____

Check if Verification only

Moran Environmental Recovery LLC Inspection Sheet

Vessel Name: Marco Skimmer Vessel Make: 30' Kvichak Skimmer
 Inspection Date: 6/14/24 Unit #: 895
 Location: Savannah, GA Registration #: GA 9056 SC

Last Months Recorded Hours _____
 Current Months Recorded Hours 29.5 / 59.6

<p>Check items (X)</p> <p><input checked="" type="checkbox"/> Visual Hull Inspection</p> <p><input checked="" type="checkbox"/> Check Batteries</p> <p><input checked="" type="checkbox"/> Inspect fuel lines</p> <p><input checked="" type="checkbox"/> Inspect Bilge</p> <p><input checked="" type="checkbox"/> Operate Bilge pump</p> <p><input checked="" type="checkbox"/> No Electronics</p>	<p>Check items (X)</p> <p><input checked="" type="checkbox"/> Check fuel level (full)</p> <p><input checked="" type="checkbox"/> Check oil level</p> <p><input checked="" type="checkbox"/> Spark Plug wires</p> <p><input checked="" type="checkbox"/> Boat Clean</p> <p><input checked="" type="checkbox"/> Operate for 15 min</p> <p><input type="checkbox"/> Insurance</p>
--	--

*** VESSEL SHOULD GO THROUGH A SEA TRIAL TO INSURE OPERATING AT PEAK PERFORMANCE A MIN OF ONCE PER QUARTER

Trailer #: <u>6648</u>	Tag & Exp: <u>TU53E28 7/24</u>
DOT Inspection: <u>7/23</u>	Insurance: _____
Tire Pressure: <input checked="" type="checkbox"/>	Wheels/Lugs: <input checked="" type="checkbox"/>
Brakes: <input checked="" type="checkbox"/>	Axle Hubs: <input checked="" type="checkbox"/>
Trailer Lights: <input checked="" type="checkbox"/>	Trailer Jack: <input checked="" type="checkbox"/>
Trailer Frame: <input checked="" type="checkbox"/>	Bunks: <input checked="" type="checkbox"/>

Inspector: Josiah Strickland Signature: Josiah Strickland
 Print: _____
 Facility Rep: _____ Signature: _____
 Print: _____

Notify Facility 24 hrs prior to inspection
 Person Notified: _____

Check if Verification only

Moran Environmental Recovery LLC Inspection Sheet

Vessel Name: 34' Barge Boat

Vessel Make: Custom

Inspection Date: 6/14/24

Unit #: 891

Location: Savannah, GA

Registration #: GA 6589 DC

Last Months Recorded Hours
Current Months Recorded Hours

71.1 / 74.1

Check items (X)

Check items (X)

Visual Hull Inspection

3/4 / 1/2 Check fuel level (full)

Check Batteries

Check oil level

Inspect fuel lines

Spark Plug wires

Inspect Bilge

Boat Clean

Operate Bilge pump

Operate for 15 min

No Electronics

Insurance

*** VESSEL SHOULD GO THROUGH A SEA TRIAL TO INSURE OPERATING AT PEAK PERFORMANCE A MIN OF ONCE PER QUARTER

Trailer #: 6004

Tag & Exp: XKG964

DOT Inspection: 5/24

Insurance: _____

Tire Pressure:

Wheels/Lugs:

Brakes:

Axle Hubs:

Trailer Lights:

Trailer Jack:

Trailer Frame:

Bunks: _____

Inspector:
Print: Josiah Strickland

Signature: Josiah Strickland

Facility Rep
Print: _____

Signature: _____

Notify Facility 24 hrs prior to inspection

Person Notified: _____

Check if Verification only

Moran Environmental Recovery LLC Inspection Sheet

DATE: 6/10/24

LOCATION Plant McIntosh

INSIDE CONTAINER

		Circle one	Comments
6- 26lb Anchors with chain	Verified: YES	<input checked="" type="radio"/> NO	_____
4- Buoys with 2 shackles each	Verified: YES	<input checked="" type="radio"/> NO	_____
2 spools of line	Verified: YES	<input checked="" type="radio"/> NO	_____
2000' 18" containment boom (verification of)	Verified: YES	<input checked="" type="radio"/> NO	_____
4 Bundles absorbent pads	Verified: YES	<input checked="" type="radio"/> NO	_____
4- Bundles absorbent boom	Verified: YES	<input checked="" type="radio"/> NO	_____
1- Roll trash bags	Verified: YES	<input checked="" type="radio"/> NO	_____
1- Pair pliers	Verified: YES	<input checked="" type="radio"/> NO	_____
1- First Aid Kit	Verified: YES	<input checked="" type="radio"/> NO	_____
1-Eye Wash	Verified: YES	<input checked="" type="radio"/> NO	_____

OUTSIDE CONTAINER

Box number 8

Container accessible Verified: YES NO _____

Seal in place Verified: YES NO 020825/020826

Seal number _____

Container Temp Hi _____ Lo _____ Date: _____

Inspector: Chase Hurst
Print: _____

Signature: [Signature]

Facility Rep: Owen Bryant
Print: _____

Signature: [Signature]

Notify Facility 24 hrs prior to inspection

Person Notified: _____

Check if Verification only

Moran Environmental Recovery LLC Inspection Sheet

DATE: 6-10-24

LOCATION Metro Ports

INSIDE CONTAINER

		Circle one		Comments
6- 26lb Anchors with chain	Verified:	<u>YES</u>	NO	_____
4- Buoys with 2 shackles each	Verified:	<u>YES</u>	NO	_____
2 spools of line	Verified:	<u>YES</u>	NO	_____
2000' 18" containment boom (verification of)	Verified:	<u>YES</u>	NO	_____
4 Bundles absorbent pads	Verified:	<u>YES</u>	NO	_____
4- Bundles absorbent boom	Verified:	<u>YES</u>	NO	_____
1- Roll trash bags	Verified:	<u>YES</u>	NO	_____
1- Pair pliers	Verified:	<u>YES</u>	NO	_____
1- First Aid Kit	Verified:	<u>YES</u>	NO	_____
1-Eye Wash	Verified:	<u>YES</u>	NO	_____

OUTSIDE CONTAINER

Box number 6

Container accessible Verified: YES NO _____

Seal in place Verified: YES NO _____

Seal number 1633105 7 1633102

Container Temp Hi ✓ Lo _____ Date: 6-10-24

Inspector:
Print: Trouf Cunningham

Signature: *Trouf Cunningham*

Facility Rep
Print: Tom Dolan

Signature: *Tom Dolan*

Notify Facility 24 hrs prior to inspection

Person Notified: _____

Check if Verification only

Moran Environmental Recovery LLC Inspection Sheet

DATE: 6-10-24

LOCATION: Metro Ports

INSIDE CONTAINER

		Circle one	
6- 26lb Anchors with chain	Verified:	<u>YES</u> NO	_____
4- Buoys with 2 shackles each	Verified:	<u>YES</u> NO	_____
2 spools of line	Verified:	<u>YES</u> NO	_____
2000' 18" containment boom (verification of)	Verified:	<u>YES</u> NO	_____
4 Bundles absorbent pads	Verified:	<u>YES</u> NO	_____
4- Bundles absorbent boom	Verified:	<u>YES</u> NO	_____
1- Roll trash bags	Verified:	<u>YES</u> NO	_____
1- Pair pliers	Verified:	<u>YES</u> NO	_____
1- First Aid Kit	Verified:	<u>YES</u> NO	_____
1-Eye Wash	Verified:	<u>YES</u> NO	_____

OUTSIDE CONTAINER

Box number 5

Container accessible Verified: YES NO _____

Seal in place Verified: YES NO _____

Seal number 1633103 / 1633104

Container Temp Hi ✓ Lo _____ Date: 6/10/24

Inspector:
Print: Troy Cunningham

Signature: [Handwritten Signature]

Facility Rep:
Print: Tom Dolan

Signature: [Handwritten Signature]

Notify Facility 24 hrs prior to inspection

Person Notified: _____

Check if Verification only

Moran Environmental Recovery LLC Inspection Sheet

DATE: 6/11/24

LOCATION Colonial Terminal

INSIDE CONTAINER

		Circle one	
6- 26lb Anchors with chain	Verified:	<input checked="" type="radio"/> YES	NO
4- Buoys with 2 shackles each	Verified:	<input checked="" type="radio"/> YES	NO
2 spools of line	Verified:	<input checked="" type="radio"/> YES	NO
2000' 18" containment boom (verification of)	Verified:	YES	<input checked="" type="radio"/> NO
4 Bundles absorbent pads	Verified:	<input checked="" type="radio"/> YES	NO
4- Bundles absorbent boom	Verified:	<input checked="" type="radio"/> YES	NO
1- Roll trash bags	Verified:	<input checked="" type="radio"/> YES	NO
1- Pair pliers	Verified:	<input checked="" type="radio"/> YES	NO
1- First Aid Kit	Verified:	<input checked="" type="radio"/> YES	NO
1-Eye Wash	Verified:	<input checked="" type="radio"/> YES	NO

OUTSIDE CONTAINER

Box number 3

Container accessible Verified: YES NO

Seal in place Verified: YES NO 026804 / 026803 (New)

Seal number _____

Container Temp Hi _____ Lo _____ Date: _____

Inspector
Print: Chase Hurst

Signature: [Signature]

Facility Rep
Print: Tom Dolan

Signature: [Signature]

Notify Facility 24 hrs prior to inspection

Person Notified: _____

Check if Verification only

Moran Environmental Recovery LLC Inspection Sheet

DATE: 6-10-24

LOCATION IMTT North

INSIDE CONTAINER

		Circle one	
6- 26lb Anchors with chain	Verified:	<u>YES</u> NO	_____
4- Buoys with 2 shackles each	Verified:	<u>YES</u> NO	_____
2 spools of line	Verified:	<u>YES</u> NO	_____
2000' 18" containment boom (verification of)	Verified:	<u>YES</u> NO	_____
4 Bundles absorbent pads	Verified:	<u>YES</u> NO	_____
4- Bundles absorbent boom ,	Verified:	<u>YES</u> NO	_____
1- Roll trash bags	Verified:	<u>YES</u> NO	_____
1- Pair pliers	Verified:	<u>YES</u> NO	_____
1- First Aid Kit	Verified:	<u>YES</u> NO	_____
1-Eye Wash	Verified:	<u>YES</u> NO	_____

OUTSIDE CONTAINER

Box number 4

Container accessible Verified: YES NO _____

Seal in place Verified: YES NO _____

Seal number 1633109 / 1633110

Container Temp Hi ✓ Lo _____ Date: _____

Inspector:
Print: Joseph Cunningham

Signature: Joseph Cunningham

Facility Rep
Print: Ray BABOT

Signature: Ray Babot

Notify Facility 24 hrs prior to inspection

Person Notified: _____

Check if Verification only

Moran Environmental Recovery LLC Inspection Sheet

DATE: 6-10-24

Location: Phillips 66

Unit #: BR 4

BOOM REELS

	Circle		Comments
Grease Chain	YES	NO	_____
Grease Fittings	YES	NO	_____
Inspect sprocket	YES	NO	_____
Check Oil level in motor	YES	NO	_____
Reel clear of debris and grass	YES	NO	_____
Run motor	YES	NO	_____
Hand Brake operational	YES	NO	_____
Boom Reel cover secure	YES	NO	_____
*** 1000ft of 18" containment boom (Verify Quanti	YES	NO	_____
Condition of Boom Reel Cover			Excellent Good (Fair) Poor
Condition of Boom Reel			Excellent Good (Fair) Poor

*** See Boom condition Report for updated Boom Condition

Inspector: _____
 Print: Troop Cunningham Signature: [Signature]

Facility Rep _____
 Print: Dan Clome Signature: [Signature]

Notify Facility 24 hrs prior to inspection

Person Notified: _____

Check if Verification only

Moran Environmental Recovery LLC Inspection Sheet

Vessel Name: Al Allen

Vessel Make: Lobelle

Inspection Date: 6-10-24

Unit #: 862

Location: Phillips 66

Registration #: GA 6658 YE

Last Months Recorded Hours
Current Months Recorded Hours

217.9

Check items (X)

Check items (X)

Visual Hull Inspection

Check fuel level (full)

Check Batteries

Check oil level

Inspect fuel lines

Spark Plug wires

Inspect Bilge

Boat Clean

Operate Bilge pump

Operate for 15 min

GPS /VHF Working

Insurance

*** VESSEL SHOULD GO THROUGH A SEA TRIAL TO INSURE OPERATING AT PEAK PERFORMANCE A MIN OF ONCE PER QUARTER

Trailer #: 6094

Tag & Exp:

DOT Inspection:

Insurance:

Tire Pressure:

Wheels/Lugs:

Brakes:

Axle Hubs:

Trailer Lights:

Trailer Jack:

Trailer Frame:

Bunks:

Inspector:

Print: Trap Ambighem

Signature: [Signature]

Facility Rep

Print: Sandra Gomez

Signature: [Signature]

Notify Facility 24 hrs prior to inspection

Person Notified: _____

Check if Verification only

Moran Environmental Recovery LLC Inspection Sheet

DATE: 6-10-24

LOCATION: Elba Island

INSIDE CONTAINER

		Circle one	
6- 26lb Anchors with chain	Verified:	<u>YES</u> NO	
4- Buoys with 2 shackles each	Verified:	<u>YES</u> NO	
2 spools of line	Verified:	<u>YES</u> NO	
2000' 18" containment boom (verification of)	Verified:	<u>YES</u> NO	
4 Bundles absorbent pads	Verified:	<u>YES</u> NO	
4- Bundles absorbent boom	Verified:	<u>YES</u> NO	
1- Roll trash bags	Verified:	<u>YES</u> NO	
1- Pair pliers	Verified:	<u>YES</u> NO	
1- First Aid Kit	Verified:	<u>YES</u> NO	
1-Eye Wash	Verified:	<u>YES</u> NO	

OUTSIDE CONTAINER

Box number 1

Container accessible Verified: YES NO

Seal in place Verified: YES NO

Seal number

Container Temp Hi ✓ Lo 020855 Date: 020853
6-10-24

Inspector:
Print: Troop Cunningham

Signature: Troop Cunningham

Facility Rep
Print: Laura Osborne

Signature: Laura Osborne

Notify Facility 24 hrs prior to inspection

Person Notified: _____

Check if Verification only

Moran Environmental Recovery LLC Inspection Sheet

DATE: 6-10-24

LOCATION: Elba Island

INSIDE CONTAINER

		Circle one	
6- 26lb Anchors with chain	Verified:	<u>YES</u> NO	_____
4- Buoys with 2 shackles each	Verified:	<u>YES</u> NO	_____
2 spools of line	Verified:	<u>YES</u> NO	_____
2000' 18" containment boom (verification of)	Verified:	<u>YES</u> NO	_____
4 Bundles absorbent pads	Verified:	<u>YES</u> NO	_____
4- Bundles absorbent boom	Verified:	<u>YES</u> NO	_____
1- Roll trash bags	Verified:	<u>YES</u> NO	_____
1- Pair pliers	Verified:	<u>YES</u> NO	_____
1- First Aid Kit	Verified:	<u>YES</u> NO	_____
1-Eye Wash	Verified:	<u>YES</u> NO	_____

OUTSIDE CONTAINER

Box number 2

Container accessible Verified: YES NO _____

Seal in place Verified: YES NO _____

Seal number _____

Container Temp Hi ✓ Lo 020827 / 020854 Date: 6-10-24

Inspector:
Print: Troup Cunningham

Signature: [Signature]

Facility Rep
Print: Laura Osburne

Signature: [Signature]

Notify Facility 24 hrs prior to inspection

Person Notified: _____

Check if Verification only

Moran Environmental Recovery LLC Inspection Sheet

Vessel Name: Porpoise

Vessel Make: Custom

Inspection Date: 6/7/24

Unit #: 835

Location: SNF Chemtall

Registration #: GA 6256 GB

Last Months Recorded Hours _____
Current Months Recorded Hours 277

Check items (X)

Check items (X)

Visual Hull Inspection

Check fuel level (full)

Check Batteries

Check oil level

Inspect fuel lines

Spark Plug wires

Inspect Bilge

Boat Clean

Operate Bilge pump

Operate for 15 min

No Electronics

Insurance/Registration

*** VESSEL SHOULD GO THROUGH A SEA TRIAL TO INSURE OPERATING AT PEAK PERFORMANCE A MIN OF ONCE PER QUARTER

Trailer #: 6042

Tag & Exp: 303WZM 06/24

DOT Inspection:

Insurance:

Tire Pressure:

Wheels/Lugs:

Brakes:

Axle Hubs:

Trailer Lights:

Trailer Jack:

Trailer Frame:

Bunks:

Inspector: Chase Hurst
Print: _____

Signature: [Signature]

Facility Rep: Jessica Jager
Print: _____

Signature: [Signature]

Notify Facility 24 hrs prior to inspection

Person Notified: _____

Check if Verification only

Moran Environmental Recovery LLC Inspection Sheet

DATE: 6/27/24

LOCATION: MER

Trailer # 6189 Trailer Serial #53FBE2426KF050872 Date Placed in Service:

		Circle one	Comments
4- 26lb Anchors with chain	Verified:	<input checked="" type="radio"/> YES NO	_____
4- Buoys with 2 shackels each	Verified:	<input checked="" type="radio"/> YES NO	_____
4- Long lines	Verified:	<input checked="" type="radio"/> YES NO	_____
4- Short lines	Verified:	<input checked="" type="radio"/> YES NO	_____
*** 1000' 18" containment boom (Verify Quali	Verified:	<input checked="" type="radio"/> YES NO	_____
4 Bundles absorbent pads	Verified:	<input checked="" type="radio"/> YES NO	_____
4- Bundles absorbent boom	Verified:	<input checked="" type="radio"/> YES NO	_____
1- Roll trash bags	Verified:	<input checked="" type="radio"/> YES NO	_____
2- Life jackets	Verified:	<input checked="" type="radio"/> YES NO	_____
1- Pair pliers	Verified:	<input checked="" type="radio"/> YES NO	_____
1- Skimmer 1800 SH	Verified:	<input checked="" type="radio"/> YES NO	_____
1- First Aid Kit	Verified:	<input checked="" type="radio"/> YES NO	_____
1-EyeWash	Verified:	<input checked="" type="radio"/> YES NO	_____

*** See Boom Condition Report for updated Boom Condition

Comments on above Inventory: _____

OUTSIDE OF TRAILER

	Circle	Comments
Tag in place and current	Tag# <u>TTQSM56</u>	<u>Exp July 24</u>
Washed/Clean	<input checked="" type="radio"/> YES NO	_____
Lights operational	<input checked="" type="radio"/> YES NO	<u>NEEDS Jack Reptool</u>
Trailer tounge greased	<input checked="" type="radio"/> YES NO	_____
Trailer number visible	<input checked="" type="radio"/> YES NO	_____
Trailer moved and brakes working	<input checked="" type="radio"/> YES NO	_____
Tire pressure ok	<input checked="" type="radio"/> YES NO	_____
Tire tread ok	<input checked="" type="radio"/> YES NO	_____
Hubs, lugs, and rims ok (need to be grea	<input checked="" type="radio"/> YES NO	_____
Doors and hinges operating properly	<input checked="" type="radio"/> YES NO	_____
Locks on doors (trailer secured)	<input checked="" type="radio"/> YES NO	_____
Condition of Trailer	Excellent Good <input checked="" type="radio"/> Fair Poor	_____
Comments on above items _____		

Inspector: Chase Hurst

Signature: [Signature]

Facility Rep: Jessica Jager

Signature: [Signature]

Notify Facility 24 hrs prior to inspection

Person Notified: _____

Check if Verification only

Moran Environmental Recovery LLC Inspection Sheet

Vessel Name: Savannah Patriot Vessel Make: Custom
 Inspection Date: 6/12/24 Unit #: 865
 Location: Savannah, GA Registration #: GA 0296 NW

Last Months Recorded Hours _____
 Current Months Recorded Hours 186 / 1006

- | | |
|--|---|
| <p>Check items (X)</p> <p><input checked="" type="checkbox"/> Visual Hull Inspection</p> <p><input checked="" type="checkbox"/> Check Batteries</p> <p><input checked="" type="checkbox"/> Inspect fuel lines</p> <p><input checked="" type="checkbox"/> Inspect Bilge</p> <p><input checked="" type="checkbox"/> Operate Bilge pump</p> <p><input checked="" type="checkbox"/> No Electronics</p> | <p>Check items (X)</p> <p><input checked="" type="checkbox"/> Check fuel level (full)</p> <p><input checked="" type="checkbox"/> Check oil level</p> <p><input checked="" type="checkbox"/> Spark Plug wires</p> <p><input checked="" type="checkbox"/> Boat Clean</p> <p><input type="checkbox"/> Operate for 15 min</p> <p><input type="checkbox"/> Insurance</p> |
|--|---|

*** VESSEL SHOULD GO THROUGH A SEA TRIAL TO INSURE OPERATING AT PEAK PERFORMANCE A MIN OF ONCE PER QUARTER

Trailer #: <u>6113</u>	Tag & Exp: <u>7/24 TR1573L</u>
DOT Inspection: <u>2023</u>	Insurance: <u>7/25</u>
Tire Pressure: _____	Wheels/Lugs: <input checked="" type="checkbox"/>
Brakes: <input checked="" type="checkbox"/>	Axle Hubs: <input checked="" type="checkbox"/>
Trailer Lights: <input checked="" type="checkbox"/>	Trailer Jack: <input checked="" type="checkbox"/>
Trailer Frame: <input checked="" type="checkbox"/>	Bunks: _____

Inspector: _____
 Print: _____ Signature: _____

Facility Rep _____
 Print: _____ Signature: _____

Notify Facility 24 hrs prior to inspection

Person Notified: _____

Check if Verification only

Moran Environmental Recovery LLC Inspection Sheet

Vessel Name: Munson

Vessel Make: Custom

Inspection Date: 6/12/24

Unit #: 871

Location: Colonial North

Registration #: GA 0499 SN

Last Months Recorded Hours
Current Months Recorded Hours

737 - 740

Check items (X)

Check items (X)

Visual Hull Inspection

Check fuel level (full)

Check Batteries

Check oil level

Inspect fuel lines

Spark Plug wires

Inspect Bilge

Boat Clean

Operate Bilge pump

Operate for 15 min

No Electronics

Insurance

*** VESSEL SHOULD GO THROUGH A SEA TRIAL TO INSURE OPERATING AT PEAK PERFORMANCE A MIN OF ONCE PER QUARTER

Trailer #: 6147

Tag & Exp: F53-673 / 2024

DOT Inspection: 2023

Insurance: 7/26

Tire Pressure:

Wheels/Lugs:

Brakes:

Axle Hubs:

Trailer Lights:

Trailer Jack:

Trailer Frame:

Bunks:

Inspector:

Print: _____

Signature: _____

Facility Rep

Print: _____

Signature: _____

Notify Facility 24 hrs prior to inspection

Person Notified: _____

Check if Verification only

Moran Environmental Recovery LLC Inspection Sheet

DATE: 6/12/24 LOCATION: MER YARD

Trailer #: 6188 SKIMMER TRAILER
 Tag#: TT35W74
 Removed: YES NO

SK-1 SKIMMERS

Elastic Drum Skimmer Hydraulic TDSH13699178
 - Condition Circle: Excellent Good Poor Fair
 - Last Run Test Date: _____
 Comment: _____

SK-2 Action Pertolium Drum Skimmer Air driven Mod 18A Serial # 314
 - Condition Circle: Excellent Good Poor Fair
 - Last Run Test Date: _____
 Comment: _____

SK-3 Crucial Coated Drum Skimmer Mod#1CD18H36 Ser#214468
 -Condition Circle: Excellent Good Poor Fair
 -Last RunTest Date: _____
 Comment: _____

SK-4 Desmi DOP 160 Screw Pump Circle: Excellent Good Poor Fair
 Date: _____
 Comment: _____

PM-1 PUMPS

3in Hydraulic Submersible Pump Serial # 11197
 - Condition Circle: Excellent Good Poor Fair
 - Last Run Test Date: _____
 Comment: _____

PM-2 4in Vickers Hydraulic Submersible Pump Serial # 25M85A1C20
 - Condition Circle: Excellent Good Poor Fair
 - Last Run Test Date: _____
 Comment: _____

PM-3 6in Hydrotech Hydraulic Submersible Pump Serial # 6F878
 - Condition Circle: Excellent Good Poor Fair
 - Last Run Test Date: _____
 Comment: _____

PM-4 3" Crucial Diesel SD Pump Mod#DDP-3 Ser#214468
 -Condition Circle: Excellent Good Poor Fair
 -Last Run Test Date: _____
 Comment: _____

PP-1 POWER PACKS

Elastic Power Pack Serial # H1198258
 - Condition Circle: Excellent Good Poor Fair
 - Last Run Test Date: _____
 Comment: _____

PP-2 739 Hydrotech Power Pack Mod # HT60DCV Serial # F:
 - Condition Circle: Excellent Good Poor Fair
 - Last Run Test Date: _____
 Comment: _____

PP-3 Crucial Diesel Compres **Mod#L70190126P17E Ser#214468**
 -Condition Circle: Excellent Good Poor Fair
 -Last Run Test Date: _____
 Comment: _____

PP-4 Crucial Trailer-Mounted Diesel 25 HP Powerpack Circle: Excellent Good Poor Fair
 Date: _____
 Comment: _____

Inspector: Josiah Strickland
 Print: _____

Signature: Josiah Strickland

Inspector: _____
 Print: _____

Signature: _____

Moran Environmental Recovery LLC Inspection Sheet

DATE: 6/12/24

LOCATION: MER

Trailer # 6186 Trailer Serial #53FBE2421KF050875 Date Placed in Service:

	Verified:	Circle one		Comments
4- 26lb Anchors with chain	YES	YES	NO	
4- Buoys with 2 shackles each	YES	YES	NO	
4- Long lines	YES	YES	NO	
4- Short lines	YES	YES	NO	OUT OF SERVICE
*** 1000' 18" containment boom (Verify Qua)	YES	YES	NO	
4 Bundles absorbent pads	YES	YES	NO	
4- Bundles absorbent boom	YES	YES	NO	
1- Roll trash bags	YES	YES	NO	
2- Life jackets	YES	YES	NO	
1- Pair pliers	YES	YES	NO	
1- Skimmer 1800 SH	YES	YES	NO	
1- First Aid Kit	YES	YES	NO	
1-EyeWash	YES	YES	NO	

*** See Boom Condition Report for updated Boom Condition

Comments on above Inventory: _____

OUTSIDE OF TRAILER

	Tag#	Circle		Comments
Tag in place and current		YES	NO	
Washed/Clean		YES	NO	
Lights operational		YES	NO	
Trailer tounge greased		YES	NO	
Trailer number visible		YES	NO	
Trailer moved and brakes working		YES	NO	
Tire pressure ok		YES	NO	
Tire tread ok		YES	NO	
Hubs, lugs, and rims ok (need to be grea		YES	NO	
Doors and hinges operating properly		YES	NO	
Locks on doors (trailer secured)		YES	NO	

Condition of Trailer Excellent Good Fair Poor

Comments on above items _____

Inspector: Joseph Strickland
 Print: _____

Signature: [Signature]

Facility Rep
 Print: _____

Signature: _____

Notify Facility 24 hrs prior to inspection

Person Notified: _____

Check if Verification only

Moran Environmental Recovery LLC Inspection Sheet

DATE: 6/12/24

LOCATION: MER

Trailer # 6187

Trailer Serial #

Date Placed in Service:

Circle one

Comments

4- 26lb Anchors with chain	Verified:	YES	NO	_____
4- Buoys with 2 shackles each	Verified:	YES	NO	_____
4- Long lines	Verified:	YES	NO	_____
4- Short lines	Verified:	YES	NO	<u>OUT OF SERVICE</u>
*** 1000' 18" containment boom (Verify Qua	Verified:	YES	NO	_____
4 Bundles absorbent pads	Verified:	YES	NO	_____
4- Bundles absorbent boom	Verified:	YES	NO	_____
1- Roll trash bags	Verified:	YES	NO	_____
2- Life jackets	Verified:	YES	NO	_____
1- Pair pliers	Verified:	YES	NO	_____
1- Skimmer 1800 SH	Verified:	YES	NO	_____
1- First Aid Kit	Verified:	YES	NO	_____
1-EyeWash	Verified:	YES	NO	_____

*** See Boom Condition Report for updated Boom Condition

Comments on above Inventory: _____

OUTSIDE OF TRAILER

Circle

Comments

Tag in place and current	Tag#	_____	_____	_____
Washed/Clean		YES	NO	_____
Lights operational		YES	NO	_____
Trailer tounge greased		YES	NO	_____
Trailer number visible		YES	NO	_____
Trailer moved and brakes working		YES	NO	_____
Tire pressure ok		YES	NO	_____
Tire tread ok		YES	NO	_____
Hubs, lugs, and rims ok (need to be grea		YES	NO	_____
Doors and hinges operating properly		YES	NO	_____
Locks on doors (trailer secured)		YES	NO	_____

Condition of Trailer Excellent Good Fair Poor

Comments on above items _____

Inspector: Josiah Strickland

Signature: Josiah Strickland

Facility Rep
Print: _____

Signature: _____

Notify Facility 24 hrs prior to inspection

Person Notified: _____

Check if Verification only

Moran Environmental Recovery LLC Inspection Sheet

DATE: 6/12/24

Location: MER Yard

Unit #: 6729

BOOM REELS

	Circle		
Grease Chain	YES	<input checked="" type="radio"/> NO	
Grease Fittings	YES	<input checked="" type="radio"/> NO	
Inspect sprocket	<input checked="" type="radio"/> YES	NO	
Check Oil level in motor	<input checked="" type="radio"/> YES	NO	
Reel clear of debris and grass	<input checked="" type="radio"/> YES	NO	
Run motor	<input checked="" type="radio"/> YES	NO	
Hand Brake operational	<input checked="" type="radio"/> YES	NO	
Boom Reel cover secure	<input checked="" type="radio"/> YES	NO	
*** 1000ft of 18" containment boom (Verify Quanti	<input checked="" type="radio"/> YES	NO	
Condition of Boom Reel Cover			Excellent <input checked="" type="radio"/> Good Fair Poor
Condition of Boom Reel			Excellent <input checked="" type="radio"/> Good Fair Poor

*** See Boom condition Report for updated Boom Condition

Trailer #: 6729

Tag & Exp: TW50V80 7/24

DOT Inspection: 11/23

Insurance:

Tire Pressure:

Wheels/Lugs:

Brakes:

Axle Hubs:

Trailer Lights:

Trailer Jack:

Trailer Frame:

Hydraulics:

Inspector: Josiah Strickland Signature: Josiah Strickland

Facility Rep Print: _____ Signature: _____

Notify Facility 24 hrs prior to inspection

Person Notified: _____

Check if Verification only

Moran Environmental Recovery LLC Inspection Sheet

DATE: 6/12/24

Location: MER Yard

Unit #: 6712

BOOM REELS

	Circle		Comments
Grease Chain	YES	<input type="radio"/> NO	_____
Grease Fittings	YES	<input type="radio"/> NO	_____
Inspect sprocket	<input checked="" type="radio"/> YES	NO	_____
Check Oil level in motor	<input checked="" type="radio"/> YES	NO	_____
Reel clear of debris and grass	<input checked="" type="radio"/> YES	NO	_____
Run motor	<input checked="" type="radio"/> YES	NO	_____
Hand Brake operational	<input checked="" type="radio"/> YES	NO	_____
Boom Reel cover secure	<input checked="" type="radio"/> YES	NO	_____
*** 1000ft of 18" containment boom (Verify Quantity)	<input checked="" type="radio"/> YES	NO	_____
Condition of Boom Reel Cover	Excellent	<input checked="" type="radio"/> Good	Fair Poor
Condition of Boom Reel	Excellent	<input checked="" type="radio"/> Good	Fair Poor

*** See Boom condition Report for updated Boom Condition

Trailer #: 6712

Tag & Exp: YHG242

DOT Inspection: 11/23

Insurance: _____

Tire Pressure:

Wheels/Lugs:

Brakes:

Axle Hubs:

Trailer Lights:

Trailer Jack:

Trailer Frame:

Hydraulics:

Inspector: Josiah Strickland

Signature: *Josiah Strickland*

Facility Rep Print: _____ Signature: _____

Notify Facility 24 hrs prior to inspection

Person Notified: _____

Check if Verification only

