

Moran Environmental Recovery LLC
Inspection Sheet

Notes

Unit 866 - Electronics need replacing

Unit 835 - Electronics need replacing

Unit 865 - VHF needs replacing

CONEX Box 8 - Spray for wasp

IMTT wash boxes

Elba Island wash boxes

Plant 2 box ~~needs~~ brush boxes

895 - Anchor light needs to be fixed / Belts and hoses replaced

871 - Port nav light out

891 - Replace the generator

835 - Out of service, it is in the shop

Pressure wash all CONEX boxes

Moran Environmental Recovery LLC Inspection Sheet

Vessel Name: Porpoise Vessel Make: Custom
 Inspection Date: 6/5/25 Unit #: 835
 Location: SNF Chemtall Registration #: GA 6256 GB

Last Months Recorded Hours _____
 Current Months Recorded Hours _____

Check items (X)

Check items (X)

<input type="checkbox"/> Visual Hull Inspection	<input type="checkbox"/> Check fuel level (full)
<input type="checkbox"/> Check Batteries	<input type="checkbox"/> Check oil level
<input type="checkbox"/> Inspect fuel lines	<input type="checkbox"/> Spark Plug wires
<input type="checkbox"/> Inspect Bilge	<input type="checkbox"/> Boat Clean
<input type="checkbox"/> Operate Bilge pump	<input type="checkbox"/> Operate for 15 min
<input type="checkbox"/> No Electronics	<input type="checkbox"/> Insurance/Registration

*** VESSEL SHOULD GO THROUGH A SEA TRIAL TO INSURE OPERATING AT PEAK PERFORMANCE A MIN OF ONCE PER QUARTER

Trailer #: 6042 Tag & Exp: _____
 DOT Inspection: _____ Insurance: _____
 Tire Pressure: Out of Service Wheels/Lugs: _____
 Brakes: _____ Axle Hubs: _____
 Trailer Lights: _____ Trailer Jack: _____
 Trailer Frame: _____ Bunks: _____

Inspector:
 Print: Shawn Smith

Signature: 

Facility Rep
 Print: _____

Signature: _____

Notify Facility 24 hrs prior to inspection

Person Notified: _____

Check if Verification only

Moran Environmental Recovery LLC Inspection Sheet

DATE: 6/5/25

Location: MER Yard

Unit #: 6712

BOOM REELS

	Circle		
Grease Chain	YES	NO	_____
Grease Fittings	YES	NO	_____
Inspect sprocket	YES	NO	_____
Check Oil level in motor	YES	NO	_____
Reel clear of debris and grass	YES	NO	_____
Run motor	YES	NO	_____
Hand Brake operational	YES	NO	_____
Boom Reel cover secure	YES	NO	_____
*** 1000ft of 18" containment boom (Verify Quanti	YES	NO	_____
Condition of Boom Reel Cover			Excellent <u>Good</u> Fair Poor
Condition of Boom Reel			Excellent <u>Good</u> Fair Poor

*** See Boom condition Report for updated Boom Condition

Trailer #: 6712

Tag & Exp: TV 50 V80 Jul/25

DOT Inspection: SEPT 24

Insurance: X

Tire Pressure: X

Wheels/Lugs: X

Brakes: X

Axle Hubs: X

Trailer Lights: X

Trailer Jack: X

Trailer Frame: X

Hydraulics: X

Inspector: Slavik Smir

Signature: _____

Facility Rep

Print: _____ Signature: _____

Notify Facility 24 hrs prior to inspection

Person Notified: _____

Check if Verification only

Moran Environmental Recovery LLC Inspection Sheet

DATE: 6/5/25

Location: MER Yard

Unit #: 6729

BOOM REELS

	Circle				
Grease Chain	YES	NO			
Grease Fittings	YES	NO			
Inspect sprocket	YES	NO			
Check Oil level in motor	YES	NO			
Reel clear of debris and grass	YES	NO			
Run motor	YES	NO			
Hand Brake operational	YES	NO			
Boom Reel cover secure	YES	NO			
*** 1000ft of 18" containment boom (Verify Quanti	YES	NO			
Condition of Boom Reel Cover			Excellent	Good	Fair
Condition of Boom Reel			Excellent	Good	Fair

*** See Boom condition Report for updated Boom Condition

Trailer #: 6729

Tag & Exp: YH 6242 Perm Tag

DOT Inspection: NOV. 24

Insurance: X

Tire Pressure: X

Wheels/Lugs: X

Brakes: X

Axle Hubs: X

Trailer Lights: X

Trailer Jack: X

Trailer Frame: X

Hydraulics: X

Inspector: Shawn Smith Signature: [Signature]

Facility Rep Print: _____ Signature: _____

Notify Facility 24 hrs prior to inspection

Person Notified: _____

Check if Verification only

Moran Environmental Recovery LLC Inspection Sheet

DATE: 6/13/25

LOCATION: _____ MER Yard _____

INSIDE CONTAINER

		Circle one	
	Verified:	YES NO	Comments
6- 26lb Anchors with chain	Verified:	YES NO	<u>Absorbent Boom</u>
4- Buoys with 2 shackles each	Verified:	YES NO	<u>Absorbent Pads</u>
2 spools of line	Verified:	YES NO	_____
2000' 18" containment boom (verification of)	Verified:	YES NO	_____
4 Bundles absorbent pads	Verified:	YES NO	_____
4- Bundles absorbent boom	Verified:	YES NO	_____
1- Roll trash bags	Verified:	YES NO	_____
1- Pair pliers	Verified:	YES NO	_____
1- First Aid Kit	Verified:	YES NO	_____
1-Eye Wash	Verified:	YES NO	_____

OUTSIDE CONTAINER

Box number 7

Container accessible Verified: YES NO _____

Seal in place Verified: YES NO _____

Seal number _____

Container Temp Hi _____ Lo _____ Date: _____

Inspector:
Print: Shawn Smith

Signature: _____

Facility Rep
Print: _____

Signature: _____

Notify Facility 24 hrs prior to inspection

Person Notified: _____

Check if Verification only

Moran Environmental Recovery LLC Inspection Sheet

DATE: 6/3/25

LOCATION: _____

INSIDE CONTAINER

		Circle one	
6- 26lb Anchors with chain	Verified: YES	NO	_____
4- Buoys with 2 shackles each	Verified: YES	NO	<u>nets</u>
2 spools of line	Verified: YES	NO	<u>props</u>
2000' 18" containment boom (verification of)	Verified: YES	NO	<u>misc. Equipment</u>
4 Bundles absorbent pads	Verified: YES	NO	_____
4- Bundles absorbent boom	Verified: YES	NO	_____
1- Roll trash bags	Verified: YES	NO	_____
1- Pair pliers	Verified: YES	NO	_____
1- First Aid Kit	Verified: YES	NO	_____
1-Eye Wash	Verified: YES	NO	_____

OUTSIDE CONTAINER

Box number 10

Container accessible Verified: YES NO _____

Seal in place Verified: YES NO _____

Seal number _____

Container Temp Hi _____ Lo _____ Date: _____

Inspector: Shawn Smith
Print: _____

Signature: _____

Facility Rep
Print: _____

Signature: _____

Notify Facility 24 hrs prior to inspection

Person Notified: _____

Check if Verification only

Moran Environmental Recovery LLC Inspection Sheet

DATE: 6/3/25

LOCATION: _____ MER Yard _____

INSIDE CONTAINER

		Circle one	
6- 26lb Anchors with chain	Verified:	<u>YES</u> NO	_____
4- Buoys with 2 shackles each	Verified:	<u>YES</u> NO	_____
2 spools of line	Verified:	<u>YES</u> NO	_____
2000' 18" containment boom (verification of)	Verified:	<u>YES</u> NO	_____
4 Bundles absorbent pads	Verified:	<u>YES</u> NO	_____
4- Bundles absorbent boom	Verified:	<u>YES</u> NO	_____
1- Roll trash bags	Verified:	<u>YES</u> NO	_____
1- Pair pliers	Verified:	<u>YES</u> NO	_____
1- First Aid Kit	Verified:	<u>YES</u> NO	_____
1-Eye Wash	Verified:	<u>YES</u> NO	_____

OUTSIDE CONTAINER

Box number 9

Container accessible _____ Verified: YES NO _____

Seal in place _____ Verified: YES NO _____

Seal number _____

Container Temp Hi _____ Lo _____ Date: _____

Inspector:
Print: Shawn Smith

Signature: [Handwritten Signature]

Facility Rep
Print: _____

Signature: _____

Notify Facility 24 hrs prior to inspection

Person Notified: _____

Check if Verification only

Moran Environmental Recovery LLC Inspection Sheet

DATE: 6/3/25

LOCATION: MER YARD

JON BOATS AND MOTORS

BOATS

Unit 853	14' Boat	G3 1436	GEN6849JG900	Circle: Excelent	<u>Good</u>	Fair	Poor
G3 1438		GEN61758G708		Circle: Excelent	<u>Good</u>	Fair	Poor
Express		JBC21426B595		Circle: Excelent	<u>Good</u>	Fair	Poor
G3 1444		GEN 36264H506		Circle: Excelent	<u>Good</u>	Fair	Poor
Lowe L1436L		LWCJ2227F506		Circle: Excelent	<u>Good</u>	Fair	Poor

MOTORS

Yamaha 9.9	559	Mod#F9.95MHA SN# GAUKS1024920	Circle: Excelent	<u>Good</u>	Fair	Poor
			Last Run Date:	<u>6/3/25</u>		
			Comments:			
Yamaha 9.9	558	Mod # F9.95MHA SN# GAUKS1028386	Circle: Excelent	Good	<u>Fair</u>	Poor
			Last Run Date:	<u>6/3/25</u>		
			Comments:	<u>OUT FOR SERVICE</u>		
Yamaha 9.9	560	Mod# F9.9MHB SN# GAUKS1030921	Circle: Excelent	<u>Good</u>	Fair	Poor
			Last Run Date:	<u>6/3/25</u>		
			Comments:			
Yamaha 15		Mod# F15SMHA SN# 6AGKS1063676	Circle: Excelent	<u>Good</u>	Fair	Poor
			Last Run Date:	<u>6/3/25</u>		
			Comments:			
Yamaha 15		Mod# F15SEHA SN# 6AGKS1062763	Circle: Excelent	<u>Good</u>	Fair	Poor
			Last Run Date:	<u>6/3/25</u>		
			Comments:			

Inspector: Shawn Smith
Print: _____

Signature: _____

Check if Verification only

Moran Environmental Recovery LLC Inspection Sheet

DATE: 6/3/25

LOCATION: MER

Trailer # 6188

Trailer Serial # _____

Date Placed in Service: _____

	Verified:	Circle one		Comments
		YES	NO	
4- 26lb Anchors with chain	Verified:	YES	NO	_____
4- Buoys with 2 shackels each	Verified:	YES	NO	_____
4- Long lines	Verified:	YES	NO	_____
4- Short lines	Verified:	YES	NO	_____
*** 1000' 18" containment boom (Verify Qua	Verified:	YES	NO	<u>Power packs</u>
4 Bundles absorbent pads	Verified:	YES	NO	<u>Skimmers</u>
4- Bundles absorbent boom	Verified:	YES	NO	_____
1- Roll trash bags	Verified:	YES	NO	_____
2- Life jackets	Verified:	YES	NO	_____
1- Pair pliers	Verified:	YES	NO	_____
1- Skimmer 1800 SH	Verified:	YES	NO	_____
1- First Aid Kit	Verified:	YES	NO	_____
1-EyeWash	Verified:	YES	NO	_____

*** See Boom Condition Report for updated Boom Condition

Comments on above Inventory: _____

OUTSIDE OF TRAILER

Tag in place and current	Tag#	Circle		Comments
		YES	NO	
Washed/Clean		<u>YES</u>	NO	_____
Lights operational		<u>YES</u>	NO	_____
Trailer tongue greased		<u>YES</u>	NO	_____
Trailer number visible		<u>YES</u>	NO	_____
Trailer moved and brakes working		<u>YES</u>	NO	_____
Tire pressure ok		<u>YES</u>	NO	_____
Tire tread ok		<u>YES</u>	NO	_____
Hubs, lugs, and rims ok (need to be grea		<u>YES</u>	NO	_____
Doors and hinges operating properly		<u>YES</u>	NO	_____
Locks on doors (trailer secured)		<u>YES</u>	NO	_____
Condition of Trailer		Excellent	<u>Good</u>	Fair Poor

Comments on above items _____

Inspector: Shawn Smith

Signature: _____

Facility Rep
 Print: _____

Signature: _____

Notify Facility 24 hrs prior to inspection

Person Notified: _____

Check if Verification only

Moran Environmental Recovery LLC Inspection Sheet

DATE: 6/3/25

LOCATION: MER

Trailer # 6186 Trailer Serial #53FBE2421KF050875 Date Placed in Service: _____

		Circle one		
4- 26lb Anchors with chain	Verified:	<input checked="" type="radio"/> YES	NO	_____
4- Buoys with 2 shackles each	Verified:	<input checked="" type="radio"/> YES	NO	_____
4- Long lines	Verified:	<input checked="" type="radio"/> YES	NO	_____
4- Short lines	Verified:	<input checked="" type="radio"/> YES	NO	_____
*** 1000' 18" containment boom (Verify Qua	Verified:	<input checked="" type="radio"/> YES	NO	_____
4 Bundles absorbent pads	Verified:	<input checked="" type="radio"/> YES	NO	_____
4- Bundles absorbent boom	Verified:	<input checked="" type="radio"/> YES	NO	_____
1- Roll trash bags	Verified:	<input checked="" type="radio"/> YES	NO	_____
2- Life jackets	Verified:	<input checked="" type="radio"/> YES	NO	_____
1- Pair pliers	Verified:	<input checked="" type="radio"/> YES	NO	_____
1- Skimmer 1800 SH	Verified:	<input checked="" type="radio"/> YES	NO	_____
1- First Aid Kit	Verified:	<input checked="" type="radio"/> YES	NO	_____
1-EyeWash	Verified:	<input checked="" type="radio"/> YES	NO	_____

*** See Boom Condition Report for updated Boom Conditi

Comments on above Inventory: _____

OUTSIDE OF TRAILER

		Circle		
Tag in place and current	Tag#	<u>TT 25 MS 7</u>		_____
Washed/Clean		<input checked="" type="radio"/> YES	NO	_____
Lights operational		<input checked="" type="radio"/> YES	NO	_____
Trailer tounge greased		<input checked="" type="radio"/> YES	NO	_____
Trailer number visible		<input checked="" type="radio"/> YES	NO	_____
Trailer moved and brakes working		<input checked="" type="radio"/> YES	NO	_____
Tire pressure ok		<input checked="" type="radio"/> YES	NO	_____
Tire tread ok		<input checked="" type="radio"/> YES	NO	_____
Hubs, lugs, and rims ok (need to be grea		<input checked="" type="radio"/> YES	NO	_____
Doors and hinges operating properly		<input checked="" type="radio"/> YES	NO	_____
Locks on doors (trailer secured)		<input checked="" type="radio"/> YES	NO	_____

Condition of Trailer Excellent Good Fair Poor

Comments on above items _____

Inspector:
Print: Shawn Smith

Signature: _____

Facility Rep
Print: _____

Signature: _____

Notify Facility 24 hrs prior to inspection

Person Notified: _____

Check if Verification only

Moran Environmental Recovery LLC Inspection Sheet

DATE: 6/3/25

LOCATION: MER

Trailer # 6189 Trailer Serial #53FBE2426KF050872 Date Placed in Service:

		Circle one		Comments
4- 26lb Anchors with chain	Verified:	<input checked="" type="radio"/> YES	<input type="radio"/> NO	_____
4- Buoys with 2 shackles each	Verified:	<input checked="" type="radio"/> YES	<input type="radio"/> NO	_____
4- Long lines	Verified:	<input checked="" type="radio"/> YES	<input type="radio"/> NO	_____
4- Short lines	Verified:	<input checked="" type="radio"/> YES	<input type="radio"/> NO	_____
*** 1000' 18" containment boom (Verify Qua	Verified:	<input checked="" type="radio"/> YES	<input type="radio"/> NO	_____
4 Bundles absorbent pads	Verified:	<input checked="" type="radio"/> YES	<input type="radio"/> NO	_____
4- Bundles absorbent boom	Verified:	<input checked="" type="radio"/> YES	<input type="radio"/> NO	_____
1- Roll trash bags	Verified:	<input checked="" type="radio"/> YES	<input type="radio"/> NO	_____
2- Life jackets	Verified:	<input checked="" type="radio"/> YES	<input type="radio"/> NO	_____
1- Pair pliers	Verified:	<input checked="" type="radio"/> YES	<input type="radio"/> NO	_____
1- Skimmer 1800 SH	Verified:	<input checked="" type="radio"/> YES	<input type="radio"/> NO	_____
1- First Aid Kit	Verified:	<input checked="" type="radio"/> YES	<input type="radio"/> NO	_____
1-EyeWash	Verified:	<input checked="" type="radio"/> YES	<input type="radio"/> NO	_____

*** See Boom Condition Report for updated Boom Condition

Comments on above Inventory: _____

OUTSIDE OF TRAILER

		Circle		Comments
Tag in place and current	Tag#	<u>1135</u>	<u>V73</u>	_____
Washed/Clean		<input checked="" type="radio"/> YES	<input type="radio"/> NO	_____
Lights operational		<input checked="" type="radio"/> YES	<input type="radio"/> NO	_____
Trailer tongue greased		<input checked="" type="radio"/> YES	<input type="radio"/> NO	_____
Trailer number visible		<input checked="" type="radio"/> YES	<input type="radio"/> NO	_____
Trailer moved and brakes working		<input checked="" type="radio"/> YES	<input type="radio"/> NO	_____
Tire pressure ok		<input checked="" type="radio"/> YES	<input type="radio"/> NO	_____
Tire tread ok		<input checked="" type="radio"/> YES	<input type="radio"/> NO	_____
Hubs, lugs, and rims ok (need to be grea		<input checked="" type="radio"/> YES	<input type="radio"/> NO	_____
Doors and hinges operating properly		<input checked="" type="radio"/> YES	<input type="radio"/> NO	_____
Locks on doors (trailer secured)		<input checked="" type="radio"/> YES	<input type="radio"/> NO	_____
Condition of Trailer		Excellent	<input checked="" type="radio"/> <u>Good</u>	Fair Poor

Comments on above items _____

Inspector: Shawn Smith
 Print: _____

Signature: _____

Facility Rep
 Print: _____

Signature: _____

Notify Facility 24 hrs prior to inspection

Person Notified: _____

Check if Verification only

Moran Environmental Recovery LLC Inspection Sheet

DATE: 6/3/25

LOCATION: MER

Trailer # 6187

Trailer Serial #

Date Placed in Service:

	Verified:	Circle one	Comments
4- 26lb Anchors with chain	YES	NO	
4- Buoys with 2 shackles each	YES	NO	
4- Long lines	YES	NO	
4- Short lines	YES	NO	
*** 1000' 18" containment boom (Verify Qua	YES	NO	
4 Bundles absorbent pads	YES	NO	
4- Bundles absorbent boom	YES	NO	
1- Roll trash bags	YES	NO	
2- Life jackets	YES	NO	
1- Pair pliers	YES	NO	
1- Skimmer 1800 SH	YES	NO	
1- First Aid Kit	YES	NO	
1-EyeWash	YES	NO	

*** See Boom Condition Report for updated Boom Condition

Comments on above Inventory: _____

OUTSIDE OF TRAILER

Tag in place and current	Tag#	Circle	Comments
Washed/Clean		YES NO	
Lights operational		YES NO	
Trailer tongue greased		YES NO	
Trailer number visible		YES NO	
Trailer moved and brakes working		YES NO	
Tire pressure ok		YES NO	
Tire tread ok		YES NO	
Hubs, lugs, and rims ok (need to be grea		YES NO	
Doors and hinges operating properly		YES NO	
Locks on doors (trailer secured)		YES NO	
Condition of Trailer		Excellent <u>Good</u> Fair Poor	

Comments on above items _____

Inspector: Shawn Smith

Signature: [Signature]

Facility Rep
 Print: _____

Signature: _____

Notify Facility 24 hrs prior to inspection

Person Notified: _____

Check if Verification only

Moran Environmental Recovery LLC Inspection Sheet

Vessel Name: Savannah Patriot

Vessel Make: Custom

Inspection Date: 11/3/25

Unit #: _____

Location: EMTT

Last Months Recorded Hours
Current Months Recorded Hours

1019 1035

Check items (X)

Check items (X)

Visual Hull Inspection

Check fuel level (full)

Check Batteries

Check oil level

Inspect fuel lines

Spark Plug wires

Inspect Bilge

Boat Clean

Operate Bilge pump

Operate for 15 min

No Electronics

*** VESSEL SHOULD GO THROUGH A SEA TRIAL TO INSURE OPERATING AT PEAK PERFORMANCE A MIN OF ONCE PER QUARTER

Trailer #: _____

Inspector:
Print: Shawn Smith

Signature: [Signature]

Facility Rep
Print: Ray BABOT

Signature: [Signature]

Notify Facility 24 hrs prior to inspection

Person Notified: _____

Check if Verification only

Moran Environmental Recovery LLC Inspection Sheet

DATE: 6/3/25

LOCATION: Metro Ports

INSIDE CONTAINER

		Circle one	
6- 26lb Anchors with chain	Verified:	<u>YES</u> NO	
4- Buoys with 2 shackles each	Verified:	<u>YES</u> NO	
2 spools of line	Verified:	<u>YES</u> NO	
2000' 18" containment boom (verification of)	Verified:	<u>YES</u> NO	
4 Bundles absorbent pads	Verified:	<u>YES</u> NO	
4- Bundles absorbent boom	Verified:	<u>YES</u> NO	
1- Roll trash bags	Verified:	<u>YES</u> NO	
1- Pair pliers	Verified:	<u>YES</u> NO	
1- First Aid Kit	Verified:	<u>YES</u> NO	
1-Eye Wash	Verified:	<u>YES</u> NO	

OUTSIDE CONTAINER

Box number 6

Container accessible Verified: YES NO

Seal in place Verified: YES NO

Seal number 020873 020872

Container Temp Hi _____ Lo _____ Date: _____

Inspector: Shawn Smith

Signature: _____

Facility Rep: William Pittman

Signature: _____

Notify Facility 24 hrs prior to inspection

Person Notified: _____

Check if Verification only

Moran Environmental Recovery LLC Inspection Sheet

DATE: 6/3/25

LOCATION: Metro Ports

INSIDE CONTAINER

		Circle one	Comments
6- 26lb Anchors with chain	Verified:	<u>YES</u> NO	_____
4- Buoys with 2 shackles each	Verified:	<u>YES</u> NO	_____
2 spools of line	Verified:	<u>YES</u> NO	_____
2000' 18" containment boom (verification of)	Verified:	<u>YES</u> NO	_____
4 Bundles absorbent pads	Verified:	<u>YES</u> NO	_____
4- Bundles absorbent boom	Verified:	<u>YES</u> NO	_____
1- Roll trash bags	Verified:	<u>YES</u> NO	_____
1- Pair pliers	Verified:	<u>YES</u> NO	_____
1- First Aid Kit	Verified:	<u>YES</u> NO	_____
1-Eye Wash	Verified:	<u>YES</u> NO	_____

OUTSIDE CONTAINER

Box number 5

Container accessible Verified: YES NO _____

Seal in place Verified: YES NO _____

Seal number 020874 020843

Container Temp Hi _____ Lo _____ Date: _____

Inspector:
Print: Shawn Smith

Signature: [Signature]

Facility Rep
Print: Ray BABOT

Signature: [Signature]

Notify Facility 24 hrs prior to inspection

Person Notified: _____

Check if Verification only

Moran Environmental Recovery LLC Inspection Sheet

DATE: 6/3/25

LOCATION: IMTT North

INSIDE CONTAINER

		Circle one	
6- 26lb Anchors with chain	Verified:	<u>YES</u> NO	_____
4- Buoys with 2 shackels each	Verified:	<u>YES</u> NO	_____
2 spools of line	Verified:	<u>YES</u> NO	_____
2000' 18" containment boom (verification of)	Verified:	<u>YES</u> NO	_____
4 Bundles absorbent pads	Verified:	<u>YES</u> NO	_____
4- Bundles absorbent boom	Verified:	<u>YES</u> NO	_____
1- Roll trash bags	Verified:	<u>YES</u> NO	_____
1- Pair pliers	Verified:	<u>YES</u> NO	_____
1- First Aid Kit	Verified:	<u>YES</u> NO	_____
1-Eye Wash	Verified:	<u>YES</u> NO	_____

OUTSIDE CONTAINER

Box number 4

Container accessible Verified: YES NO _____

Seal in place Verified: YES NO _____

Seal number 020821 163710

Container Temp Hi _____ Lo _____ Date: _____

Inspector:
Print: Shawn Smith

Signature: _____

Facility Rep
Print: Roy BABOT

Signature: Roy Babot

Notify Facility 24 hrs prior to inspection

Person Notified: _____

Check if Verification only

Moran Environmental Recovery LLC Inspection Sheet

DATE: 6/3/25

LOCATION: Colonial Terminal

INSIDE CONTAINER

		Circle one	
6- 26lb Anchors with chain	Verified:	<u>YES</u> NO	_____
4- Buoys with 2 shackles each	Verified:	<u>YES</u> NO	_____
2 spools of line	Verified:	<u>YES</u> NO	_____
2000' 18" containment boom (verification of)	Verified:	<u>YES</u> NO	_____
4 Bundles absorbent pads	Verified:	<u>YES</u> NO	_____
4- Bundles absorbent boom	Verified:	<u>YES</u> NO	_____
1- Roll trash bags	Verified:	<u>YES</u> NO	_____
1- Pair pliers	Verified:	<u>YES</u> NO	_____
1- First Aid Kit	Verified:	<u>YES</u> NO	_____
1-Eye Wash	Verified:	<u>YES</u> NO	_____

OUTSIDE CONTAINER

Box number 3

Container accessible Verified: YES NO _____

Seal in place Verified: YES NO _____

Seal number 620803

Container Temp Hi _____ Lo _____ Date: 6/3/2025

Inspector: Shawn Smith

Signature: _____

Facility Rep: Harvel Butcher

Signature: _____ 6/3/2025

Notify Facility 24 hrs prior to inspection

Person Notified: _____

Check if Verification only

Moran Environmental Recovery LLC Inspection Sheet

DATE: 6/3/25

LOCATION: Elba Island

INSIDE CONTAINER

		Circle one	
6- 26lb Anchors with chain	Verified:	<input checked="" type="radio"/> YES NO	_____
4- Buoys with 2 shackles each	Verified:	<input checked="" type="radio"/> YES NO	_____
2 spools of line	Verified:	<input checked="" type="radio"/> YES NO	_____
2000' 18" containment boom (verification of)	Verified:	<input checked="" type="radio"/> YES NO	_____
4 Bundles absorbent pads	Verified:	<input checked="" type="radio"/> YES NO	_____
4- Bundles absorbent boom	Verified:	<input checked="" type="radio"/> YES NO	_____
1- Roll trash bags	Verified:	<input checked="" type="radio"/> YES NO	_____
1- Pair pliers	Verified:	<input checked="" type="radio"/> YES NO	_____
1- First Aid Kit	Verified:	<input checked="" type="radio"/> YES NO	_____
1-Eye Wash	Verified:	<input checked="" type="radio"/> YES NO	_____

OUTSIDE CONTAINER

Box number 2

Container accessible Verified: YES NO _____

Seal in place Verified: YES NO _____

Seal number _____

Container Temp Hi _____ Lo 020845 Date: 1633108

Inspector: Shack Smith
Print: _____

Signature: _____

Facility Rep: Lashuna Bryant
Print: _____

Signature: _____

Notify Facility 24 hrs prior to inspection

Person Notified: _____

Check if Verification only

Moran Environmental Recovery LLC Inspection Sheet

DATE: 6/3/25

LOCATION: Elba Island

INSIDE CONTAINER

		Circle one	
6- 26lb Anchors with chain	Verified:	<u>YES</u> NO	_____
4- Buoys with 2 shackles each	Verified:	<u>YES</u> NO	_____
2 spools of line	Verified:	<u>YES</u> NO	_____
2000' 18" containment boom (verification of)	Verified:	<u>YES</u> NO	_____
4 Bundles absorbent pads	Verified:	<u>YES</u> NO	_____
4- Bundles absorbent boom	Verified:	<u>YES</u> NO	_____
1- Roll trash bags	Verified:	<u>YES</u> NO	_____
1- Pair pliers	Verified:	<u>YES</u> NO	_____
1- First Aid Kit	Verified:	<u>YES</u> NO	_____
1-Eye Wash	Verified:	<u>YES</u> NO	_____

OUTSIDE CONTAINER

Box number 1

Container accessible Verified: YES NO _____

Seal in place Verified: YES NO _____

Seal number 020862

Container Temp Hi _____ Lo _____ Date: _____

Inspector:
Print: Shawn Smith

Signature: [Signature]

Facility Rep
Print: Lashuna Bryant

Signature: [Signature]

Notify Facility 24 hrs prior to inspection

Person Notified: _____

Check if Verification only

Moran Environmental Recovery LLC Inspection Sheet

Vessel Name: Al Allen

Vessel Make: Lobelle

Inspection Date: 6/2/25

Unit #: 862

Location: MER Yard

Last Months Recorded Hours 221.3
Current Months Recorded Hours _____

Check items (X)

- Visual Hull Inspection
- Check Batteries
- Inspect fuel lines
- Inspect Bilge
- Operate Bilge pump
- GPS /VHF Working

Check items (X)

- Check fuel level (full)
- Check oil level
- Spark Plug wires
- Boat Clean
- Operate for 15 min

*** VESSEL SHOULD GO THROUGH A SEA TRIAL TO INSURE OPERATING AT PEAK PERFORMANCE A MIN OF ONCE PER QUARTER

Trailer #: 6094

Inspector:
Print: Shawn Smith

Signature: [Signature]

Facility Rep
Print: Sandra Gomez

Signature: [Signature]

Notify Facility 24 hrs prior to inspection

Person Notified: _____

Check if Verification only

Moran Environmental Recovery LLC Inspection Sheet

DATE: 6/3/25

Location: Phillips 66

Unit #: BR 4

BOOM REELS

	Circle		Comments				
Grease Chain	YES	NO					
Grease Fittings	YES	NO	<u>Boom out of</u>				
Inspect sprocket	YES	NO	<u>Service</u>				
Check Oil level in motor	YES	NO					
Reel clear of debris and grass	YES	NO					
Run motor	YES	NO					
Hand Brake operational	YES	NO					
Boom Reel cover secure	YES	NO					
*** 1000ft of 18" containment boom (Verify Quantiti	YES	NO					
Condition of Boom Reel Cover			<table border="0" style="width: 100%; font-size: small;"> <tr> <td style="width: 25%;">Excellent</td> <td style="width: 25%;">Good</td> <td style="width: 25%;">Fair</td> <td style="width: 25%;">Poor</td> </tr> </table>	Excellent	Good	Fair	Poor
Excellent	Good	Fair	Poor				
Condition of Boom Reel			<table border="0" style="width: 100%; font-size: small;"> <tr> <td style="width: 25%;">Excellent</td> <td style="width: 25%;">Good</td> <td style="width: 25%;">Fair</td> <td style="width: 25%;">Poor</td> </tr> </table>	Excellent	Good	Fair	Poor
Excellent	Good	Fair	Poor				

*** See Boom condition Report for updated Boom Condition

Inspector: Shawn Smith Signature: [Signature]

Facility Rep Sandra Gomez Signature: [Signature]

Notify Facility 24 hrs prior to inspection

Person Notified: _____

Check if Verification only

Moran Environmental Recovery LLC Inspection Sheet

Vessel Name: 34' Barge Boat

Vessel Make: Custom

Inspection Date: 6/3/2025

Unit #: 891

Location: MER Yard

	P	S
Last Months Recorded Hours	<u>74.8</u>	<u>77.8</u>
Current Months Recorded Hours	<u>74.8</u>	<u>77.8</u>

Check items (X)

Visual Hull Inspection

Check Batteries

Inspect fuel lines

Inspect Bilge

Operate Bilge pump

No Electronics

Check items (X)

Check fuel level (full)

Check oil level

Spark Plug wires

Boat Clean

Operate for 15 min

*** VESSEL SHOULD GO THROUGH A SEA TRIAL TO INSURE OPERATING AT PEAK PERFORMANCE A MIN OF ONCE PER QUARTER

Trailer #: 6004

Inspector:

Print: Callaway Bowers

Signature: [Signature]

Facility Rep

Print: _____

Signature: _____

Notify Facility 24 hrs prior to inspection

Person Notified: _____

Check if Verification only

Moran Environmental Recovery LLC Inspection Sheet

Vessel Name: Munson

Vessel Make: Custom

Inspection Date: 6/8/2025

Unit #: 871

Location: MER Yard

Last Months Recorded Hours
Current Months Recorded Hours

P	S
<u>103.7</u>	<u>103.8</u>
<u>103.7</u>	<u>103.8</u>

Check items (X)

Check items (X)

Visual Hull Inspection

Check fuel level (full)

Check Batteries

Check oil level

Inspect fuel lines

Spark Plug wires

Inspect Bilge

Boat Clean

Operate Bilge pump

Operate for 15 min

No Electronics

*** VESSEL SHOULD GO THROUGH A SEA TRIAL TO INSURE OPERATING AT PEAK PERFORMANCE A MIN OF ONCE PER QUARTER

Trailer #: 6651

Inspector:

Print: Callaway Bowers

Signature: [Signature]

Facility Rep

Print: _____

Signature: _____

Notify Facility 24 hrs prior to inspection

Person Notified: _____

Check if Verification only

Moran Environmental Recovery LLC Inspection Sheet

Vessel Name: 17' Work Boat

Vessel Make: Custom

Inspection Date: 6/3/2029

Unit #: 866

Location: MER Yard

Last Months Recorded Hours 170
Current Months Recorded Hours 170

Check items (X)

Visual Hull Inspection

Check Batteries

Inspect fuel lines

Inspect Bilge

Operate Bilge pump

No Electronics

Check items (X)

Check fuel level (full)

Check oil level

Spark Plug wires

Boat Clean

Operate for 15 min

*** VESSEL SHOULD GO THROUGH A SEA TRIAL TO INSURE OPERATING AT PEAK PERFORMANCE A MIN OF ONCE PER QUARTER

Trailer #: 6135

Inspector:

Print: Callaway Bowers

Signature: 

Facility Rep

Print: _____

Signature: _____

Notify Facility 24 hrs prior to inspection

Person Notified: _____

Check if Verification only

Moran Environmental Recovery LLC Inspection Sheet

Vessel Name: Marco Skimmer Vessel Make: 30' Kvichak Skimmer
 Inspection Date: 6/5/25 Unit #: 895
 Location: Savannah, GA Registration #: GA 9056 SC
 Last Months Recorded Hours: 13.7 13.7
 Current Months Recorded Hours: _____

Check items (X)

Visual Hull Inspection
 Check Batteries
 Inspect fuel lines
 Inspect Bilge
 Operate Bilge pump
 No Electronics

Check items (X)

Check fuel level (full)
 Check oil level
 Spark Plug wires
 Boat Clean
 Operate for 15 min
 Insurance

*** VESSEL SHOULD GO THROUGH A SEA TRIAL TO INSURE OPERATING AT PEAK PERFORMANCE A MIN OF ONCE PER QUARTER

Trailer #: 6648 Tag & Exp: T053E28
 DOT Inspection: July 25 Insurance: X
 Tire Pressure: X Wheels/Lugs: X
 Brakes: X Axle Hubs: X
 Trailer Lights: X Trailer Jack: X
 Trailer Frame: X Bunks: X

Inspector: Shawn Smith Signature: _____

Facility Rep: _____ Signature: _____

Notify Facility 24 hrs prior to inspection

Person Notified: _____

Check if Verification only

Moran Environmental Recovery LLC Inspection Sheet

DATE: 6/5/25

LOCATION: Plant McIntosh

INSIDE CONTAINER

		Circle one		Comments
6- 26lb Anchors with chain	Verified:	<input checked="" type="radio"/> YES	NO	_____
4- Buoys with 2 shackles each	Verified:	<input checked="" type="radio"/> YES	NO	_____
2 spools of line	Verified:	<input checked="" type="radio"/> YES	NO	_____
2000' 18" containment boom (verification of)	Verified:	<input checked="" type="radio"/> YES	NO	_____
4 Bundles absorbent pads	Verified:	<input checked="" type="radio"/> YES	NO	_____
4- Bundles absorbent boom	Verified:	<input checked="" type="radio"/> YES	NO	_____
1- Roll trash bags	Verified:	<input checked="" type="radio"/> YES	NO	_____
1- Pair pliers	Verified:	<input checked="" type="radio"/> YES	NO	_____
1- First Aid Kit	Verified:	<input checked="" type="radio"/> YES	NO	_____
1-Eye Wash	Verified:	<input checked="" type="radio"/> YES	NO	_____

OUTSIDE CONTAINER

Box number 8

Container accessible Verified: YES NO _____

Seal in place Verified: YES NO _____

Seal number _____

Container Temp Hi _____ Lo 020880 Date: 020860

Inspector:
Print: Shawn Smith

Signature: _____

Facility Rep
Print: Owen Bryant

Signature: Owen M. Bryant

Notify Facility 24 hrs prior to inspection

Person Notified: _____

Check if Verification only

Moran Environmental Recovery LLC Inspection Sheet

DATE: 6/10/25

LOCATION: MER

Trailer # 6190 Trailer Serial # 53FBE2427KF050878 Date Placed in Service:

		Circle one		Comments
4- 26lb Anchors with chain	Verified:	<u>YES</u>	NO	_____
4- Buoys with 2 shackels each	Verified:	<u>YES</u>	NO	_____
4- Long lines	Verified:	<u>YES</u>	NO	_____
4- Short lines	Verified:	<u>YES</u>	NO	_____
*** 1000' 18" containment boom (Verify Quali	Verified:	<u>YES</u>	NO	_____
4 Bundles absorbent pads	Verified:	<u>YES</u>	NO	_____
4- Bundles absorbent boom	Verified:	<u>YES</u>	NO	_____
1- Roll trash bags	Verified:	<u>YES</u>	NO	_____
2- Life jackets	Verified:	<u>YES</u>	NO	_____
1- Pair pliers	Verified:	<u>YES</u>	NO	_____
1- Skimmer 1800 SH	Verified:	<u>YES</u>	NO	_____
1- First Aid Kit	Verified:	<u>YES</u>	NO	_____
1-EyeWash	Verified:	<u>YES</u>	NO	_____

*** See Boom Condition Report for updated Boom Condition

Comments on above Inventory: _____

OUTSIDE OF TRAILER

		Circle		Comments
Tag in place and current	Tag#	<u>TT25MS6</u>		_____
Washed/Clean		<u>YES</u>	NO	_____
Lights operational		<u>YES</u>	NO	_____
Trailer tounge greased		<u>YES</u>	NO	_____
Trailer number visible		<u>YES</u>	NO	_____
Trailer moved and brakes working		<u>YES</u>	NO	_____
Tire pressure ok		<u>YES</u>	NO	_____
Tire tread ok		<u>YES</u>	NO	_____
Hubs, lugs, and rims ok (need to be grea		<u>YES</u>	NO	_____
Doors and hinges operating properly		<u>YES</u>	NO	_____
Locks on doors (trailer secured)		<u>YES</u>	NO	_____
Condition of Trailer			Excellent <u>Good</u> Fair Poor	

Comments on above items _____

Inspector: Shawn Smith
 Print: _____

Signature: _____

Facility Rep: Jessica Jager
 Print: _____

Signature: _____

Notify Facility 24 hrs prior to inspection

Person Notified: _____

Check if Verification only

Moran Environmental Recovery LLC Inspection Sheet

DATE: _____ LOCATION: VOPAK

Trailer # 6017 Trailer Serial # 4X4TSEZ253U202767 Date Placed in Service: 2003

		Circle one		Comments
4- 26lb Anchors with chain	Verified:	YES	NO	_____
4- Buoys with 2 shackles each	Verified:	YES	NO	_____
4- Long lines	Verified:	YES	NO	_____
4- Short lines	Verified:	YES	NO	_____
*** 1000' 18" containment boom (Verify Qua	Verified:	YES	NO	_____
4 Bundles absorbent pads	Verified:	YES	NO	_____
4- Bundles absorbent boom	Verified:	YES	NO	_____
1- Roll trash bags	Verified:	YES	NO	_____
2- Life jackets	Verified:	YES	NO	_____
1- Pair pliers	Verified:	YES	NO	_____
1- Skimmer 1800 SH	Verified:	YES	NO	_____
1- First Aid Kit	Verified:	YES	NO	_____
1-EyeWash	Verified:	YES	NO	_____

*** See Boom Condition Report for updated Boom Condition

Comments on above Inventory: _____

OUTSIDE OF TRAILER

	Tag#	Circle		Comments
Tag in place and current				_____
Washed/Clean		YES	NO	_____
Lights operational		YES	NO	_____
Trailer tounge greased		YES	NO	_____
Trailer number visible		YES	NO	_____
Trailer moved and brakes working		YES	NO	_____
Tire pressure ok		YES	NO	_____
Tire tread ok		YES	NO	_____
Hubs, lugs, and rims ok (need to be grea		YES	NO	_____
Doors and hinges operating properly		YES	NO	_____
Locks on doors (trailer secured)		YES	NO	_____

Condition of Trailer _____
 Excellent Good Fair Poor

Comments on above items _____

Inspector:
 Print: _____ Signature: _____

Facility Rep
 Print: _____ Signature: _____

Notify Facility 24 hrs prior to inspection

Person Notified: _____

Check if Verification only

Moran Environmental Recovery LLC Inspection Sheet

DATE: _____

Location: Imperial Sugar

Unit #: BR 5

BOOM REELS

Circle

Comments

Grease Chain	YES	NO					
Grease Fittings	YES	NO					
Inspect sprocket	YES	NO					
Check Oil level in motor	YES	NO					
Reel clear of debris and grass	YES	NO					
Run motor	YES	NO					
Hand Brake operational	YES	NO					
Boom Reel cover secure	YES	NO					
*** 1000ft of 18" containment boom (Verify Quantil	YES	NO					
Condition of Boom Reel Cover			<table border="0" style="margin: auto;"> <tr> <td style="padding: 0 10px;">Excellent</td> <td style="padding: 0 10px;">Good</td> <td style="padding: 0 10px;">Fair</td> <td style="padding: 0 10px;">Poor</td> </tr> </table>	Excellent	Good	Fair	Poor
Excellent	Good	Fair	Poor				
Condition of Boom Reel			<table border="0" style="margin: auto;"> <tr> <td style="padding: 0 10px;">Excellent</td> <td style="padding: 0 10px;">Good</td> <td style="padding: 0 10px;">Fair</td> <td style="padding: 0 10px;">Poor</td> </tr> </table>	Excellent	Good	Fair	Poor
Excellent	Good	Fair	Poor				

*** See Boom condition Report for updated Boom Condition

Inspector:

Print: _____ Signature: _____

Facility Rep

Print: _____ Signature: _____

Notify Facility 24 hrs prior to inspection

Person Notified: _____

Check if Verification only

Moran Environmental Recovery LLC Inspection Sheet

DATE: _____

Location: Ocean Terminal

Unit #: BR 1

BOOM REELS

	Circle		Comments				
Grease Chain	YES	NO	_____				
Grease Fittings	YES	NO	_____				
Inspect sprocket	YES	NO	_____				
Check Oil level in motor	YES	NO	_____				
Reel clear of debris and grass	YES	NO	_____				
Run motor	YES	NO	_____				
Hand Brake operational	YES	NO	_____				
Boom Reel cover secure	YES	NO	_____				
*** 1000ft of 18" containment boom (Verify Quantii	YES	NO	_____				
Condition of Boom Reel Cover			<table border="1" style="display: inline-table; border-collapse: collapse;"> <tr> <td style="padding: 2px;">Excellent</td> <td style="padding: 2px;">Good</td> <td style="padding: 2px;">Fair</td> <td style="padding: 2px;">Poor</td> </tr> </table>	Excellent	Good	Fair	Poor
Excellent	Good	Fair	Poor				
Condition of Boom Reel			<table border="1" style="display: inline-table; border-collapse: collapse;"> <tr> <td style="padding: 2px;">Excellent</td> <td style="padding: 2px;">Good</td> <td style="padding: 2px;">Fair</td> <td style="padding: 2px;">Poor</td> </tr> </table>	Excellent	Good	Fair	Poor
Excellent	Good	Fair	Poor				

*** See Boom condition Report for updated Boom Condition

Inspector:

Print: _____ Signature: _____

Facility Rep

Print: _____ Signature: _____

Notify Facility 24 hrs prior to inspection

Check if Verification only

Person Notified: _____