

Moran Environmental Recovery LLC Inspection Sheet

DATE: 7/7/25

LOCATION: MER YARD

TOWABLE BLADDER

	Circle one		Comments
BLADDER #1 Abasco Towable 1000gal Stored in place at MER Yard Deployed and tested	Verified: <u>YES</u>	NO	_____
	Verified: YES	<u>NO</u>	_____

BLADDER #2 Abaso Towable 1000gal Stored in place at MER Yard Deployed and tested	Verified: <u>YES</u>	NO	_____
	Verified: YES	<u>NO</u>	_____

BLADDER #3 Abaso Towable 1000gal Stored in place at MER Yard Deployed and tested			_____

Inspector:
Print: Shane Smith

Signature: [Signature]

Facility Rep
Print: _____

Signature: _____

Notify Facility 24 hrs prior to inspection
Person Notified: _____

Check if Verification only

Moran Environmental Recovery LLC Inspection Sheet

Vessel Name: Al Allen

Vessel Make: Lobelle

Inspection Date: 7/7/25

Unit #: 862

Location: MER-Yard- Philipstide

Last Months Recorded Hours _____
Current Months Recorded Hours 221.3

Check items (X)

Check items (X)

Visual Hull Inspection

Check fuel level (full)

Check Batteries

Check oil level

Inspect fuel lines

Skimmer Pads

Inspect Bilge

Backing belt and pins

Operate Bilge pump

Boat Clean

GPS /VHF Working

Operate PP and engines

*** VESSEL SHOULD GO THROUGH A SEA TRIAL TO INSURE OPERATING AT PEAK PERFORMANCE A MIN OF ONCE PER QUARTER

Trailer #: 6094

Inspector:

Print: Shawn Smith

Signature: [Signature]

Facility Rep

Print: Danah Coates

Signature: [Signature]

Notify Facility 24 hrs prior to inspection

Person Notified: _____

Check if Verification only

Moran Environmental Recovery LLC Inspection Sheet

Vessel Name: Porpoise

Vessel Make: Custom

Inspection Date: 7/7/25

Unit #: 835

Location: Phillips 66 SNF

Last Months Recorded Hours _____
Current Months Recorded Hours _____

Check items (X)

Check items (X)

- | | |
|---|--|
| <input type="checkbox"/> Visual Hull Inspection | <input type="checkbox"/> Check fuel level (full) |
| <input type="checkbox"/> Check Batteries | <input type="checkbox"/> Check oil level |
| <input type="checkbox"/> Inspect fuel lines | <input type="checkbox"/> Skimmer Pads |
| <input type="checkbox"/> Inspect Bilge | <input type="checkbox"/> Backing belt and pins |
| <input type="checkbox"/> Operate Bilge pump | <input type="checkbox"/> Boat Clean |
| <input type="checkbox"/> No Electronics | <input type="checkbox"/> Operate PP and engines |

*** VESSEL SHOULD GO THROUGH A SEA TRIAL TO INSURE OPERATING AT PEAK PERFORMANCE A MIN OF ONCE PER QUARTER

OUT OF SERVICE

Trailer #: 6042

Inspector:
Print: Mark Smith

Signature: [Signature]

Facility Rep
Print: _____

Signature: _____

Notify Facility 24 hrs prior to inspection

Person Notified: _____

Check if Verification only

Moran Environmental Recovery LLC Inspection Sheet

Vessel Name: 34' Barge Boat

Vessel Make: Custom

Inspection Date: 7/27/25

Unit #: 891

Location: MED YARD

Last Months Recorded Hours
Current Months Recorded Hours

P S
74.8 77.8

Check items (X)

Check items (X)

Visual Hull Inspection

Check fuel level (full)

Check Batteries

Check oil level

Inspect fuel lines

Skimmer Pads

Inspect Bilge

Backing belt and pins

Operate Bilge pump

Boat Clean

No Electronics

Operate PP and engines

*** VESSEL SHOULD GO THROUGH A SEA TRIAL TO INSURE OPERATING AT PEAK PERFORMANCE A MIN OF ONCE PER QUARTER

Trailer #: _____

Inspector:
Print: Shawn Smith

Signature: [Signature]

Facility Rep
Print: _____

Signature: _____

Notify Facility 24 hrs prior to inspection

Person Notified: _____

Check if Verification only

Moran Environmental Recovery LLC Inspection Sheet

Vessel Name: Munson

Vessel Make: Custom

Inspection Date: 7/7/25

Unit #: 871

Location: MEOR Yard

Last Months Recorded Hours P
Current Months Recorded Hours 106 S 106.

Check items (X)

Check items (X)

- Visual Hull Inspection
- Check Batteries
- Inspect fuel lines
- Inspect Bilge
- Operate Bilge pump
- No Electronics

- Check fuel level (full)
- Check oil level
- Inspect Bidge
- Backing belt and pins
- Boat Clean
-

*** VESSEL SHOULD GO THROUGH A SEA TRIAL TO INSURE OPERATING AT PEAK PERFORMANCE A MIN OF ONCE PER QUARTER

Trailer #: _____

Inspector:
Print: Shawn Smith

Signature: [Signature]

Facility Rep
Print: _____

Signature: _____

Notify Facility 24 hrs prior to inspection

Person Notified: _____

Check if Verification only

Moran Environmental Recovery LLC Inspection Sheet

Vessel Name: Marco Skimmer

Vessel Make: 30' Kvichak Skimmer

Inspection Date: 7/7/25

Unit #: 895

Location: Savannah, GA

Last Months Recorded Hours
Current Months Recorded Hours

P S
13.7 13.7

Check items (X)

Check items (X)

Visual Hull Inspection

Check fuel level (full)

Check Batteries

Check oil level

Inspect fuel lines

Skimmer Pads

Inspect Bilge

Backing belt and pins

Operate Bilge pump

Boat Clean

No Electronics

Operate PP and engines

*** VESSEL SHOULD GO THROUGH A SEA TRIAL TO INSURE OPERATING AT PEAK PERFORMANCE A MIN OF ONCE PER QUARTER

Trailer #: _____

Inspector:
Print: Shawn Smith

Signature: [Signature]

Facility Rep
Print: _____

Signature: _____

Notify Facility 24 hrs prior to inspection

Person Notified: _____

Check if Verification only

Moran Environmental Recovery LLC Inspection Sheet

Vessel Name: Savannah Patriot

Vessel Make: Custom

Inspection Date: 7/7/25

Unit #: 865

Location: Colonial Foundation

Last Months Recorded Hours
Current Months Recorded Hours

P S
1016 1037

Check items (X)

Check items (X)

Visual Hull Inspection

Check fuel level (full)

Check Batteries

Check oil level

Inspect fuel lines

Skimmer Pads

Inspect Bilge

Backing belt and pins

Operate Bilge pump

Boat Clean

No Electronics

Operate PP and engines

*** VESSEL SHOULD GO THROUGH A SEA TRIAL TO INSURE OPERATING AT PEAK PERFORMANCE A MIN OF ONCE PER QUARTER

Trailer #: _____

Inspector:
Print: Shawn Smith

Signature: _____

Facility Rep
Print: Roy BABOT

Signature: _____

Notify Facility 24 hrs prior to inspection

Person Notified: _____

Check if Verification only

Moran Environmental Recovery LLC Inspection Sheet

DATE: 7/7/25

LOCATION: Colonial Foundation

INSIDE CONTAINER

		Circle one		Comments
6- 26lb Anchors with chain	Verified:	<u>YES</u>	NO	_____
4- Buoys with 2 shackles each	Verified:	<u>YES</u>	NO	_____
2 spools of line	Verified:	<u>YES</u>	NO	_____
2000' 18" containment boom (verification of)	Verified:	<u>YES</u>	NO	_____
4 Bundles absorbent pads	Verified:	<u>YES</u>	NO	_____
4- Bundles absorbent boom	Verified:	<u>YES</u>	NO	_____
1- Roll trash bags	Verified:	<u>YES</u>	NO	_____
1- Pair pliers	Verified:	<u>YES</u>	NO	_____
1- First Aid Kit	Verified:	<u>YES</u>	NO	_____
1-Eye Wash	Verified:	<u>YES</u>	NO	_____

OUTSIDE CONTAINER

Box number 5

Container accessible Verified: YES NO 020874

Seal in place Verified: YES NO 020863

Seal number _____

Container Temp Hi _____ Lo _____ Date: _____

Inspector: Shawn Smyke
Print: _____

Signature: [Signature]

Facility Rep: Ron BARD
Print: _____

Signature: [Signature]

Notify Facility 24 hrs prior to inspection

Person Notified: _____

Verification only

Moran Environmental Recovery LLC Inspection Sheet

DATE: 7/7/25

LOCATION: Colonial Foundation

INSIDE CONTAINER

		Circle one	
6- 26lb Anchors with chain	Verified:	<u>YES</u> NO	_____
4- Buoys with 2 shackles each	Verified:	<u>YES</u> NO	_____
2 spools of line	Verified:	<u>YES</u> NO	_____
2000' 18" containment boom (verification of)	Verified:	<u>YES</u> NO	_____
4 Bundles absorbent pads	Verified:	<u>YES</u> NO	_____
4- Bundles absorbent boom	Verified:	<u>YES</u> NO	_____
1- Roll trash bags	Verified:	<u>YES</u> NO	_____
1- Pair pliers	Verified:	<u>YES</u> NO	_____
1- First Aid Kit	Verified:	<u>YES</u> NO	_____
1-Eye Wash	Verified:	<u>YES</u> NO	_____

OUTSIDE CONTAINER

Box number 4
 Container accessible Verified: YES NO 026821
 Seal in place Verified: YES NO 143710
 Seal number _____
 Container Temp Hi _____ Lo _____ Date: _____

Inspector: Shawn Smith
 Print: _____

Signature: _____

Facility Rep: Ray BABOT
 Print: _____

Signature: Ray Babot

Notify Facility 24 hrs prior to inspection

Person Notified: _____

Verification only

Moran Environmental Recovery LLC Inspection Sheet

DATE: 7/7/25

LOCATION: MER

Trailer # 6190 Trailer Serial # 53FBE2427KF050878 Date Placed in Service: _____

	Circle one	Comments
4- 26lb Anchors with chain	Verified: <input checked="" type="radio"/> YES <input type="radio"/> NO	_____
4- Buoys with 2 shackels each	Verified: <input checked="" type="radio"/> YES <input type="radio"/> NO	_____
4- Long lines	Verified: <input checked="" type="radio"/> YES <input type="radio"/> NO	_____
4- Short lines	Verified: <input checked="" type="radio"/> YES <input type="radio"/> NO	_____
** 1000' 18" containment boom (Verify Qua	Verified: <input checked="" type="radio"/> YES <input type="radio"/> NO	_____
4 Bundles absorbent pads	Verified: <input checked="" type="radio"/> YES <input type="radio"/> NO	_____
4- Bundles absorbent boom	Verified: <input checked="" type="radio"/> YES <input type="radio"/> NO	_____
1- Roll trash bags	Verified: <input checked="" type="radio"/> YES <input type="radio"/> NO	_____
2- Life jackets	Verified: <input checked="" type="radio"/> YES <input type="radio"/> NO	_____
1- Pair pliers	Verified: <input checked="" type="radio"/> YES <input type="radio"/> NO	_____
1- Skimmer 1800 SH	Verified: <input checked="" type="radio"/> YES <input type="radio"/> NO	_____
1- First Aid Kit	Verified: <input checked="" type="radio"/> YES <input type="radio"/> NO	_____
1-EyeWash	Verified: <input checked="" type="radio"/> YES <input type="radio"/> NO	_____

*** See Boom Condition Report for updated Boom Condition

Comments on above Inventory: _____

OUTSIDE OF TRAILER

Tag in place and current	Tag#	Circle	Comments
Washed/Clean		<input checked="" type="radio"/> YES <input type="radio"/> NO	<u>sticker expires this month</u>
Lights operational		<input checked="" type="radio"/> YES <input type="radio"/> NO	
Trailer tounge greased		<input checked="" type="radio"/> YES <input type="radio"/> NO	
Trailer number visible		<input checked="" type="radio"/> YES <input type="radio"/> NO	
Trailer moved and brakes working		<input checked="" type="radio"/> YES <input type="radio"/> NO	
Tire pressure ok		<input checked="" type="radio"/> YES <input type="radio"/> NO	
Tire tread ok		<input checked="" type="radio"/> YES <input type="radio"/> NO	
Hubs, lugs, and rims ok (need to be grea		<input checked="" type="radio"/> YES <input type="radio"/> NO	
Doors and hinges operating properly		<input checked="" type="radio"/> YES <input type="radio"/> NO	
Locks on doors (trailer secured)		<input checked="" type="radio"/> YES <input type="radio"/> NO	
Condition of Trailer		Excellent <input checked="" type="radio"/> Good <input type="radio"/> Fair <input type="radio"/> Poor	

TT 25M56

Comments on above items _____

Inspector: Josiah Strickland
 Print: _____
 Facility Rep
 Print: _____

Signature: Josiah Strickland
 Signature: _____

Notify Facility 24 hrs prior to inspection

Person Notified: _____

Check if Verification only

Moran Environmental Recovery LLC Inspection Sheet

Vessel Name: 17' Work Boat Vessel Make: Custom
Inspection Date: 7/7/25 Unit #: 866
Location: SNF

Last Months Recorded Hours _____
Current Months Recorded Hours 171

Check items (X)		Check items (X)	
<input checked="" type="checkbox"/>	Visual Hull Inspection	<input checked="" type="checkbox"/>	Check fuel level (full)
<input checked="" type="checkbox"/>	Check Batteries	<input checked="" type="checkbox"/>	Check oil level
<input checked="" type="checkbox"/>	Inspect fuel lines	<input checked="" type="checkbox"/>	Inspect bilge
<input checked="" type="checkbox"/>	Inspect Bilge	<input checked="" type="checkbox"/>	Spark Plug Wires
<input checked="" type="checkbox"/>	Operate Bilge pump	<input checked="" type="checkbox"/>	Boat Clean
<input checked="" type="checkbox"/>	Electronics	<input type="checkbox"/>	

*** VESSEL SHOULD GO THROUGH A SEA TRIAL TO INSURE OPERATING AT PEAK PERFORMANCE A MIN OF ONCE PER QUARTER

Trailer #: 6135

Inspector: Joshua Strickland
Print: _____

Signature: Joshua Strickland

Facility Rep _____
Print: _____

Signature: _____

Notify Facility 24 hrs prior to inspection

Person Notified: _____

Check if Verification only

Moran Environmental Recovery LLC Inspection Sheet

DATE: 7/7/23

Location: Phillips 66

Unit #: BR 4

BOOM REELS

	Circle	YES	NO	Comments
Grease Chain	YES		NO	<u>Out of Service</u>
Grease Fittings	YES		NO	
Inspect sprocket	YES		NO	
Check Oil level in motor	YES		NO	
Reel clear of debris and grass	YES		NO	
Run motor	YES		NO	
Hand Brake operational	YES		NO	
Boom Reel cover secure	YES		NO	
*** 1000ft of 18" containment boom (Verify Quanti	YES		NO	
Condition of Boom Reel Cover				Excellent Good Fair Poor
Condition of Boom Reel				Excellent Good Fair Poor

*** See Boom condition Report for updated Boom Condition

Inspector: Shawn Smith Signature: [Signature]

Facility Rep
Print: _____ Signature: _____

Notify Facility 24 hrs prior to inspection

Person Notified: _____

Check if Verification only

Moran Environmental Recovery LLC Inspection Sheet

DATE: 7/7/25

LOCATION: Elba Island

INSIDE CONTAINER

		Circle one		Comments
6- 26lb Anchors with chain	Verified:	<u>YES</u>	NO	_____
4- Buoys with 2 shackles each	Verified:	<u>YES</u>	NO	_____
2 spools of line	Verified:	<u>YES</u>	NO	_____
2000' 18" containment boom (verification of)	Verified:	<u>YES</u>	NO	_____
4 Bundles absorbent pads	Verified:	<u>YES</u>	NO	_____
4- Bundles absorbent boom	Verified:	<u>YES</u>	NO	_____
1- Roll trash bags	Verified:	<u>YES</u>	NO	_____
1- Pair pliers	Verified:	<u>YES</u>	NO	_____
1- First Aid Kit	Verified:	<u>YES</u>	NO	_____
1-Eye Wash	Verified:	<u>YES</u>	NO	_____

OUTSIDE CONTAINER

Box number 2

Container accessible Verified: YES NO 020845

Seal in place Verified: YES NO 1633108

Seal number _____

Container Temp Hi _____ Lo _____ Date: _____

Inspector:
Print: Shawn Smith

Signature: [Signature]

Facility Rep
Print: Sam Moran

Signature: [Signature]

Notify Facility 24 hrs prior to inspection

Person Notified: _____

Verification only

Moran Environmental Recovery LLC Inspection Sheet

DATE: 7/7/25

LOCATION: Elba Island

INSIDE CONTAINER

		Circle one		Comments
6- 26lb Anchors with chain	Verified:	<input checked="" type="radio"/> YES	NO	_____
4- Buoys with 2 shackles each	Verified:	<input checked="" type="radio"/> YES	NO	_____
2 spools of line	Verified:	<input checked="" type="radio"/> YES	NO	_____
2000' 18" containment boom (verification of)	Verified:	<input checked="" type="radio"/> YES	NO	_____
4 Bundles absorbent pads	Verified:	<input checked="" type="radio"/> YES	NO	_____
4- Bundles absorbent boom	Verified:	<input checked="" type="radio"/> YES	NO	_____
1- Roll trash bags	Verified:	<input checked="" type="radio"/> YES	NO	_____
1- Pair pliers	Verified:	<input checked="" type="radio"/> YES	NO	_____
1- First Aid Kit	Verified:	<input checked="" type="radio"/> YES	NO	_____
1-Eye Wash	Verified:	<input checked="" type="radio"/> YES	NO	_____

OUTSIDE CONTAINER

Box number 1

Container accessible Verified: YES NO 020862

Seal in place Verified: YES NO _____

Seal number _____

Container Temp Hi _____ Lo _____ Date: _____

Inspector:
Print: Shawn Smith

Signature: [Signature]

Facility Rep
Print: [Signature]

Signature: [Signature]

Notify Facility 24 hrs prior to inspection

Person Notified: _____

Verification only

Moran Environmental Recovery LLC Inspection Sheet

DATE: 7/7/25

LOCATION: MER Yard

INSIDE CONTAINER

		Circle one		Comments
6- 26lb Anchors with chain	Verified:	YES	NO	_____
4- Buoys with 2 shackles each	Verified:	YES	NO	_____
2 spools of line	Verified:	YES	NO	_____
2000' 18" containment boom (verification of)	Verified:	YES	NO	<u>MISC. EQUIPMENT</u>
4 Bundles absorbent pads	Verified:	YES	NO	_____
4- Bundles absorbent boom	Verified:	YES	NO	_____
1- Roll trash bags	Verified:	YES	NO	_____
1- Pair pliers	Verified:	YES	NO	_____
1- First Aid Kit	Verified:	YES	NO	_____
1-Eye Wash	Verified:	YES	NO	_____

OUTSIDE CONTAINER

Box number 7

Container accessible Verified: YES NO _____

Seal in place Verified: YES NO _____

Seal number _____

Container Temp Hi _____ Lo _____ Date: _____

Inspector: Shawn Smith
Print: _____

Signature: _____

Facility Rep
Print: _____

Signature: _____

Notify Facility 24 hrs prior to inspection

Person Notified: _____

Verification only

Moran Environmental Recovery LLC Inspection Sheet

DATE: 7/1/25

LOCATION: MER Yard

INSIDE CONTAINER

			Circle one		Comments
6- 26lb Anchors with chain	Verified:	YES	NO		<u>Boom</u>
4- Buoys with 2 shackles each	Verified:	YES	NO		<u>absorbent</u>
2 spools of line	Verified:	YES	NO		<u>pads</u>
Skimmer F	Verified:	YES	NO		
4 Bundles absorbent pads	Verified:	YES	NO		
4- Bundles absorbent boom	Verified:	YES	NO		
1- Roll trash bags	Verified:	YES	NO		
1- Pair pliers	Verified:	YES	NO		
1- First Aid Kit	Verified:	YES	NO		
1-Eye Wash	Verified:	YES	NO		

OUTSIDE CONTAINER

Box number 10

Container accessible Verified: YES NO _____

Seal in place Verified: YES NO _____

Seal number _____

Container Temp Hi _____ Lo _____ Date: _____

Inspector: Shawn Smith
Print: _____

Signature: _____

Facility Rep
Print: _____

Signature: _____

Notify Facility 24 hrs prior to inspection

Person Notified: _____

Verification only

Moran Environmental Recovery LLC Inspection Sheet

DATE: 2/7/25

LOCATION: MER Yard

INSIDE CONTAINER

		Circle one		Comments
6- 26lb Anchors with chain	Verified:	<input checked="" type="radio"/> YES	<input type="radio"/> NO	_____
4- Buoys with 2 shackles each	Verified:	<input checked="" type="radio"/> YES	<input type="radio"/> NO	_____
2 spools of line	Verified:	<input checked="" type="radio"/> YES	<input type="radio"/> NO	_____
2000' 18" containment boom (ver Skimmer F	Verified:	<input checked="" type="radio"/> YES	<input type="radio"/> NO	_____
4 Bundles absorbent pads Backing b	Verified:	<input checked="" type="radio"/> YES	<input type="radio"/> NO	_____
4- Bundles absorbent boom Boat Clear	Verified:	<input checked="" type="radio"/> YES	<input type="radio"/> NO	_____
1- Roll trash bags Operate PI	Verified:	<input checked="" type="radio"/> YES	<input type="radio"/> NO	_____
1- Pair pliers	Verified:	<input checked="" type="radio"/> YES	<input type="radio"/> NO	_____
1- First Aid Kit	Verified:	<input checked="" type="radio"/> YES	<input type="radio"/> NO	_____
1-Eye Wash	Verified:	<input checked="" type="radio"/> YES	<input type="radio"/> NO	_____

OUTSIDE CONTAINER

Box number 9

Container accessible Verified: YES NO _____

Seal in place Verified: YES NO _____

Seal number _____

Container Temp Hi _____ Lo _____ Date: _____

Inspector: Shawn Smay
Print: _____

Signature: _____

Facility Rep
Print: _____

Signature: _____

Notify Facility 24 hrs prior to inspection

Person Notified: _____

Verification only

Moran Environmental Recovery LLC Inspection Sheet

DATE: 7/7/25

LOCATION: MER

Trailer # 6189 Trailer Serial #53FBE2426KF050872 Date Placed in Service:

	Circle one		Comments
4- 26lb Anchors with chain	Verified: <u>YES</u>	NO	_____
4- Buoys with 2 shackles each	Verified: <u>YES</u>	NO	_____
4- Long lines	Verified: <u>YES</u>	NO	_____
4- Short lines	Verified: <u>YES</u>	NO	_____
** 1000' 18" containment boom (Verify Qual	Verified: <u>YES</u>	NO	_____
4 Bundles absorbent pads	Verified: <u>YES</u>	NO	_____
4- Bundles absorbent boom	Verified: <u>YES</u>	NO	_____
1- Roll trash bags	Verified: <u>YES</u>	NO	_____
2- Life jackets	Verified: <u>YES</u>	NO	_____
1- Pair pliers	Verified: <u>YES</u>	NO	_____
1- Skimmer 1800 SH	Verified: <u>YES</u>	NO	_____
1- First Aid Kit	Verified: <u>YES</u>	NO	_____
1-EyeWash	Verified: <u>YES</u>	NO	_____

*** See Boom Condition Report for updated Boom Condition

Comments on above Inventory: _____

OUTSIDE OF TRAILER

	Circle	Comments
Tag in place and current	<u>YES</u>	_____
Washed/Clean	<u>YES</u>	_____
Lights operational	<u>YES</u>	_____
Trailer tongue greased	<u>YES</u>	_____
Trailer number visible	<u>YES</u>	_____
Trailer moved and brakes working	<u>YES</u>	_____
Tire pressure ok	<u>YES</u>	_____
Tire tread ok	<u>YES</u>	_____
Hubs, lugs, and rims ok (need to be grea	<u>YES</u>	_____
Doors and hinges operating properly	<u>YES</u>	_____
Locks on doors (trailer secured)	<u>YES</u>	_____

Condition of Trailer Excellent Good Fair Poor

Comments on above items _____

Inspector: Shawn Smith
Print: _____
Facility Rep
Print: _____

Signature: [Signature]
Signature: _____

Notify Facility 24 hrs prior to inspection

Person Notified: _____

Check if Verification only

Moran Environmental Recovery LLC Inspection Sheet

DATE: 7/7/25

LOCATION: MER

Trailer # 6188

Trailer Serial #

Date Placed in Service:

	Verified:	Circle one	Comments
4- 26lb Anchors with chain	YES	NO	
4- Buoys with 2 shackles each	YES	NO	
4- Long lines	YES	NO	
4- Short lines	YES	NO	
** 1000' 18" containment boom (Verify Qual)	YES	NO	
4 Bundles absorbent pads	YES	NO	
4- Bundles absorbent boom	YES	NO	Power Packs
1- Roll trash bags	YES	NO	
2- Life jackets	YES	NO	
1- Pair pliers	YES	NO	
1- Skimmer 1800 SH	YES	NO	
1- First Aid Kit	YES	NO	
1-EyeWash	YES	NO	

*** See Boom Condition Report for updated Boom Condition

Comments on above Inventory: _____

OUTSIDE OF TRAILER

	Tag#	Circle	Comments
Tag in place and current	<u>TT35W74</u>		
Washed/Clean		<u>YES</u> NO	
Lights operational		<u>YES</u> NO	
Trailer tongue greased		<u>YES</u> NO	
Trailer number visible		<u>YES</u> NO	
Trailer moved and brakes working		<u>YES</u> NO	
Tire pressure ok		<u>YES</u> NO	
Tire tread ok		<u>YES</u> NO	
Hubs, lugs, and rims ok (need to be grea		<u>YES</u> NO	
Doors and hinges operating properly		<u>YES</u> NO	
Locks on doors (trailer secured)		<u>YES</u> NO	

Condition of Trailer Excellent Good Fair Poor
 Comments on above items _____

Inspector:
 Print: Shawn Smith
 Facility Rep
 Print: _____

Signature: [Signature]
 Signature: _____

Notify Facility 24 hrs prior to inspection

Person Notified: _____

Check if Verification only

Moran Environmental Recovery LLC Inspection Sheet

DATE: 7/7/25

LOCATION: MER YARD

Trailer #: 0188

SKIMMER TRAILER

Tag#: _____
Removed: YES NO

SK-1 SKIMMERS

Elastic Drum Skimmer Hydrolic TDSH13699178
 - Condition Circle: Excellent Good Poor Fair
 - Last Run Test Date: _____
 Comment: _____

SK-2

Action Pertolium Drum Skimmer Air driven Mod 18A Serial # 314
 - Condition Circle: Excellent Good Poor Fair
 - Last Run Test Date: _____
 Comment: _____

SK-3

Crucial Coated Drum Skimmer Mod#1CD18H36 Ser#214468
 -Condition Circle: Excellent Good Poor Fair
 -Last RunTest Date: _____
 Comment: _____

SK-4 Desmi DOP Circle: Excellent Good Poor Fair
 Date: _____

Desmi DOP Comment: _____

PM-1 PUMPS

3in Hydrolic Submersible Pump Serial # 11197
 - Condition Circle: Excellent Good Poor Fair
 - Last Run Test Date: _____
 Comment: _____

PM-2

4in Vickers Hydrolic Submersible Pump Serial # 25M65A1C20
 - Condition Circle: Excellent Good Poor Fair
 - Last Run Test Date: _____
 Comment: _____

PM-3

6in Hydrotech Hydrolic Submersible Pump Serial # 6F878
 - Condition Circle: Excellent Good Poor Fair
 - Last Run Test Date: _____
 Comment: _____

PM-4

3" Crucial Diesel SD Pump Mod#DDP-3 Ser#214468
 -Condition Circle: Excellent Good Poor Fair
 -Last Run Test Date: _____
 Comment: _____

PP-1 POWER PACKS

Elastic Power Pack Serial # H1198258
 - Condition Circle: Excellent Good Poor Fair
 - Last Run Test Date: _____
 Comment: _____

PP-2

739 Hydrotech Power Pack Mod # HT60DCV Serial # F:
 - Condition Circle: Excellent Good Poor Fair
 - Last Run Test Date: _____
 Comment: _____

PP-3

Crucial Diesel Compres **Mod#L70190126P17E Ser#214468**
 -Condition Circle: Excellent Good Poor Fair
 -Last Run Test Date: _____
 Comment: _____

PP-4

Crucial Trailer-Mounted Diesel 25 HP Powerpack Circle: Excellent Good Poor Fair
 Date: _____
 Comment: _____

Moran Environmental Recovery LLC Inspection Sheet

DATE: 7/7/25

LOCATION: MER

Trailer # 6187

Trailer Serial #

Date Placed in Service:

		Circle one		Comments
4- 26lb Anchors with chain	Verified:	<input checked="" type="radio"/> YES	<input type="radio"/> NO	_____
4- Buoys with 2 shackles each	Verified:	<input checked="" type="radio"/> YES	<input type="radio"/> NO	_____
4- Long lines	Verified:	<input checked="" type="radio"/> YES	<input type="radio"/> NO	_____
4- Short lines	Verified:	<input checked="" type="radio"/> YES	<input type="radio"/> NO	_____
** 1000' 18" containment boom (Verify Qua	Verified:	<input checked="" type="radio"/> YES	<input type="radio"/> NO	_____
4 Bundles absorbent pads	Verified:	<input checked="" type="radio"/> YES	<input type="radio"/> NO	_____
4- Bundles absorbent boom	Verified:	<input checked="" type="radio"/> YES	<input type="radio"/> NO	_____
1- Roll trash bags	Verified:	<input checked="" type="radio"/> YES	<input type="radio"/> NO	_____
2- Life jackets	Verified:	<input checked="" type="radio"/> YES	<input type="radio"/> NO	_____
1- Pair pliers	Verified:	<input checked="" type="radio"/> YES	<input type="radio"/> NO	_____
1- Skimmer 1800 SH	Verified:	<input checked="" type="radio"/> YES	<input type="radio"/> NO	_____
1- First Aid Kit	Verified:	<input checked="" type="radio"/> YES	<input type="radio"/> NO	_____
1-EyeWash	Verified:	<input checked="" type="radio"/> YES	<input type="radio"/> NO	_____

*** See Boom Condition Report for updated Boom Condition

Comments on above inventory: _____

OUTSIDE OF TRAILER

	Tag#	Circle		Comments
Tag in place and current	<u>TT25m65</u>			_____
Washed/Clean		<input checked="" type="radio"/> YES	<input type="radio"/> NO	_____
Lights operational		<input checked="" type="radio"/> YES	<input type="radio"/> NO	_____
Trailer tongue greased		<input checked="" type="radio"/> YES	<input type="radio"/> NO	_____
Trailer number visible		<input checked="" type="radio"/> YES	<input type="radio"/> NO	_____
Trailer moved and brakes working		<input checked="" type="radio"/> YES	<input type="radio"/> NO	_____
Tire pressure ok		<input checked="" type="radio"/> YES	<input type="radio"/> NO	_____
Tire tread ok		<input checked="" type="radio"/> YES	<input type="radio"/> NO	_____
Hubs, lugs, and rims ok (need to be grea		<input checked="" type="radio"/> YES	<input type="radio"/> NO	_____
Doors and hinges operating properly		<input checked="" type="radio"/> YES	<input type="radio"/> NO	_____
Locks on doors (trailer secured)		<input checked="" type="radio"/> YES	<input type="radio"/> NO	_____
Condition of Trailer		Excellent	<input checked="" type="radio"/> Good	Fair Poor

Comments on above items _____

Inspector:
Print: Shark Smith

Signature: [Signature]

Facility Rep
Print: _____

Signature: _____

Notify Facility 24 hrs prior to inspection

Person Notified: _____

Check if Verification only

Moran Environmental Recovery LLC Inspection Sheet

DATE: 7/7/25

LOCATION: MER

Trailer # 6186 Trailer Serial #53FBE2421KF050875 Date Placed in Service:

	Circle one	Comments
4- 26lb Anchors with chain	Verified: <u>YES</u> NO	_____
4- Buoys with 2 shackels each	Verified: <u>YES</u> NO	_____
4- Long lines	Verified: <u>YES</u> NO	_____
4- Short lines	Verified: <u>YES</u> NO	_____
** 1000' 18" containment boom (Verify Qua)	Verified: <u>YES</u> NO	_____
4 Bundles absorbent pads	Verified: <u>YES</u> NO	_____
4- Bundles absorbent boom	Verified: <u>YES</u> NO	_____
1- Roll trash bags	Verified: <u>YES</u> NO	_____
2- Life jackets	Verified: <u>YES</u> NO	_____
1- Pair pliers	Verified: <u>YES</u> NO	_____
1- Skimmer 1800 SH	Verified: <u>YES</u> NO	_____
1- First Aid Kit	Verified: <u>YES</u> NO	_____
1-EyeWash	Verified: <u>YES</u> NO	_____

*** See Boom Condition Report for updated Boom Condition

Comments on above Inventory: _____

OUTSIDE OF TRAILER

	Circle	Comments
Tag in place and current	Tag# <u>TJ25M57</u>	_____
Washed/Clean	<u>YES</u> NO	_____
Lights operational	<u>YES</u> NO	_____
Trailer tounge greased	<u>YES</u> NO	_____
Trailer number visible	<u>YES</u> NO	_____
Trailer moved and brakes working	<u>YES</u> NO	_____
Tire pressure ok	<u>YES</u> NO	_____
Tire tread ok	<u>YES</u> NO	_____
Hubs, lugs, and rims ok (need to be grea	<u>YES</u> NO	_____
Doors and hinges operating properly	<u>YES</u> NO	_____
Locks on doors (trailer secured)	<u>YES</u> NO	_____

Condition of Trailer Excellent Good Fair Poor
 Comments on above items _____

Inspector:
 Print: Shawn Smith
 Facility Rep
 Print: _____

Signature: [Signature]
 Signature: _____

Notify Facility 24 hrs prior to inspection

Person Notified: _____

Check if Verification only

Moran Environmental Recovery LLC Inspection Sheet

DATE: 7/7/25

Location: MER Yard

Unit #: 6712

BOOM REELS

	Circle			
			Comments	
Grease Chain	YES	NO		
Grease Fittings	YES	NO		
Inspect sprocket	YES	NO		
Check Oil level in motor	YES	NO		
Reel clear of debris and grass	YES	NO		
Run motor	YES	NO		
Hand Brake operational	YES	NO		
Boom Reel cover secure	YES	NO		
*** 1000ft of 18" containment boom (Verify Quanti	YES	NO		
Condition of Boom Reel Cover			Excellent <u>Good</u> Fair Poor	
Condition of Boom Reel			Excellent <u>Good</u> Fair Poor	

*** See Boom condition Report for updated Boom Condition

Inspector: Shawn Smith Signature: [Signature]

Facility Rep
Print: _____ Signature: _____

Notify Facility 24 hrs prior to inspection

Person Notified: _____

Check if Verification only

Moran Environmental Recovery LLC Inspection Sheet

DATE: 7/16/25

LOCATION: MER YARD

JON BOATS AND MOTORS

BOATS

Unit 853	14' Boat	G3 1436	GEN6849JG900	Circle: Excelent	<u>Good</u>	Fair	Poor
G3 1438		GEN61758G708		Circle: Excelent	<u>Good</u>	Fair	Poor
Express		JBC21426B595		Circle: Excelent	<u>Good</u>	Fair	Poor
G3 1444		GEN 36264H506		Circle: Excelent	<u>Good</u>	Fair	Poor
Lowe L1436L	LWCJ2227	Backing belt and pins		Circle: Excelent	<u>Good</u>	Fair	Poor

Boat Clean MOTORS

Yamaha 9.9		Operate PP and engines SN# GAUKS1024920	Circle: Excelent	<u>Good</u>	Fair	Poor
			Last Run Date: _____			
			Comments: _____			
Yamaha 9.9	558	Mod # F9.95MHA SN# GAUKS1028386	Circle: Excelent	<u>Good</u>	Fair	Poor
			Last Run Date: _____			
			Comments: _____			
Yamaha 9.9	560	Mod# F9.9MHB SN# GAUKS1030921	Circle: Excelent	<u>Good</u>	Fair	Poor
			Last Run Date: _____			
			Comments: _____			
Yamaha 15		Mod# F15SMHA SN# 6AGKS1063676	Circle: Excelent	<u>Good</u>	Fair	Poor
			Last Run Date: _____			
			Comments: _____			
Yamaha 15		Mod# F15SEHA SN# 6AGKS1062763	Circle: Excelent	<u>Good</u>	Fair	Poor
			Last Run Date: _____			
			Comments: _____			

Inspector: Shawn Smith
Print: _____

Signature: [Signature]

Check if Verification only

Moran Environmental Recovery LLC Inspection Sheet

DATE: 7.16.25

LOCATION: Colonial Terminal

INSIDE CONTAINER

		Circle one		Comments
6- 26lb Anchors with chain	Verified:	<input checked="" type="radio"/> YES	NO	_____
4- Buoys with 2 shackles each	Verified:	<input checked="" type="radio"/> YES	NO	_____
2 spools of line	Verified:	<input checked="" type="radio"/> YES	NO	_____
2000' 18" containment boom (verification of)	Verified:	<input checked="" type="radio"/> YES	NO	_____
4 Bundles absorbent pads	Verified:	<input checked="" type="radio"/> YES	NO	_____
4- Bundles absorbent boom	Verified:	<input checked="" type="radio"/> YES	NO	_____
1- Roll trash bags	Verified:	<input checked="" type="radio"/> YES	NO	_____
1- Pair pliers	Verified:	<input checked="" type="radio"/> YES	NO	_____
1- First Aid Kit	Verified:	<input checked="" type="radio"/> YES	NO	_____
1-Eye Wash	Verified:	<input checked="" type="radio"/> YES	NO	_____

OUTSIDE CONTAINER

Box number 3

Container accessible Verified: YES NO _____

Seal in place Verified: YES NO _____

Seal number 020803 020804

Container Temp Hi _____ Lo _____ Date: _____

Inspector:
Print: Carson Deloach

Signature: Carson Deloach

Facility Rep
Print: Chris Hill

Signature: _____

Notify Facility 24 hrs prior to inspection

Person Notified: _____

Verification only

Moran Environmental Recovery LLC Inspection Sheet

DATE: _____

Location: MER Yard

Unit #: _____

BOOM REELS

	Circle		Comments				
Grease Chain	YES	NO	_____				
Grease Fittings	YES	NO	_____				
Inspect sprocket	YES	NO	_____				
Check Oil level in motor	YES	NO	_____				
Reel clear of debris and grass	YES	NO	_____				
Run motor	YES	NO	_____				
Hand Brake operational	YES	NO	_____				
Boom Reel cover secure	YES	NO	_____				
*** 1000ft of 18" containment boom (Verify Quanti	YES	NO	_____				
Condition of Boom Reel Cover			<table border="0" style="width: 100%; font-size: small;"> <tr> <td style="width: 25%;">Excellent</td> <td style="width: 25%;">Good</td> <td style="width: 25%;">Fair</td> <td style="width: 25%;">Poor</td> </tr> </table>	Excellent	Good	Fair	Poor
Excellent	Good	Fair	Poor				
Condition of Boom Reel			<table border="0" style="width: 100%; font-size: small;"> <tr> <td style="width: 25%;">Excellent</td> <td style="width: 25%;">Good</td> <td style="width: 25%;">Fair</td> <td style="width: 25%;">Poor</td> </tr> </table>	Excellent	Good	Fair	Poor
Excellent	Good	Fair	Poor				

*** See Boom condition Report for updated Boom Condition

Inspector:
Print: _____ Signature: _____

Facility Rep
Print: _____ Signature: _____

Notify Facility 24 hrs prior to inspection

Person Notified: _____

Check if Verification only

Moran Environmental Recovery LLC Inspection Sheet

DATE: _____ LOCATION: VOPAK

Trailer # 6017 Trailer Serial # 4X4TSEZ253U202767 Date Placed in Service: 2003

		Circle one		Comments
4- 26lb Anchors with chain	Verified:	YES	NO	_____
4- Buoys with 2 shackels each	Verified:	YES	NO	_____
4- Long lines	Verified:	YES	NO	_____
4- Short lines	Verified:	YES	NO	_____
** 1000' 18" containment boom (Verify Qua	Verified:	YES	NO	_____
4 Bundles absorbent pads	Verified:	YES	NO	_____
4- Bundles absorbent boom	Verified:	YES	NO	_____
1- Roll trash bags	Verified:	YES	NO	_____
2- Life jackets	Verified:	YES	NO	_____
1- Pair pliers	Verified:	YES	NO	_____
1- Skimmer 1800 SH	Verified:	YES	NO	_____
1- First Aid Kit	Verified:	YES	NO	_____
1-EyeWash	Verified:	YES	NO	_____

*** See Boom Condition Report for updated Boom Condition

Comments on above Inventory: _____

OUTSIDE OF TRAILER

		Circle		Comments
Tag in place and current	Tag#			_____
Washed/Clean		YES	NO	_____
Lights operational		YES	NO	_____
Trailer tounge greased		YES	NO	_____
Trailer number visible		YES	NO	_____
Trailer moved and brakes working		YES	NO	_____
Tire pressure ok		YES	NO	_____
Tire tread ok		YES	NO	_____
Hubs, lugs, and rims ok (need to be grea		YES	NO	_____
Doors and hinges operating properly		YES	NO	_____
Locks on doors (trailer secured)		YES	NO	_____

Condition of Trailer Excellent Good Fair Poor

Comments on above items _____

Inspector: _____
 Print: _____ Signature: _____

Facility Rep _____
 Print: _____ Signature: _____

Notify Facility 24 hrs prior to inspection

Person Notified: _____

Check if Verification only