

Moran Environmental Recovery LLC Inspection Sheet

DATE: 3/10/25

Location: MER Yard

Unit #: 6712

BOOM REELS

	Circle	NO	Comments
Grease Chain	YES	NO	_____
Grease Fittings	YES	NO	_____
Inspect sprocket	YES	NO	_____
Check Oil level in motor	YES	NO	_____
Reel clear of debris and grass	YES	NO	_____
Run motor	YES	NO	<u>bad batteries, unable to pull start</u>
Hand Brake operational	YES	NO	_____
Boom Reel cover secure	YES	NO	_____
*** 1000ft of 18" containment boom (Verify Quanti	YES	NO	_____
Condition of Boom Reel Cover			Excellent <u>Good</u> Fair Poor
Condition of Boom Reel			Excellent <u>Good</u> Fair Poor

*** See Boom condition Report for updated Boom Condition

Trailer #: 6712

Tag & Exp: _____

DOT Inspection: _____

Insurance: X

Tire Pressure: X

Wheels/Lugs: X

Brakes: X

Axle Hubs: X

Trailer Lights: X

Trailer Jack: X

Trailer Frame: X

Hydraulics: _____

Inspector: Josiah Strickland

Signature: Josiah Strickland

Facility Rep
Print: _____

Signature: _____

Notify Facility 24 hrs prior to inspection

Person Notified: _____

Check if Verification only

Moran Environmental Recovery LLC Inspection Sheet

DATE: 3/10/25

LOCATION: _____ MER _____

Trailer # 6189 Trailer Serial #53FBE2426KF050872 Date Placed in Service: _____

		Circle one		Comments
4- 26lb Anchors with chain	Verified:	<input checked="" type="radio"/> YES	NO	_____
4- Buoys with 2 shackles each	Verified:	<input checked="" type="radio"/> YES	NO	_____
4- Long lines	Verified:	<input checked="" type="radio"/> YES	NO	_____
4- Short lines	Verified:	<input checked="" type="radio"/> YES	NO	_____
** 1000' 18" containment boom (Verify Quali	Verified:	<input checked="" type="radio"/> YES	NO	_____
4 Bundles absorbent pads	Verified:	<input checked="" type="radio"/> YES	NO	_____
4- Bundles absorbent boom	Verified:	<input checked="" type="radio"/> YES	NO	_____
1- Roll trash bags	Verified:	<input checked="" type="radio"/> YES	NO	_____
2- Life jackets	Verified:	<input checked="" type="radio"/> YES	NO	_____
1- Pair pliers	Verified:	<input checked="" type="radio"/> YES	NO	_____
1- Skimmer 1800 SH	Verified:	<input checked="" type="radio"/> YES	NO	_____
1- First Aid Kit	Verified:	<input checked="" type="radio"/> YES	<input type="radio"/> NO	_____
1-EyeWash	Verified:	YES	<input type="radio"/> NO	_____

*** See Boom Condition Report for updated Boom Condition

Comments on above Inventory: _____

OUTSIDE OF TRAILER

		Circle		Comments
Tag in place and current	Tag#		<u>TT 35W73</u>	_____
Washed/Clean		<input checked="" type="radio"/> YES	NO	_____
Lights operational		<input checked="" type="radio"/> YES	NO	_____
Trailer tounge greased		<input checked="" type="radio"/> YES	NO	_____
Trailer number visible		<input checked="" type="radio"/> YES	NO	_____
Trailer moved and brakes working		<input checked="" type="radio"/> YES	NO	_____
Tire pressure ok		<input checked="" type="radio"/> YES	NO	_____
Tire tread ok		<input checked="" type="radio"/> YES	NO	_____
Hubs, lugs, and rims ok (need to be grea		<input checked="" type="radio"/> YES	NO	_____
Doors and hinges operating properly		<input checked="" type="radio"/> YES	NO	_____
Locks on doors (trailer secured)		YES	<input type="radio"/> NO	_____
Condition of Trailer			Excellent <input checked="" type="radio"/> Good Fair Poor	_____

Comments on above items _____

Inspector: _____
 Print: Shawn Smith

Signature: [Signature]
 Signature: _____

Notify Facility 24 hrs prior to inspection

Person Notified: _____

Check if Verification only

Moran Environmental Recovery LLC Inspection Sheet

DATE: 3/7/25

LOCATION: Elba Island

INSIDE CONTAINER

		Circle one	
6- 26lb Anchors with chain	Verified:	<u>YES</u> NO	_____
4- Buoys with 2 shackles each	Verified:	<u>YES</u> NO	_____
2 spools of line	Verified:	<u>YES</u> NO	_____
2000' 18" containment boom (verification of)	Verified:	<u>YES</u> NO	_____
4 Bundies absorbent pads	Verified:	<u>YES</u> NO	_____
4- Bundles absorbent boom	Verified:	<u>YES</u> NO	_____
1- Roll trash bags	Verified:	<u>YES</u> NO	_____
1- Pair pliers	Verified:	<u>YES</u> NO	_____
1- First Aid Kit	Verified:	<u>YES</u> NO	_____
1-Eye Wash	Verified:	<u>YES</u> NO	_____

OUTSIDE CONTAINER

Box number 2

Container accessible Verified: YES NO _____

Seal in place Verified: YES NO _____

Seal number 1633108 020845

Container Temp Hi _____ Lo _____ Date: _____

Inspector: Shawn Smith
Print: _____

Signature: [Signature]

Facility Rep: Sean Coorh
Print: _____

Signature: [Signature]

Notify Facility 24 hrs prior to inspection

Person Notified: _____

Check if Verification only

Moran Environmental Recovery LLC Inspection Sheet

DATE: 3/7/25

LOCATION: Elba Island

INSIDE CONTAINER

		Circle one		Comments
6- 26lb Anchors with chain	Verified:	<u>YES</u> NO	_____	
4- Buoys with 2 shackles each	Verified:	<u>YES</u> NO	_____	
2 spools of line	Verified:	<u>YES</u> NO	_____	
2000' 18" containment boom (verification of)	Verified:	<u>YES</u> NO	_____	
4 Bundles absorbent pads	Verified:	<u>YES</u> NO	_____	
4- Bundles absorbent boom	Verified:	<u>YES</u> NO	_____	
1- Roll trash bags	Verified:	<u>YES</u> NO	_____	
1- Pair pliers	Verified:	<u>YES</u> NO	_____	
1- First Aid Kit	Verified:	<u>YES</u> NO	_____	
1-Eye Wash	Verified:	<u>YES</u> NO	_____	

OUTSIDE CONTAINER

Box number 1

Container accessible _____ Verified: YES NO _____

Seal in place _____ Verified: YES NO _____

Seal number _____

Container Temp Hi _____ Lo 020862 Date: 1633107

Inspector:
Print: Shawn Smith

Signature: _____

Facility Rep
Print: Sean Courtois

Signature: _____

Notify Facility 24 hrs prior to inspection

Person Notified: _____

Check if Verification only

Moran Environmental Recovery LLC Inspection Sheet

DATE: 3/7/25

Location: Phillips 66

Unit #: BR 4

BOOM REELS

Circle

Comments

Grease Chain	YES	NO	
Grease Fittings	YES	NO	
Inspect sprocket	YES	NO	
Check Oil level in motor	YES	NO	
Reel clear of debris and grass	YES	NO	
Run motor	YES	NO	
Hand Brake operational	YES	NO	
Boom Reel cover secure	YES	NO	
*** 1000ft of 18" containment boom (Verify Quanti	YES	NO	<u>Boom off the reel</u>
Condition of Boom Reel Cover			Excellent Good Fair <u>Poor</u>
Condition of Boom Reel			Excellent Good Fair <u>Poor</u>

*** See Boom condition Report for updated Boom Condition

Inspector: Shawn Smith Signature: _____

Facility Rep Print: James S. Thekend Signature: _____

Notify Facility 24 hrs prior to inspection

Person Notified: _____

Check if Verification only

Moran Environmental Recovery LLC Inspection Sheet

Vessel Name: Al Allen

Vessel Make: Lobelle

Inspection Date: 3/7/25

Unit #: 862

Location: Phillips 66

Registration #: GA 6658 YE

Last Months Recorded Hours 219.6
Current Months Recorded Hours _____

Check items (X)

Check items (X)

Visual Hull Inspection

Check fuel level (full)

Check Batteries

Check oil level

Inspect fuel lines

Spark Plug wires

Inspect Bilge

Boat Clean

Operate Bilge pump

Operate for 15 min

GPS /VHF Working

Insurance

*** VESSEL SHOULD GO THROUGH A SEA TRIAL TO INSURE OPERATING AT PEAK PERFORMANCE A MIN OF ONCE PER QUARTER

Trailer #: 6094

Tag & Exp: _____

DOT Inspection: _____

Insurance:

Tire Pressure:

Wheels/Lugs:

Brakes:

Axle Hubs:

Trailer Lights:

Trailer Jack:

Trailer Frame:

Bunks:

Inspector: Shawn Smith
Print: _____

Signature: _____

Facility Rep: James Sutherland
Print: _____

Signature: _____

Notify Facility 24 hrs prior to inspection

Person Notified: _____

Check if Verification only

Moran Environmental Recovery LLC Inspection Sheet

DATE: 3/7/25

LOCATION: MER

Trailer # 6190 Trailer Serial # 53FBE2427KF050878 Date Placed in Service: _____

Circle one

Comments

4- 26lb Anchors with chain	Verified:	<u>YES</u>	NO	
4- Buoys with 2 shackles each	Verified:	<u>YES</u>	NO	
4- Long lines	Verified:	<u>YES</u>	NO	
4- Short lines	Verified:	<u>YES</u>	NO	
*** 1000' 18" containment boom (Verify Qua	Verified:	<u>YES</u>	NO	
4 Bundles absorbent pads	Verified:	<u>YES</u>	NO	
4- Bundles absorbent boom	Verified:	<u>YES</u>	NO	
1- Roll trash bags	Verified:	<u>YES</u>	NO	
2- Life jackets	Verified:	<u>YES</u>	NO	
1- Pair pliers	Verified:	<u>YES</u>	NO	
1- Skimmer 1800 SH	Verified:	<u>YES</u>	NO	
1- First Aid Kit	Verified:	<u>YES</u>	NO	
1-EyeWash	Verified:	<u>YES</u>	NO	

*** See Boom Condition Report for updated Boom Condition

Comments on above inventory: _____

OUTSIDE OF TRAILER

Circle

Comments

Tag in place and current	Tag#	<u>TT 25msd</u>	<u>JUL/25</u>	
Washed/Clean		<u>YES</u>	NO	
Lights operational		<u>YES</u>	NO	
Trailer tounge greased		<u>YES</u>	NO	
Trailer number visible		<u>YES</u>	NO	
Trailer moved and brakes working		<u>YES</u>	NO	
Tire pressure ok		<u>YES</u>	NO	
Tire tread ok		<u>YES</u>	NO	
Hubs, lugs, and rims ok (need to be grea		<u>YES</u>	NO	
Doors and hinges operating properly		<u>YES</u>	NO	
Locks on doors (trailer secured)		<u>YES</u>	NO	

Condition of Trailer Excellent Good Fair Poor

Comments on above items _____

Inspector: Shawn Smith
 Print: _____

Signature: _____

Facility Rep: Karen Riley
 Print: _____

Signature: _____

Notify Facility 24 hrs prior to inspection

Person Notified: _____

Check if Verification only

Moran Environmental Recovery LLC Inspection Sheet

Vessel Name: Porpoise Vessel Make: Custom

Inspection Date: 3/7/25 Unit #: 835

Location: SNF Chemtall Registration #: GA 6256 GB

Last Months Recorded Hours 277
Current Months Recorded Hours _____

Check items (X)

Check items (X)

<input checked="" type="checkbox"/> Visual Hull Inspection	<input checked="" type="checkbox"/> Check fuel level (full)
<input checked="" type="checkbox"/> Check Batteries	<input checked="" type="checkbox"/> Check oil level
<input checked="" type="checkbox"/> Inspect fuel lines	<input checked="" type="checkbox"/> Spark Plug wires
<input checked="" type="checkbox"/> Inspect Bilge	<input checked="" type="checkbox"/> Boat Clean
<input checked="" type="checkbox"/> Operate Bilge pump	<input checked="" type="checkbox"/> Operate for 15 min
<input checked="" type="checkbox"/> No Electronics	<input checked="" type="checkbox"/> Insurance/Registration

*** VESSEL SHOULD GO THROUGH A SEA TRIAL TO INSURE OPERATING AT PEAK PERFORMANCE A MIN OF ONCE PER QUARTER

Trailer #: <u>6042</u>	Tag & Exp: <u>308 VZM 06/25</u>
DOT Inspection: <u>April 24</u>	Insurance: <input checked="" type="checkbox"/>
Tire Pressure: <input checked="" type="checkbox"/>	Wheels/Lugs: <input checked="" type="checkbox"/>
Brakes: <input checked="" type="checkbox"/>	Axle Hubs: <input checked="" type="checkbox"/>
Trailer Lights: <input checked="" type="checkbox"/>	Trailer Jack: <input checked="" type="checkbox"/>
Trailer Frame: <input checked="" type="checkbox"/>	Bunks: <input checked="" type="checkbox"/>

Inspector: Shawn Smith Signature: _____

Facility Rep Print: Karen Riley Signature: _____

Notify Facility 24 hrs prior to inspection

Person Notified: _____

Check if Verification only

Moran Environmental Recovery LLC Inspection Sheet

DATE: 3/4/25

LOCATION: Plant McIntosh

INSIDE CONTAINER

		Circle one	
6- 26lb Anchors with chain	Verified:	<u>YES</u> NO	_____
4- Buoys with 2 shackles each	Verified:	<u>YES</u> NO	_____
2 spools of line	Verified:	<u>YES</u> NO	_____
2000' 18" containment boom (verification of)	Verified:	<u>YES</u> NO	_____
4 Bundles absorbent pads	Verified:	<u>YES</u> NO	_____
4- Bundles absorbent boom	Verified:	<u>YES</u> NO	_____
1- Roll trash bags	Verified:	<u>YES</u> NO	_____
1- Pair pliers	Verified:	<u>YES</u> NO	_____
1- First Aid Kit	Verified:	<u>YES</u> NO	_____
1-Eye Wash	Verified:	<u>YES</u> NO	_____

OUTSIDE CONTAINER

Box number 8

Container accessible Verified: YES NO _____

Seal in place Verified: YES NO _____

Seal number 020880 Date: 02/08/20

Container Temp Hi _____ Lo _____

Inspector: Shawn Smith
Print: _____

Signature: [Signature]

Facility Rep: Owen Bryant
Print: _____

Signature: [Signature]

Notify Facility 24 hrs prior to inspection

Person Notified: _____

Check if Verification only

Moran Environmental Recovery LLC Inspection Sheet

Vessel Name: Savannah Patriot Vessel Make: Custom

Inspection Date: _____ Unit #: 865

Location: Savannah, GA Registration #: GA 0296 NW

Last Months Recorded Hours _____
Current Months Recorded Hours _____

Check items (X)

Check items (X)

<input checked="" type="checkbox"/> Visual Hull Inspection	<input checked="" type="checkbox"/> Check fuel level (full)
<input checked="" type="checkbox"/> Check Batteries	<input checked="" type="checkbox"/> Check oil level
<input checked="" type="checkbox"/> Inspect fuel lines	<input checked="" type="checkbox"/> Spark Plug wires
<input checked="" type="checkbox"/> Inspect Bilge	<input checked="" type="checkbox"/> Boat Clean
<input checked="" type="checkbox"/> Operate Bilge pump	<input checked="" type="checkbox"/> Operate for 15 min
<input checked="" type="checkbox"/> No Electronics	<input checked="" type="checkbox"/> Insurance

*** VESSEL SHOULD GO THROUGH A SEA TRIAL TO INSURE OPERATING AT PEAK PERFORMANCE A MIN OF ONCE PER QUARTER

Trailer #: 6113

DOT Inspection: SEPT 24

Tire Pressure: X

Brakes: X

Trailer Lights: X

Trailer Frame: X

Tag & Exp: TR 1523L JUL 25

Insurance: X

Wheels/Lugs: X

Axle Hubs: X

Trailer Jack: X

Bunks: X

Inspector: Shane Smyth
Print: _____

Signature: _____

Facility Rep
Print: _____

Signature: _____

Notify Facility 24 hrs prior to inspection

Person Notified: _____

Check if Verification only

Moran Environmental Recovery LLC Inspection Sheet

Vessel Name: 17' Work Boat Vessel Make: Custom

Inspection Date: 3/7/25 Unit #: 866

Location: Savannah, GA Registration #: GA 0302 UT

Last Months Recorded Hours 169
Current Months Recorded Hours _____

Check items (X)

Check items (X)

<input checked="" type="checkbox"/> Visual Hull Inspection	<input checked="" type="checkbox"/> Check fuel level (full)
<input checked="" type="checkbox"/> Check Batteries	<input checked="" type="checkbox"/> Check oil level
<input checked="" type="checkbox"/> Inspect fuel lines	<input checked="" type="checkbox"/> Spark Plug wires
<input checked="" type="checkbox"/> Inspect Bilge	<input checked="" type="checkbox"/> Boat Clean
<input checked="" type="checkbox"/> Operate Bilge pump	<input checked="" type="checkbox"/> Operate for 15 min
<input checked="" type="checkbox"/> No Electronics	

*** VESSEL SHOULD GO THROUGH A SEA TRIAL TO INSURE OPERATING AT PEAK PERFORMANCE A MIN OF ONCE PER QUARTER

Trailer #: <u>6135</u>	Tag & Exp: <u>FR5916Q JUL 25</u>
DOT Inspection: <u>Aug 24</u>	Insurance: <u>X</u>
Tire Pressure: <u>X</u>	Wheels/Lugs: <u>X</u>
Brakes: <u>X</u>	Axle Hubs: <u>X</u>
Trailer Lights: <u>X</u>	Trailer Jack: <u>X</u>
Trailer Frame: <u>X</u>	Bunks: <u>X</u>

Inspector: Shaw Smith Signature: [Signature]

Facility Rep _____
Print: _____ Signature: _____

Notify Facility 24 hrs prior to inspection

Person Notified: _____

Check if Verification only

Moran Environmental Recovery LLC Inspection Sheet

Vessel Name: Marco Skimmer

Vessel Make: 30' Kvichak Skimmer

Inspection Date: 3/7/25

Unit #: 895

Location: Savannah, GA

Registration #: GA 9056 SC

Last Months Recorded Hours P.S. 13.7
Current Months Recorded Hours _____

Check items (X)

Check items (X)

<input checked="" type="checkbox"/> Visual Hull Inspection	<input checked="" type="checkbox"/> Check fuel level (full)
<input checked="" type="checkbox"/> Check Batteries	<input checked="" type="checkbox"/> Check oil level
<input checked="" type="checkbox"/> Inspect fuel lines	<input checked="" type="checkbox"/> Spark Plug wires
<input checked="" type="checkbox"/> Inspect Bilge	<input checked="" type="checkbox"/> Boat Clean
<input checked="" type="checkbox"/> Operate Bilge pump	<input checked="" type="checkbox"/> Operate for 15 min
<input checked="" type="checkbox"/> No Electronics	<input checked="" type="checkbox"/> Insurance

*** VESSEL SHOULD GO THROUGH A SEA TRIAL TO INSURE OPERATING AT PEAK PERFORMANCE A MIN OF ONCE PER QUARTER

Trailer #: 6648
DOT Inspection: July 24
Tire Pressure: X
Brakes: X
Trailer Lights: X
Trailer Frame: X

Tag & Exp: TUS3 E28 JUL25
Insurance: X
Wheels/Lugs: X
Axle Hubs: X
Trailer Jack: X
Bunks: X

Inspector: Shawn Smith
Print: _____

Signature: _____

Facility Rep
Print: _____

Signature: _____

Notify Facility 24 hrs prior to inspection

Person Notified: _____

Check if Verification only

Moran Environmental Recovery LLC Inspection Sheet

Vessel Name: Munson Vessel Make: Custom

Inspection Date: 3/7/25 Unit #: 871

Location: Colonial North Registration #: GA 0499 SN

Last Months Recorded Hours 102.3 ^P
Current Months Recorded Hours 102.4 ^S

Check items (X)

Visual Hull Inspection

Check Batteries

Inspect fuel lines

Inspect Bilge

Operate Bilge pump

No Electronics

Check items (X)

Check fuel level (full)

Check oil level

Spark Plug wires

Boat Clean

Operate for 15 min

Insurance

*** VESSEL SHOULD GO THROUGH A SEA TRIAL TO INSURE OPERATING AT PEAK PERFORMANCE A MIN OF ONCE PER QUARTER

Trailer #: 6147

Tag & Exp: F53 673 25

DOT Inspection: Sept 24

Insurance: X

Tire Pressure: X

Wheels/Lugs: X

Brakes: X

Axle Hubs: X

Trailer Lights: X

Trailer Jack: X

Trailer Frame: X

Bunks: X

Inspector:
Print: Shawn Smith

Signature: [Signature]

Facility Rep
Print: _____

Signature: _____

Notify Facility 24 hrs prior to inspection

Person Notified: _____

Check if Verification only

Moran Environmental Recovery LLC Inspection Sheet

Vessel Name: 34' Barge Boat

Vessel Make: Custom

Inspection Date: 3/7/25

Unit #: 891

Location: Savannah, GA

Registration #: GA 6589 DC

Last Months Recorded Hours
Current Months Recorded Hours

74.8 ^P
77.8 ^S

Check items (X)

Check items (X)

Visual Hull Inspection

Check fuel level (full)

Check Batteries

Check oil level

Inspect fuel lines

Spark Plug wires

Inspect Bilge

Boat Clean

Operate Bilge pump

Operate for 15 min

No Electronics

Insurance

*** VESSEL SHOULD GO THROUGH A SEA TRIAL TO INSURE OPERATING AT PEAK PERFORMANCE A MIN OF ONCE PER QUARTER

Trailer #: 6004

Tag & Exp: XK 6964 Perm tag

DOT Inspection: max 24

Insurance: Y

Tire Pressure: X

Wheels/Lugs: Y

Brakes: X

Axle Hubs: X

Trailer Lights: X

Trailer Jack: X

Trailer Frame: X

Bunks: X

Inspector:
Print: Shawn Smith

Signature: [Signature]

Facility Rep
Print: _____

Signature: _____

Notify Facility 24 hrs prior to inspection

Person Notified: _____

Check if Verification only

Moran Environmental Recovery LLC Inspection Sheet

DATE: 3/10/25

LOCATION: MER YARD

JON BOATS AND MOTORS

BOATS

Unit 853	14' Boat	G3 1436	GEN6849JG900	Circle: Excelent	Good	<u>Fair</u>	Poor
G3 1438		GEN61758G708		Circle: Excelent	Good	<u>Fair</u>	Poor
Express		JBC21426B595		Circle: Excelent	Good	<u>Fair</u>	Poor
G3 1444		GEN 36264H506		Circle: Excelent	Good	<u>Fair</u>	Poor
Lowe L1436L		LWCJ2227F506		Circle: Excelent	Good	<u>Fair</u>	Poor

MOTORS

Yamaha 9.9	559	Mod#F9.95MHA SN# GAUKS1024920	Circle: Excelent	Good	Fair	Poor	
			Last Run Date: _____	<u>not found</u>			
			Comments: _____				
Yamaha 9.9	558	Mod # F9.95MHA SN# GAUKS1028386	Circle: Excelent	Good	Fair	<u>Poor</u>	
			Last Run Date: _____	<u>Restart success</u>			
			Comments: _____				
Yamaha 9.9	560	Mod# F9.9MHB SN# GAUKS1030921	Circle: Excelent	Good	Fair	Poor	
			Last Run Date: _____	<u>not found</u>			
			Comments: _____				
Yamaha 15		Mod# F15SMHA SN# 6AGKS1063676	Circle: Excelent	Good	Fair	<u>Poor</u>	
			Last Run Date: _____	<u>water return line broken</u>			
			Comments: _____				
Yamaha 15		Mod# F15SEHA SN# 6AGKS1062763	Circle: Excelent	<u>Good</u>	Fair	Poor	
			Last Run Date: <u>3/10/25</u>				
			Comments: _____				

Inspector: Josiah Strickland
Print: _____

Signature: Josiah Strickland

Check if Verification only

Moran Environmental Recovery LLC Inspection Sheet

DATE: 3/10/25

LOCATION: MER Yard

INSIDE CONTAINER

		Circle one	Comments
6- 26lb Anchors with chain	Verified:	<input checked="" type="radio"/> YES NO	_____
4- Buoys with 2 shackles each	Verified:	<input checked="" type="radio"/> YES NO	_____
2 spools of line	Verified:	<input checked="" type="radio"/> YES NO	_____
2000' 18" containment boom (verification of)	Verified:	<input checked="" type="radio"/> YES NO	_____
4 Bundles absorbent pads	Verified:	<input checked="" type="radio"/> YES NO	_____
4- Bundles absorbent boom	Verified:	<input checked="" type="radio"/> YES NO	_____
1- Roll trash bags	Verified:	<input checked="" type="radio"/> YES NO	_____
1- Pair pliers	Verified:	<input checked="" type="radio"/> YES NO	_____
1- First Aid Kit	Verified:	YES <input checked="" type="radio"/> NO	<i>not found</i>
1-Eye Wash	Verified:	YES <input checked="" type="radio"/> NO	<i>not found</i>

OUTSIDE CONTAINER

Box number 9

Container accessible _____ Verified: YES NO

Seal in place _____ Verified: YES NO

Seal number _____

Container Temp Hi _____ Lo _____ Date: _____

Inspector: Josiah Strickland
Print: _____

Signature: *Josiah Strickland*
Signature: _____

Facility Rep _____
Print: _____

Notify Facility 24 hrs prior to inspection

Person Notified: _____

Check if Verification only

Moran Environmental Recovery LLC Inspection Sheet

DATE: 3/10/25

LOCATION: MER yard

INSIDE CONTAINER

		Circle one	
6- 26lb Anchors with chain	Verified:	YES NO	<u>Misc equipment</u>
4- Buoys with 2 shackles each	Verified:	YES NO	
2 spools of line	Verified:	YES NO	
2000' 18" containment boom (verification of)	Verified:	YES NO	
4 Bundles absorbent pads	Verified:	YES NO	
4- Bundles absorbent boom	Verified:	YES NO	
1- Roll trash bags	Verified:	YES NO	
1- Pair pliers	Verified:	YES NO	
1- First Aid Kit	Verified:	YES NO	
1-Eye Wash	Verified:	YES NO	

OUTSIDE CONTAINER

Box number 10

Container accessible Verified: YES NO

Seal in place Verified: YES NO

Seal number _____

Container Temp Hi _____ Lo _____ Date: _____

Inspector: Joshua Strickland
Print: _____

Signature: Joshua Strickland

Facility Rep _____
Print: _____

Signature: _____

Notify Facility 24 hrs prior to inspection

Person Notified: _____

Check if Verification only

Moran Environmental Recovery LLC Inspection Sheet

DATE: 3/16/25

LOCATION: MER yard

Trailer # 6187

Trailer Serial #

Date Placed in Service:

Circle one

Comments

4- 26lb Anchors with chain	Verified:	<input checked="" type="radio"/> YES	NO	
4- Buoys with 2 shackles each	Verified:	<input checked="" type="radio"/> YES	NO	
4- Long lines	Verified:	<input checked="" type="radio"/> YES	NO	
4- Short lines	Verified:	<input checked="" type="radio"/> YES	NO	
*** 1000' 18" containment boom (Verify Qua	Verified:	<input checked="" type="radio"/> YES	NO	
4 Bundles absorbent pads	Verified:	<input checked="" type="radio"/> YES	NO	
4- Bundles absorbent boom	Verified:	<input checked="" type="radio"/> YES	NO	
1- Roll trash bags	Verified:	<input checked="" type="radio"/> YES	NO	
2- Life jackets	Verified:	<input checked="" type="radio"/> YES	NO	
1- Pair pliers	Verified:	<input checked="" type="radio"/> YES	NO	
1- Skimmer 1800 SH	Verified:	<input checked="" type="radio"/> YES	NO	
1- First Aid Kit	Verified:	YES	<input checked="" type="radio"/> NO	not found
1-EyeWash	Verified:	YES	<input checked="" type="radio"/> NO	not found

*** See Boom Condition Report for updated Boom Condition

Comments on above Inventory: _____

OUTSIDE OF TRAILER

Circle

Comments

Tag in place and current	Tag#	<u>T725 M65</u>		
Washed/Clean		<input checked="" type="radio"/> YES	NO	
Lights operational		<input checked="" type="radio"/> YES	NO	
Trailer tounge greased		<input checked="" type="radio"/> YES	NO	
Trailer number visible		<input checked="" type="radio"/> YES	NO	
Trailer moved and brakes working		<input checked="" type="radio"/> YES	NO	
Tire pressure ok		<input checked="" type="radio"/> YES	NO	
Tire tread ok		<input checked="" type="radio"/> YES	NO	
Hubs, lugs, and rims ok (need to be grea		<input checked="" type="radio"/> YES	NO	
Doors and hinges operating properly		<input checked="" type="radio"/> YES	NO	
Locks on doors (trailer secured)		YES	<input checked="" type="radio"/> NO	
Condition of Trailer		Excellent	<input checked="" type="radio"/> Good	Fair Poor

Comments on above items _____

Inspector: Josiah Strickland
 Print: _____
 Facility Rep
 Print: _____

Signature: Josiah Strickland
 Signature: _____

Notify Facility 24 hrs prior to inspection

Person Notified: _____

Check if Verification only

Moran Environmental Recovery LLC Inspection Sheet

DATE: 3/10/25

LOCATION: MER

Trailer # 6186 Trailer Serial # 53FBE2421KF050875 Date Placed in Service: _____

Circle one

					Comments
4- 26lb Anchors with chain	Verified:	<input checked="" type="radio"/> YES	<input type="radio"/> NO		_____
4- Buoys with 2 shackles each	Verified:	<input checked="" type="radio"/> YES	<input type="radio"/> NO		_____
4- Long lines	Verified:	<input checked="" type="radio"/> YES	<input type="radio"/> NO		_____
4- Short lines	Verified:	<input checked="" type="radio"/> YES	<input type="radio"/> NO		_____
** 1000' 18" containment boom (Verify Qua	Verified:	<input checked="" type="radio"/> YES	<input type="radio"/> NO		_____
4 Bundles absorbent pads	Verified:	<input checked="" type="radio"/> YES	<input type="radio"/> NO		_____
4- Bundles absorbent boom	Verified:	<input checked="" type="radio"/> YES	<input type="radio"/> NO		_____
1- Roll trash bags	Verified:	<input checked="" type="radio"/> YES	<input type="radio"/> NO		_____
2- Life jackets	Verified:	<input checked="" type="radio"/> YES	<input type="radio"/> NO		_____
1- Pair pliers	Verified:	<input checked="" type="radio"/> YES	<input checked="" type="radio"/> NO		<u>not found</u>
1- Skimmer 1800 SH	Verified:	<input checked="" type="radio"/> YES	<input type="radio"/> NO		_____
1- First Aid Kit	Verified:	<input checked="" type="radio"/> YES	<input checked="" type="radio"/> NO		<u>not found</u>
1-EyeWash	Verified:	<input checked="" type="radio"/> YES	<input type="radio"/> NO		_____

*** See Boom Condition Report for updated Boom Condition

Comments on above Inventory: _____

OUTSIDE OF TRAILER

Circle

Comments

					Comments
Tag in place and current	Tag#	<u>TT25M59</u>			_____
Washed/Clean		<input checked="" type="radio"/> YES	<input type="radio"/> NO		_____
Lights operational		<input checked="" type="radio"/> YES	<input type="radio"/> NO		_____
Trailer tounge greased		<input checked="" type="radio"/> YES	<input type="radio"/> NO		_____
Trailer number visible		<input checked="" type="radio"/> YES	<input type="radio"/> NO		_____
Trailer moved and brakes working		<input checked="" type="radio"/> YES	<input type="radio"/> NO		_____
Tire pressure ok		<input checked="" type="radio"/> YES	<input type="radio"/> NO		_____
Tire tread ok		<input checked="" type="radio"/> YES	<input type="radio"/> NO		_____
Hubs, lugs, and rims ok (need to be grea		<input checked="" type="radio"/> YES	<input type="radio"/> NO		_____
Doors and hinges operating properly		<input checked="" type="radio"/> YES	<input type="radio"/> NO		_____
Locks on doors (trailer secured)		YES	<input checked="" type="radio"/> NO		_____
Condition of Trailer		Excellent	<input checked="" type="radio"/> Good	Fair	Poor

Comments on above items _____

Inspector: Josiah Strickland
 Print: _____
 Facility Rep
 Print: _____

Signature: Josiah Strickland
 Signature: _____

Notify Facility 24 hrs prior to inspection

Person Notified: _____

Check if Verification only

Moran Environmental Recovery LLC Inspection Sheet

DATE: 3/10/25

LOCATION: MER

Trailer # 6188

Trailer Serial #

Date Placed in Service:

Circle one

Comments

4- 26lb Anchors with chain	Verified:	YES	NO	_____
4- Buoys with 2 shackles each	Verified:	YES	NO	_____
4- Long lines	Verified:	YES	NO	_____
4- Short lines	Verified:	YES	NO	_____
*** 1000' 18" containment boom (Verify Qua	Verified:	YES	NO	_____
4 Bundles absorbent pads	Verified:	YES	NO	_____
4- Bundles absorbent boom	Verified:	YES	NO	_____
1- Roll trash bags	Verified:	YES	NO	_____
2- Life jackets	Verified:	YES	NO	_____
1- Pair pliers	Verified:	YES	NO	_____
1- Skimmer 1800 SH	Verified:	YES	NO	_____
1- First Aid Kit	Verified:	YES	NO	_____
1-EyeWash	Verified:	YES	NO	_____

*** See Boom Condition Report for updated Boom Condition

Comments on above Inventory: _____

OUTSIDE OF TRAILER

Circle

Comments

Tag in place and current	Tag#	<u>TT35W74</u>	_____
Washed/Clean	<input checked="" type="radio"/> YES	NO	_____
Lights operational	<input checked="" type="radio"/> YES	NO	_____
Trailer tounge greased	<input checked="" type="radio"/> YES	NO	_____
Trailer number visible	<input checked="" type="radio"/> YES	NO	_____
Trailer moved and brakes working	<input checked="" type="radio"/> YES	NO	_____
Tire pressure ok	<input checked="" type="radio"/> YES	NO	_____
Tire tread ok	<input checked="" type="radio"/> YES	NO	_____
Hubs, lugs, and rims ok (need to be grea	<input checked="" type="radio"/> YES	NO	_____
Doors and hinges operating properly	<input checked="" type="radio"/> YES	NO	_____
Locks on doors (trailer secured)	YES <input checked="" type="radio"/> NO		_____
Condition of Trailer	Excellent <input checked="" type="radio"/> Good	Fair	Poor

Comments on above items _____

Inspector: Josiah Strickland
 Print: _____
 Facility Rep
 Print: _____

Signature: Josiah Strickland
 Signature: _____

Notify Facility 24 hrs prior to inspection

Person Notified: _____

Check if Verification only

Moran Environmental Recovery LLC Inspection Sheet

DATE: 3/10/25

LOCATION: MER YARD

Trailer #: 6188

SKIMMER TRAILER

Tag#: TT35W74
Removed: YES NO

SK-1 SKIMMERS

- Elastic Drum Skimmer Hydraulic TDSH13699178
- Condition Circle: Excellent Good Poor Fair
- Last Run Test Date: _____
Comment: _____
- SK-2 Action Pertolium Drum Skimmer Air driven Mod 18A Serial # 314
- Condition Circle: Excellent Good Poor Fair
- Last Run Test Date: _____
Comment: _____
- SK-3 Crucial Coated Drum Skimmer Mod#1CD18H36 Ser#214468
-Condition Circle: Excellent Good Poor Fair
-Last RunTest Date: _____
Comment: _____

SK-4 Desmi DOP 160 Screw Pump
Circle: Excellent Good Poor Fair
Date: _____
Comment: _____

PM-1 PUMPS

- PM-1 3in Hydraulic Submersible Pump Serial # 11197
- Condition Circle: Excellent Good Poor Fair
- Last Run Test Date: _____
Comment: _____
- PM-2 4in Vickers Hydraulic Submersible Pump Serial # 25M65A1C20
- Condition Circle: Excellent Good Poor Fair
- Last Run Test Date: _____
Comment: _____
- PM-3 6in Hydrotech Hydraulic Submersible Pump Serial # 6F878
- Condition Circle: Excellent Good Poor Fair
- Last Run Test Date: _____
Comment: _____
- PM-4 3" Crucial Diesel SD Pump Mod#DDP-3 Ser#214468
-Condition Circle: Excellent Good Poor Fair
-Last Run Test Date: _____
Comment: _____

PP-1 POWER PACKS

- PP-1 Elastic Power Pack Serial # H1198258
- Condition Circle: Excellent Good Poor Fair
- Last Run Test Date: _____
Comment: _____
- PP-2 739 Hydrotech Power Pack Mod # HT60DCV Serial # F:
- Condition Circle: Excellent Good Poor Fair
- Last Run Test Date: _____
Comment: _____
- PP-3 Crucial Diesel Compres **Mod#L70190126P17E Ser#214468**
-Condition Circle: Excellent Good Poor Fair
-Last Run Test Date: _____
Comment: _____
- PP-4 Crucial Trailer-Mounted Diesel 25 HP Powerpack
Circle: Excellent Good Poor Fair
Date: _____
Comment: _____

Inspector: Josiah Strickland
Print: _____

Signature: Josiah Strickland

Inspector: _____
Print: _____

Signature: _____

Moran Environmental Recovery LLC Inspection Sheet

DATE: 3/10/25

Location: MER Yard

Unit #: 6729

BOOM REELS

	Circle		Comments
Grease Chain	YES	NO	_____
Grease Fittings	YES	NO	_____
Inspect sprocket	YES	NO	_____
Check Oil level in motor	YES	NO	_____
Reel clear of debris and grass	YES	NO	_____
Run motor	YES	NO	_____
Hand Brake operational	YES	NO	_____
Boom Reel cover secure	YES	NO	_____
*** 1000ft of 18" containment boom (Verify Quantity)	YES	NO	_____
Condition of Boom Reel Cover			Excellent <u>Good</u> Fair Poor
Condition of Boom Reel			Excellent <u>Good</u> Fair Poor

*** See Boom condition Report for updated Boom Condition

Trailer #: 6729

DOT Inspection: 9/24

Tire Pressure: ✓

Brakes: ✓

Trailer Lights: ✓

Trailer Frame: ✓

Tag & Exp: TW/56V80

Insurance: ✓

Wheels/Lugs: ✓

Axle Hubs: ✓

Trailer Jack: ✓

Hydraulics: ✓

Inspector: bsiah Strickland Signature: bsiah Strickland

Facility Rep: _____ Signature: _____

Notify Facility 24 hrs prior to inspection

Person Notified: _____

Check if Verification only

Moran Environmental Recovery LLC Inspection Sheet

DATE: 3/10/25

LOCATION: Colonial Terminal

INSIDE CONTAINER

		Circle one		Comments
6- 26lb Anchors with chain	Verified:	<input checked="" type="radio"/> YES	NO	_____
4- Buoys with 2 shackles each	Verified:	<input checked="" type="radio"/> YES	NO	_____
2 spools of line	Verified:	<input checked="" type="radio"/> YES	NO	_____
2000' 18" containment boom (verification of)	Verified:	<input checked="" type="radio"/> YES	NO	_____
4 Bundles absorbent pads	Verified:	<input checked="" type="radio"/> YES	NO	_____
4- Bundles absorbent boom	Verified:	<input checked="" type="radio"/> YES	NO	_____
1- Roll trash bags	Verified:	<input checked="" type="radio"/> YES	NO	_____
1- Pair pliers	Verified:	<input checked="" type="radio"/> YES	NO	_____
1- First Aid Kit	Verified:	<input checked="" type="radio"/> YES	NO	_____
1-Eye Wash	Verified:	<input checked="" type="radio"/> YES	NO	_____

OUTSIDE CONTAINER

Box number 3

Container accessible Verified: YES NO _____

Seal in place Verified: YES NO _____

Seal number _____

Container Temp Hi _____ Lo _____ Date: _____

Inspector: Josiah Strickland
Print: _____

Signature: Josiah Strickland

Facility Rep: [Signature]
Print: 1515 3/10/25

Signature: _____

Notify Facility 24 hrs prior to inspection

Person Notified: _____

Check if Verification only

Moran Environmental Recovery LLC Inspection Sheet

DATE: 3/10/25

LOCATION: Metro Ports

INSIDE CONTAINER

		Circle one		Comments
6- 26lb Anchors with chain	Verified:	<input checked="" type="radio"/> YES	NO	_____
4- Buoys with 2 shackles each	Verified:	<input checked="" type="radio"/> YES	NO	_____
2 spools of line	Verified:	<input checked="" type="radio"/> YES	NO	_____
2000' 18" containment boom (verification of)	Verified:	<input checked="" type="radio"/> YES	NO	_____
4 Bundles absorbent pads	Verified:	<input checked="" type="radio"/> YES	NO	_____
4- Bundles absorbent boom	Verified:	<input checked="" type="radio"/> YES	NO	_____
1- Roll trash bags	Verified:	<input checked="" type="radio"/> YES	NO	_____
1- Pair pliers	Verified:	<input checked="" type="radio"/> YES	NO	_____
1- First Aid Kit	Verified:	<input checked="" type="radio"/> YES	NO	_____
1-Eye Wash	Verified:	<input checked="" type="radio"/> YES	NO	_____

OUTSIDE CONTAINER

Box number 6

Container accessible Verified: YES NO _____

Seal in place Verified: YES NO _____

Seal number _____

Container Temp Hi _____ Lo _____ Date: _____

Inspector: Josiah Strickland
Print: _____

Signature: Josiah Strickland

Facility Rep: Mike Nettles
Print: _____

Signature: [Signature]

Notify Facility 24 hrs prior to inspection

Person Notified: _____

Check if Verification only

Moran Environmental Recovery LLC Inspection Sheet

DATE: 3/10/25

LOCATION: Metro Ports

INSIDE CONTAINER

		Circle one		Comments
6- 26lb Anchors with chain	Verified:	<input checked="" type="radio"/> YES	NO	_____
4- Buoys with 2 shackles each	Verified:	<input checked="" type="radio"/> YES	NO	_____
2 spools of line	Verified:	<input checked="" type="radio"/> YES	NO	_____
2000' 18" containment boom (verification of)	Verified:	<input checked="" type="radio"/> YES	NO	_____
4 Bundles absorbent pads	Verified:	<input checked="" type="radio"/> YES	NO	_____
4- Bundles absorbent boom	Verified:	<input checked="" type="radio"/> YES	NO	_____
1- Roll trash bags	Verified:	<input checked="" type="radio"/> YES	NO	_____
1- Pair pliers	Verified:	<input checked="" type="radio"/> YES	NO	_____
1- First Aid Kit	Verified:	<input checked="" type="radio"/> YES	NO	_____
1-Eye Wash	Verified:	<input checked="" type="radio"/> YES	NO	_____

OUTSIDE CONTAINER

Box number 5

Container accessible Verified: YES NO _____

Seal in place Verified: YES NO _____

Seal number _____

Container Temp Hi _____ Lo _____ Date: _____

Inspector: Josiah Strickland
Print: _____

Signature: Josiah Strickland

Facility Rep Roy BAIBOT
Print: _____

Signature: Roy Baibot

Notify Facility 24 hrs prior to inspection

Person Notified: _____

Check if Verification only

Moran Environmental Recovery LLC Inspection Sheet

DATE: 3/10/25

LOCATION: IMTT North

INSIDE CONTAINER

		Circle one		Comments
6- 26lb Anchors with chain	Verified:	<input checked="" type="radio"/> YES	NO	
4- Buoys with 2 shackles each	Verified:	<input checked="" type="radio"/> YES	NO	
2 spools of line	Verified:	<input checked="" type="radio"/> YES	NO	
2000' 18" containment boom (verification of)	Verified:	<input checked="" type="radio"/> YES	NO	
4 Bundles absorbent pads	Verified:	<input checked="" type="radio"/> YES	NO	
4- Bundles absorbent boom	Verified:	<input checked="" type="radio"/> YES	NO	
1- Roll trash bags	Verified:	<input checked="" type="radio"/> YES	NO	
1- Pair pliers	Verified:	<input checked="" type="radio"/> YES	NO	
1- First Aid Kit	Verified:	<input checked="" type="radio"/> YES	NO	
1-Eye Wash	Verified:	<input checked="" type="radio"/> YES	NO	

OUTSIDE CONTAINER

Box number 4

Container accessible Verified: YES NO

Seal in place Verified: YES NO

Seal number _____

Container Temp Hi _____ Lo _____ Date: _____

Inspector: Josiah Strickland
Print: _____

Signature: Josiah Strickland

Facility Rep: Roy BABOT
Print: _____

Signature: Roy Babot

Notify Facility 24 hrs prior to inspection

Person Notified: _____

Check if Verification only

Moran Environmental Recovery LLC Inspection Sheet

DATE: _____

LOCATION: _____ MER YARD _____

TOWABLE BLADDER

		Circle one	Comments
BLADDER #1 Abasco Towable 1000gal			
Stored in place at MER Yard	Verified:	YES NO	_____
Deployed and tested	Verified:	YES NO	_____
BLADDER #2 Abaso Towable 1000gal			
Stored in place at MER Yard	Verified:	YES NO	_____
Deployed and tested	Verified:	YES NO	_____
BLADDER #3 Abaso Towable 1000gal			
Stored in place at MER Yard	Verified:	YES NO	_____
Deployed and tested	Verified:	YES NO	_____

Inspector:
Print: _____

Signature: _____

Facility Rep
Print: _____

Signature: _____

Notify Facility 24 hrs prior to inspection

Person Notified: _____

Check if Verification only

Moran Environmental Recovery LLC Inspection Sheet

DATE: _____

Location: Ocean Terminal

Unit #: BR 1

BOOM REELS

Circle

Comments

Grease Chain	YES	NO	
Grease Fittings	YES	NO	
Inspect sprocket	YES	NO	
Check Oil level in motor	YES	NO	
Reel clear of debris and grass	YES	NO	
Run motor	YES	NO	
Hand Brake operational	YES	NO	
Boom Reel cover secure	YES	NO	
*** 1000ft of 18" containment boom (Verify Quanti	YES	NO	

Condition of Boom Reel Cover	Excellent	Good	Fair	Poor
Condition of Boom Reel	Excellent	Good	Fair	Poor

*** See Boom condition Report for updated Boom Condition

Inspector:
Print: _____ Signature: _____

Facility Rep
Print: _____ Signature: _____

Notify Facility 24 hrs prior to inspection

Check if Verification only

Person Notified: _____

Moran Environmental Recovery LLC Inspection Sheet

DATE: _____

Location: Imperial Sugar

Unit #: BR 5

BOOM REELS

	Circle		Comments				
Grease Chain	YES	NO	_____				
Grease Fittings	YES	NO	_____				
Inspect sprocket	YES	NO	_____				
Check Oil level in motor	YES	NO	_____				
Reel clear of debris and grass	YES	NO	_____				
Run motor	YES	NO	_____				
Hand Brake operational	YES	NO	_____				
Boom Reel cover secure	YES	NO	_____				
*** 1000ft of 18" containment boom (Verify Quanti	YES	NO	_____				
Condition of Boom Reel Cover			<table border="0" style="width: 100%; font-size: small;"> <tr> <td style="width: 25%;">Excellent</td> <td style="width: 25%;">Good</td> <td style="width: 25%;">Fair</td> <td style="width: 25%;">Poor</td> </tr> </table>	Excellent	Good	Fair	Poor
Excellent	Good	Fair	Poor				
Condition of Boom Reel			<table border="0" style="width: 100%; font-size: small;"> <tr> <td style="width: 25%;">Excellent</td> <td style="width: 25%;">Good</td> <td style="width: 25%;">Fair</td> <td style="width: 25%;">Poor</td> </tr> </table>	Excellent	Good	Fair	Poor
Excellent	Good	Fair	Poor				

*** See Boom condition Report for updated Boom Condition

Inspector:
Print: _____ Signature: _____

Facility Rep
Print: _____ Signature: _____

Notify Facility 24 hrs prior to inspection

Person Notified: _____

Check if Verification only

Moran Environmental Recovery LLC
Inspection Sheet

Notes

unit 835 - Nav needs replaced

unit 891 - Front Port bumper Brake

Phillips Cole - Boat lift needs service and pillings
are coming away from the dock itself pictures on SSR
ELOW

